



# CERTIFICATE OF APPROPRIATENESS APPLICATION FORM

Incomplete applications will not be processed for Commission review.

Please print legibly.

*Paul  
HP  
6/4/2012*

1. HISTORIC NAME OF PROPERTY OR HISTORIC DISTRICT: (if known)

Northpoint North

ADDRESS OF PROPERTY:

2717 E. Bellevue Pl

2. NAME AND ADDRESS OF OWNER:

Name(s): Thomas Maloney

Address: 2717 E. Bellevue Pl.

City: Milwaukee State: WI ZIP: 53211

Email: +maloney6@wi.rr.com

Telephone number (area code & number) Daytime: 414 943 1008 Evening: 414 943 1008

3. APPLICANT, AGENT OR CONTRACTOR: (if different from owner)

Name(s): \_\_\_\_\_

Address: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ ZIP Code: \_\_\_\_\_

Email: \_\_\_\_\_

Telephone number (area code & number) Daytime: \_\_\_\_\_ Evening: \_\_\_\_\_

4. ATTACHMENTS: (Because projects can vary in size and scope, please call the HPC Office at 414-286-5712 for submittal requirements)

**A. REQUIRED FOR MAJOR PROJECTS:**

included Photographs of affected areas & all sides of the building (annotated photos recommended)

included Sketches and Elevation Drawings (1 full size and 1 reduced to 11" x 17" or 8 1/2" x 11")  
A digital copy of the photos and drawings is also requested.

included Material and Design Specifications (see next page)

**B. NEW CONSTRUCTION ALSO REQUIRES:**

\_\_\_\_\_ Floor Plans (1 full size and 1 reduced to a maximum of 11" x 17")

\_\_\_\_\_ Site Plan showing location of project and adjoining structures and fences

**PLEASE NOTE: YOUR APPLICATION CANNOT BE PROCESSED UNLESS BOTH PAGES OF THIS FORM ARE PROPERLY COMPLETED AND SIGNED.**

**5. DESCRIPTION OF PROJECT:**

Tell us what you want to do. Describe all proposed work including materials, design, and dimensions. Additional pages may be attached via email.

My plan is to repair the porch columns on my house from the trim molding to the porch floor. From the top of the trim molding to the porch floor measures 28". In other words, only the bottom 28" of each column will be repaired. The trim molding and lower portion of columns are in bad shape with crumbling and cracking of cement/mortar. Please note that the columns above the molding are made of 4" limestone and will not be touched. My plastering contractor will remove all loose cement/mortar and repair with a similar material. It is obvious from inspection that the columns below the trim molding have been patched/repainted through the years.

**6. SIGNATURE OF APPLICANT:**

Thomas A. Maloney  
Signature

Thomas Maloney  
Please print or type name

6-4-2022  
Date

This form and all supporting documentation MUST arrive by 4:00 pm (11:59 pm via email) on the deadline date established to be considered at the next Historic Preservation Commission Meeting. Any information not provided to staff in advance of the meeting will not be considered by the Commission during their deliberation. Please call if you have any questions and staff will assist you.

**Mail or Email Form to:**  
Historic Preservation Commission  
City Clerk's Office  
841 N. Broadway, Rm. B1  
Milwaukee, WI 53202

**PHONE: (414) 286-5712 or 286-5722      hpc@milwaukee.gov      www.milwaukee.gov/hpc**

**Or click the SUBMIT button to automatically email this form for submission.**

**SUBMIT**









Porch  
floor

Cement  
skim coat

4" thick

limestone

trim  
molding

28"

Elevation Drawing