

**Certificate of Appropriateness** 

Milwaukee Historic Preservation Commission/841 N Broadway/Milwaukee, WI 53202/phone 414-286-5722

# Property Description of

# 2411 N. Terrace Avenue, North Point North Historic District

Repair to fourteen (14) prime windows on the first and second floors of the residence. Replacement of aluminum combination storm windows with Marvin wood-framed combination storm windows. Replacement of two deteriorated metal frame windows in the garage with wood frame window to match the existing nine-light design. Temporary removal of a portion of the porch roof to diagnose and repair water line problem.

## Date issued

# 5/9/2024

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

### N/A

work

All work must be done in a craftsman-like manner. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Historic Preservation staff as follows: Phone: (414) 286-5722 E-mail: <u>hpc@milwaukee.gov</u>.

### Permits and timeline

You are responsible for determining if permits are required and obtaining them prior to commencing work. Consult the Development Center on the web or by telephone for details: <u>www.milwaukee.gov/lms</u> - (414) 286-8210. If permits are not required, work must be completed within one year of the date this certificate was issued. If permits are required, permits must be obtained within one year of the date this certificate was issued.

Andrew CAA

City of Milwaukee Historic Preservation

Copies to: Development Center, Ald. Brostoff

### DOUBLE HUNG SCREEN OPTIONS





#### RETRACTABLE SCREEN

The innovative Retractable Screen, available on the Ultimate Double Hung G2 window, is a factory-installed screen that easily retracts out of sight when not in use. The screen can be drawn to rest at one of two stop points, resulting in a seal at either the sill or at the checkrail.

FULL OR HALF SCREEN Exterior screen with an aluminum surround. The full screen covers both the top and bottom sash. The half screen only covers the bottom sash.

### DOUBLE HUNG STORM OPTIONS





TWO-LITE WOOD STORM SASH OR SCREEN A wood frame containing non-

removable glass. The storm sash can be removed during the summer and replaced with a wood framed screen. Available only for wood windows.

STORM AND SCREEN COMBINATIONS A combination unit is composed of two glass panels and one screen panel that can be easily removed from the interior for cleaning. Available with a wood (bare or primed) or aluminum surround, panels can be configured multiple ways, glass above screen,



#### ENERGY PANEL

Often confused with storm windows, an energy panel is technically a glazing option. It is a removable, exterior glass panel finished on the edges by a surround. Energy panels cover the exposed glass surface of each sash and offer added energy efficiency for screen above glass, or glass above glass. wood windows with single glazing.

106

## Wood replacement storm windows

2 of 3

### LINE ITEM QUOTES

The following is a schedule of the windows and doors for this project. For additional unit details, please see Line Item Quotes. Additional charges, tax or Terms and Conditions may apply. Detail pricing is per unit.

Line #1 Qty: 2	Mark Unit:		Net Price: Ext. Net Price:	USD	1,102.00 2,204.00
MARVIN	From The Exterior	Bronze Exterior Bare Pine Interior Elevate Direct Glaze Rectangle Rough Opening 43" X 61" IG Low E2 w/Argon Stainless Perimeter and Spacer Bar 7/8" SDL - With Spacer Bar - Stainless Rectangular - Special Cut 3W3H Bronze Ext - Bare Int Additional Mull Info: Stand Alone 4 9/16" Jambs Structural Brackets DH/GL/DR Frame ****Note: Divided lite cut alignment may I OMS drawing. Please consult your local re ****Note: Unit Availability and Price is S	epresentative for exact specif		

Entered V3. V6 MO 42 1/2" X 60 3/4" FS 42" X 60 1/2" RO 43" X 61" Performance Grade Licensee #876 AAMA/WDMA/CSA/101/I.S.2/A440-11 CW-PG50 1829X1829 mm (72X72 in)

## Garage replacement window