



Chimney to be removed.




Front of building.




Front of building.




Rear of building.




Rear of building.



Front and east side of building.



Close up of the condition of metal tile.



Current Shingles



Proposed Landmark regular shingle for front and rear of building.



Proposed style for alternate option for front of building- Matterhorn Metal Roofing 'Tuscan Ville' tile. https://www.certainteed.com/residential-roofing/products/matterhorn-metal-roofing-tile/