



Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

Property 102 E. VINE ST. Brewers Hill HD
Description of work Install Acker combination storms on house to replace existing storm windows as needed. One horizontal divider bar in each window to be aligned with sash divider in prime windows. Manufactured in Clear Solid Northern White Pine and painted. Constructed with mortise and tenon glued joints. Finish hand sanded, woodlife treated, oil-base primed and finish painted Includes Fitting/Installation Glass washed in Combinations before final install. Combinations with 1/8" clear glass.
Date issued 1/4/2018 PTS ID 114446 COA: storm windows

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness: N/A

All work must be done in a craftsman-like manner, and must be completed within two years of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: HPC@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.milwaukee.gov/build, or call (414) 286-8210.

City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Milele Coggs, Contractor , Inspector John Cunningham (286-2538)

119 E Vine St
Milwaukee, Wisconsin
Google, Inc.
Street View - May 2009



Subject property



Typical windows to be replaced on house



Replacement storm type