


Photo 1



Upper Cornice – West End - improper repair - rusted holes in metal

Photo 2



Upper Cornice – rusted holes in metal

Photo 3



Upper Cornice – West End – repaired with formed sheet metal

Photo 4



Upper Cornice – repaired with formed sheet metal