



Photo 1 – Context view on W. St. Paul Ave., north & west elevations, view looking southeast



Photo 2 – North and west elevations, view looking southeast



Photo 3 – Primary entrance on west elevation by the building’s northwest corner, view looking southeast



Photo 4 – Round-arched opening around corner from primary entrance. On north elevation by the building’s northwest corner, view looking south



Photo 5 – West elevation, view looking east



Photo 6 – West and south elevations, view looking northeast



Photo 7 – West elevation, view looking east (boarded-over industrial steel sash window)



Photo 8 – West elevation, view looking southeast (boarded-over steel sash window & ramp)



Photo 9 – West elevation, view looking south (boarded-over steel sash window & ramp)



Photo 10 – West and south elevations, view looking northeast



Photo 11 – Concrete pad behind the south (rear) elevation, view looking east




Photo 12 – South (rear) elevation, SWC of building, looking north along vacated N. 15th St.



Photo 13 – South (rear) elevation, view looking north



Photo 14 – South (rear) elevation, view looking north



Photo 15 – South (rear) elevation, view looking north



Photo 16 – South and east elevations, view looking northwest



Photo 17 – South and east elevations, view looking northwest



Photo 18 – East elevation brick-infilled opening, view looking west



Photo 19 – East and south elevations, view looking west



Photo 20 – East elevation, concrete block infilled opening, view looking west



Photo 21 – East and south elevations, view looking northwest



Photo 22 – East and south elevations, view looking west



Photo 23 – East and south elevations, view looking northwest



Photo 24 – East and south elevations, view looking west



Photo 25 – South elevation, view looking east



Photo 26 – South elevation, view looking east



Photo 27 – East and south elevation, view looking north



Photo 28 – South elevation, view looking north



Photo 29 – South elevation, view looking north



Photo 30 – South elevation, CMU-infilled entrance, view looking north



Photo 31 – South elevation, view looking northeast



Photo 32 – South and east elevations, view looking northwest



Photo 33 – South and east elevations, view looking northwest



Photo 34 – South elevation, view looking northwest



Photo 35 – East elevations, view looking west



Photo 36 – East elevations, view looking west



Photo 37 – East elevations, view looking west



Photo 38 – East elevation, CMU-infilled entrance, view looking west



Photo 39 – East elevation, view looking southwest



Photo 40 – North and east elevations, view looking southwest



Photo 41 – North and east elevations, view looking southwest



Photo 42 – North elevation secondary entrance, view looking south



Photo 43 – North elevation secondary entrance stair, view looking southeast



Photo 44 – North and east elevations, view looking southwest



Photo 45 – North elevation basement-level entrance, view looking south



Photo 46 – North elevation basement-level entrance, view looking south



Photo 47 – North elevation, view looking southwest



Photo 48 – North elevation, view looking south



Photo 49 – North elevation, fire escape & standpipe, view looking south



Photo 50 – North elevation, view looking southwest



Photo 51 – North elevation, view looking southwest



Photo 52 – Roof, view looking east standing at the northwest corner of the building



Photo 53 – Roof, view looking south standing at the northwest corner of the building



Photo 54 – Roof, view looking northeast



Photo 55 – Area of proposed new construction east of building, view looking southeast



Photo 56 – Area of proposed new construction east of building, view looking southwest