

1 CAMPUS SITE PLAN
SCALE: N.T.S.






Photo 1 - Gymnasium Building prior to Pool Addition



Photo 2 - South Overall at Gymnasium



Photo 3 - South (western portion) at Gymnasium



Photo 4 - South (central portion) at Gymnasium



Photo 5 - South (eastern portion) at Gymnasium



Photo 6 - South Entry Plaque at Gymnasium



Photo 7 - East Overall at Gymnasium




Photo 8 - East (southern portion) at Gymnasium



Photo 9 - East (central portion) at Gymnasium



Photo 10 - East (northern portion) at Gymnasium



Photo 11 - East Entry (northern portion) at Gymnasium



Photo 12 - West (southern portion) at Gymnasium




Photo 13 - West (central portion) at Gymnasium




Photo 14 - West (northern portion) at Gymnasium



Photo 15 - West Entry (southern portion) at Gymnasium



Photo 16 - Upper Windows at Gymnasium



Photo 17 - South parapet damage at Gymnasium



Photo 18 - East parapet damage at Gymnasium



Photo 19 - West parapet damage at Gymnasium



Photo 20 - West entry damage at Gymnasium



Photo 21 - North Overall at Pool Addition



Photo 22 - North-east corner at Pool Addition



Photo 23 - East Overall at Pool Addition




Photo 24 - West Overall at Pool Addition



Photo 25 - North (loading dock) at Pool Addition



Photo 26 - North-east parapet damage at Pool Addition



Photo 27 - North-east corner damage at Pool Addition



Photo 28 - East parapet damage at Pool Addition



Photo 29 - East elevation cracking at Pool Addition



Photo 30 - South-west elevation cracking at Pool Addition



Photo 31 - South-west elevation cracking at Pool Addition




Photo 32 - South-west parapet damage at Pool Addition



Bowing facade
at corner

Photo 33 - South elevation bowing and brick damage at Pool Addition



Step cracking

Photo 34 - South-east elevation cracking at Pool Addition



Photo 35 - West parapet damage at Pool Addition



Photo 34 - North parapet damage at Pool Addition