



*Photo 01: West Exterior Elevation of Mansion*



*Photo 02: Southwest corner of Porte Cochere*





*Photo 03: South View of Porte Cochere showing drop in terra cotta arch stones and deterioration of entry steps.*



*Photo 04: View of Wisconsin Avenue Facade (South Elevation).*





*Photo 05: East Exterior Elevation of Mansion.*



*Photo 06: Detail of Conservatory. Non-original stone window framing to be removed and replaced with new to match original.*





*Photo 07: East Side - Capped foundation at removed Pavilion*



*Photo 08: East Exterior Elevation of Mansion - Fire Escape to be Removed*





*Photo 09: View of East Side of Mansion from Northeast Corner of Lot*



*Photo 10: View of North Side of Mansion from the Northwest*





*Photo 11: North Elevation at West Side of Mansion Viewed from the North*



*Photo 12: West Side of South Entrance Terrace Showing Stone & Paver Deterioration*





*Photo 13: Southwest Corner of South Entrance Terrace*



*Photo 14: South Side of South Entrance Terrace Showing Condition of Stair and Balustrade*