

**Certificate of Appropriateness Application – Supporting Photos**  
Frank Lloyd Wright American System-Built Homes Model Two Flat “C” Exterior Restoration  
2732-2734 West Burnham Street  
American System Built Homes Historic District



**PHOTO 1:** 1931 Photo.  
Subject building is  
westernmost (left) duplex



**PHOTO 2:**  
Existing south  
(front) elevation



**PHOTO 3:**  
Existing west  
elevation



**PHOTO 4:**  
Existing north  
elevation



**PHOTO 5:**  
Existing east  
elevation



**PHOTO 6:**  
Existing east  
elevation



**PHOTO 7:**  
Exploratory window in exterior wall showing original and added stucco systems.



**PHOTO 8:**  
Loss of shadow line from added stucco system.



**PHOTO 9:**  
Low-pitched hip roof on  
top of original roof.



**PHOTO 10:**  
Low-pitched hip roof on  
top of original roof.  
Deteriorated roof on  
monitor.



**PHOTO 11:**  
Low-pitched hip roof on  
top of original roof.  
Deteriorated roof on  
monitor.



**PHOTO 12:**  
New roof structure on  
top of original roof.



**PHOTO 13:**  
Existing fascia condition.



**PHOTO 14:**  
Original pressed metal fascia still remains on one of adjacent identical duplexes.



**PHOTO 15:**  
Deteriorated wood trim,  
covered with aluminum  
cladding.



**PHOTO 16:**  
Wood trim, in various  
stages of deterioration/  
soundness.



**PHOTO 17:**  
Sagging and twisting  
stairs and landing.



**PHOTO 18:**  
Existing stair condition  
– uneven treads and  
risers, deteriorated wall.



**PHOTO 19:**  
Existing stair condition.



**PHOTO 20:**  
Existing stair condition.



**PHOTO 21:**  
Rear sleeping porch  
added glazing.



**PHOTO 22:**  
Rear sleeping porch  
added glazing.



**PHOTO 23:**  
Rear sleeping porch  
added glazing.



**PHOTO 24:**  
Deteriorated front  
planter.  
Location of existing  
footings below grade.



**PHOTO 25:**  
Deteriorated front  
planter.  
Location of existing  
footings below grade.