1. Prepare surfaces and paint exterior: of front house

SW 6990 Caviar

SW 7551 / Greek Villa



SW 6990 Caviar

SW 7551 Greek Villa

SW 6990 Caviar



SW 7551 Greek Villa

gutter and fascia repair. then SW 6990 Cavier

SW 6990 Caviar —

SW 7551 Greek Villa

(Door repaired) SW 6990 Caviar



All surfaces to be cleaned and scraped free of lose paint.

Sanded and primmed

Window glass re-glazed as needed. And confirmed operable.

All vegetation removed from foundation walls (and any other weeds that have attached to the exterior.

All cracks at windows, door trim, and any other meeting of materials or elements caulked prior to painting.



SW 6990 Caviar

SW 7551 Greek Villa

SW 6990 Caviar

SW 7551 Greek Villa



SW 6990 Caviar



All trim, fascias, soffits, cornice, and doors to the painted exterior grade SW 6990 "Cavier" semi-gloss.



All siding, scalloped finishes at gables, and other decorative elements in the main body of exterior to be Greek Villa SW 7551 exterior grade cashmere low luster finish.

2. Prepare surfaces and paint exterior of rear house



SW 6990 Caviar SW 7551

Greek Villa

SW 6990 -Caviar



SW 7551 Greek Villa SW 6990 Cavier

SW 6990 Caviar

> SW 7551 Greek Villa



All surfaces to be cleaned and scraped free of lose paint.

Sanded and primmed

Window glass re-glazed as needed. And confirmed operable.

All vegetation removed from foundation walls (and any other weeds that have attached to the exterior.

All cracks at windows, door trim, and any other meeting of materials or elements caulked prior to painting.




SW 6990 Caviar

SW 7551 Greek Villa

SW 6990 Caviar

SW 7551 Greek Villa





All trim, fascias, soffits, cornice, and doors to the painted exterior grade SW 6990 "Cavier" semi-gloss.

SW 7551 Greek Villa

All siding, scalloped finishes at gables, and other decorative elements in the main body of exterior to be Greek Villa SW 7551 exterior grade cashmere low luster finish.

3. Reconnect down spouts to gutter system on north and south sides of rear house



South Face of Rear House

East Face of Rear House

Gutters repaired / replaced and properly connected to down spouts on Rear house north and south and noted.



North Face of Rear House


4. West side / Rear Porch of Front house rebuilt / repaired.



Existing Rear Porch Front house

Remove all of porch and supportive structure back to house facade

Cellar door repaired / replace



Proposed East House Rear Porch reconstruction