



Milwaukee Historic Preservation Commission Staff Report

LIVING WITH HISTORY

HPC meeting date

7/6/2026

CCF # 260145

Ald. Stamper

Staff reviewer: Andrew Stern

Property

2377 N. Sherman Blvd

Sherman Boulevard Historic District

Owner/Applicant

LaQuita Hoskin
2377 N. Sherman Blvd.
Milwaukee, WI 53210

Proposal

The applicant is seeking after-the-fact approval for vinyl window replacement.

Staff comments

The Charles DuBorney House is a Craftsman style residence constructed in 1913. In April 2025, the property owner received a violation for vinyl window replacement without a COA. The applicant applied to HPC in August 2025 to retroactively keep the vinyl windows. HPC denied the request and recommended the applicant replace the vinyl windows with solid wood sash windows with nine-over-one sashes that match the historic appearance. The applicant did not appeal the denial to Zoning, Neighborhoods, and Development Committee (ZND) in the provided time and is again requesting HPC approval for eight windows with vinyl one-over-one windows. The applicant has not provided the model or manufacturer of the windows. The windows were installed by Universal Windows.

The preservation guidelines for Sherman Boulevard state to:

Retain existing window and door openings that are visible from the public right-of-way. Retain the present configuration of panes, sash, sills, architraves, hoods, doors and hardware, except as necessary to restore to the original condition. Avoid making additional openings or changes in the principle elevations by enlarging or reducing window or door sizes. Avoid changing the size or configuration of windowpanes or sash. Avoid discarding original windows, doors, and door hardware when they can be repaired or reused.

Respect the stylistic period or periods a building represents. If replacement of window sash or doors is necessary, the replacement should duplicate the appearance and design of the original window sash or door. Avoid using inappropriate sash and door replacements such as unpainted aluminum storm and screen window combinations. Avoid the filling in or covering of openings with materials like glass block or the installation of fake shutters that are not in proportion to the openings or that are historically out of character the building. Avoid using modern style window units, such as with horizontal sliding sash, in place of double-hung sash or the substitution of units with glazing configurations not appropriate to the style of the building. The installation of glass block in basement windows visible from the street is generally not permitted.

Prior to replacement, the house had original nine-over-one wood double-hung sash windows and wood storm windows. The upper sash was smaller than the lower sash on the original windows. The applicant has provided no evidence the historic wood windows were deteriorated beyond repair. Vinyl windows have never been approved by HPC and are not appropriate for the historic district. Staff recommends all vinyl windows be replaced with solid wood sash nine-over-one windows that match the profile of the original windows.

Recommendation

Recommend denial of the vinyl windows, with replacement with solid wood sash nine-over-one windows and new storm windows.

Conditions

Previous HPC action

Previous Council action

