File No. 141107. An ordinance relating to the change in zoning from Industrial-Light to Local Business for adaptive reuse of the building located at 2801-2821 North 4th Street, on the north side of West Hadley Street, west of North 4th Street, in the 6th Aldermanic District.



File No. 141107. Site Context Photos





Milwaukee Enternia

View of Site from North 4th Street, looking southwest





View of Site from W Hadley St and N 5th St

View of Site from W Hadley St and N 4th St










FOCUS AREA
W. NORTH AVE TO W. LOCUST ST,
BETWEEN N. 4TH ST & N PALMER ST

2013 VISIONING CHARETTE













SOUTH ELEVATION_FROM HADLEY

SITE I_W. LOCUST & MLK DRIVE

SITE 2_MILWAUKEE ENTERPRISE CENTER

SITE 3_5TH STREET SCHOOL


SITE 3A_W. CENTER & MLK DRIVE

SITE 4_MALCOLM X SCHOOL

SITE 5_W. CLARKE ST & MLK DRIVE

SITE 6_W. NORTH AVE & MLK DRIVE

SITE 2_MILWAUKEE ENTERPRISE CENTER



EXISTING SITE CONDITIONS

Originally built as a shoe factory, the Milwaukee Enterprise Center now houses a wide variety of businesses and professional services in large, lofty spaces. The building has a lack of parking and does not have a highly visible presence in the area, despite the many thousand square feet of rentable space that it has available. A large steam boiler building occupies the southwest corner of the site.



FOCUS GROUP INPUT

Developer Thoughts:

- Historic district (North Ave to North of Locust Ave)
- Connection to site I (W. Hadley & MLK Drive)
- Affordable methodology (Workforce)
- · Foster opportunity for non-profits

Lender Thoughts:

- Need jobs
- Housing with economic development
- · Tax credit project
- · Training "command center"

Base Program:

- Reuse all or portions of existing building
- · On-site parking
- Potential connection to MLK Drive or Locust St
 - Public open space
 - Flexible use

Zoning Information (IL2):

- · No min/max height
- · No parking requirements

SITE 2_MILWAUKEE ENTERPRISE CENTER W. HADLEY ST CITY OWNED VACANT PROPERTY PRIVATELY OWNED VACANT PROPERTY Owner Address Value Lot Size Zoning 2824 North 4th Street LLC | 2821 N 4th St | \$1,400,000.00 IL2





Image 1: Nunn-Bush Company Shoe Factory, looking northeast (1930).



Image 2: Architectural elevations of 1917 addition by Herman J. Esser.




Image 3: Sanborn Insurance Map (1937).




Image 4: Site Plan (1953).




Image 5: Section through building looking south showing cafeteria/recreation hall on 6th floor (1953).



Image 6: Nunn-Bush Ladies Bowling League Costume Party in 6th floor cafeteria/recreational hall (1930).





Image 7: Henry L. Nunn (1878-1972).



. . . President Nunn joins his "co-workers" in the big cafeteria on the sixth floor of the factory. The cafeteria was started twenty-two years ago by the management, but was turned over to the workers' union in 1923. For the last few months it has been operating at a loss; recently, rather than have one of their number laid off, the women who work in it asked for a 7.5 per cent pay cut. Such doings are fairly typical of Mr. Nunn's "industrial democracy." Nunn is a rigid vegetarian, eats peanuts instead of bread, and frequently tops off his meal with a taffy-like apple confection called "Aplets," which he urges companionably on favored visitors. Several members of the female office staff have been converted to vegetarianism, and they join him every noon at his special "vegetarian table." He plans to open a vegetarian restaurant in downtown Milwaukee shortly-a "really high-class restaurant," says Mr. Nunn, "named Ambrosia House."

Image 8: Article from Fortune Magazine, November 1938.





Image 10: Aerial view of site, looking north (2013).



Image 11: West and south elevations, looking northeast (2013).



Image 12: West and south elevations, looking northeast (2013).



Image 13: South elevation, looking west (2013).



Image 14: South and east elevations, looking northwest (2013).



Image 15: East elevation, looking southwest (2013).



Image 16: East elevation, looking northwest (2013).



Image 17: East and north elevations, looking southwest (2013).



Image 18: North elevation, looking west (2013).



Image 19: North elevation, looking east (2013).



Image 20: North and west elevations, looking southeast (2013).



Image 21: West elevation, looking southeast (2013).



Image 22: Stair in 1916 portion of complex (2013).



Image 23: Typical floor in 1916 portion of complex (2013).



Image 24: : Typical floor in 1917 portion of complex (2013).



Image 25: Cafeteria/recreation hall on 6th floor of 1917 addition (2013).



Image 26: Ladies Parlor off cafeteria/recreation hall on 6th floor (2013).

