

2015 N Palmer St. Milwaukee WI  
Photographs



Front/East Face



South Face



North Face

2015 N Palmer St. Milwaukee WI  
Photographs

2015 N Palmer St. Milwaukee WI  
Photographs



West Face/Rear



Example of Existing Stone Sills, (North Face)  
Windows to be replaced



Wooden Sills to be replaced with Stone. Closed Window to be opened. New window to be installed. (North Face)

2015 N Palmer St. Milwaukee WI  
Photographs

Examples of deterioration to brick to be repaired.



Section above shows signs of delamination.  
Portion of wall to be disassembled and rebuilt.



2015 N Palmer St. Milwaukee WI  
Photographs


Lower Level Window to be opened up (North Face)




Lower level Side door to be opened up. (North Face)

# Doors

## Traditional door



All styles  
1860-1910



Itali  
1860

Intended Door Style

2015 N Palmer St. Milwaukee WI  
Photographs