



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Looking east from North Van Buren Street at monument sign and security camera.



CCF 140507 Northwestern Mutual Life Insurance Company 8-9-2017
Looking south across East Mason Street towards the main building entrance located at
North Cass Street. There are bollards, pavers, and private light fixtures at this location.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Close up of one of four private storm drains located on the curb extension into the south side of East Mason Street at North Cass Street.



CCF 140507 Northwestern Mutual Life Insurance Company 8-9-2017
Close up of private pedestrian level light located at the main building entrance off of East
Mason Street at North Cass Street. Note: Other specialty streetlight fixtures will be
permitted under a separate maintenance agreement.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Looking east at the south sidewalk area of East Mason Street at North Marshall Street. In particular, looking at the bollards on the left and the security bollard on the right.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Looking south at the southwest corner of East Mason Street and North Prospect Avenue.




CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Close up of an electrical control box located in the planters surrounding the office campus.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Looking northeast at the pavers on the north side of East Wisconsin Avenue at North Cass Street.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Close up of a freestanding security camera at North Prospect Avenue and East Wisconsin Avenue.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Looking south at the backup driveway in the east side of North Van Buren Street.



CCF 140507

Northwestern Mutual Life Insurance Company

8-9-2017

Close up of the loading dock door served by the backup driveway on North Van Buren Street.