


Front View



Left Front View




Rear View




Right Rear View



Right Side View







Existing Kitchen Window






Proposed Marvin Ultimate All Wood Window



Capped Pipes from Radiators Previously Removed




Proposed Hydronic Toe Space Heaters




Historical Picture Showing Crown Cap Molding On Windows in Living and Dining Rooms Removed by Previous Owner



Proposed Installing Similar Crown Cap On Windows







Existing Ductwork for Downdraft Range





Propose Changing Dining Room-Kitchen Door to glass Mullion Door