

2045 N. 2nd Street
June 10, 2019

Defective Work By Previous Owner

2045 N. 2nd Street
Front



Side



Rear

Defective 6 Year Old Roof System



Sagging Ridge and Rafters;
Poorly Installed Siding



Improperly Installed Siding; Water
Damage




Siding Attached with Staples;
Defective Work



Improper siding installation and water logged window trim



Bulging Brick/Foundation



Bowing Northern Wall Caused by Ceiling Joist Removal



Southern Wall and Window Misalignment Caused by Ceiling Joist Removal

