







SYCAMORE PLACE IMPROVEMENTS SITE UPDATES









SYCAMORE PLACE IMPROVEMENTS SITE UPDATES

PROPOSED LANDSCAPE IMPROVEMENTS

APARTMENT LANDSCAPE AMENITY ZONE DOG RUN, CHILDREN'S PLAYGROUND, GRILL ZONE, COMMUNITY GARDEN









DOG RUN



CHILDREN'S PLAYGROUND










RECEPTION



SEWING



LOBBY




ARTS & CRAFTS ROOM







SECURE MAIL / PACKAGE ROOM



COMMUNITY ROOM



COMMUNITY ROOM



COMMUNITY ROOM





ORIGINAL CORRIDOR CONDITIONS

- -DATED INTERIORS
- -OLD CARPET AND FIXTURES







CORRIDOR IMPROVEMENTS

-LIGHT, MODERN, & WELCOMING AESTHETIC -PAINT REFRESH, NEW CARPET, & LIGHTING

-IMPROVED SECURITY & RESIDENT SAFETY FEATURES











ORIGINAL LOBBY CONDITION



RENOVATED LOBBY CONDITION











ELEVATED BRANDING AND WAYFINDING










IMPROVED TENANT SECURITY FEATURES













SYCAMORE PLACE - RESIDENT UNIT IMPROVEMENTS















SYCAMORE PLACE - PROPOSED EXTERIOR IMPROVEMENTS





EXTERIOR CONDITION 01 VINYL SIDING MAJORITY



- 1. GC TO CONDUCT FULL EXTERIOR INSPECTION OF ALL BUILDING FACADES,
- GC TO CONDUCT FULL EXTERIOR INSPECTION OF ALL BUILDING FACADES, WINDOWS, DOORS, SOFFITS, FASCIA, MECHANICAL LOUVERS, BALODN RAILS, ROOF, AND GUTTERS PROR TO WORK.
 FOLLOWING. INSPECTION GC TO PROVIDE ANY REPAIR RECOMMENDATIONS TO ARCHITECT AND UNIVER OF DOCUMENTED DAMAGE OR AREAS NEEDING REPAIR PRIOR TO WORK.
- REPAIR PRIOR TO WORK

 G. TO CLEAN ALL FACADES PRIOR TO WORK.

 4. REFER TO ATTACHMENT FOR ADDITIONAL SPECIFICATION SECTIONS.

EXTERIOR PAINT SELECTIONS COLOR







Black - 353535 Accent areas as shown (balcony/volume projections) Concrete surfaces Window Railings



Wood look accent (Re-Siding)
(provide alternate priceing for black
paint on existing vinyl and alabaster
paint on existing brick)
Wood or wood-look to match entry
vertical orientation

EXTERIOR CONDITION 01



GENERAL NOTES:

- GC TO CONDUCT FULL EXTERIOR INSPECTION OF ALL BUILDING FACADES, WINDOWS, DOORS, SOFFITS, NASCA, MECHANICAL LOUVERS, BALCONY PALLS, 2. FOLLOWING INSPECTIONS OF TO PROVIDE ANY REPAIR RECOMMENDATIONS TO ARCHITECT AND OWNER OF DOCUMENTED DAMAGE OR AREAS NEEDING REPAIR PRIOR TO WORK.

 3. CC TO CLEAN ALL FACADES PRIOR TO WORK.

 4. MERRY TO ATTACHMENT FOR ADDITIONAL SPECIFICATION SECTIONS.

LOCATIONS

EXTERIOR PAINT SELECTIONS





Gutters, Flashing & Louvers Black - 353535



Wood look accent (Re-Siding) (provide alternate priceing for black paint on existing vinyl and alabaster paint on existing brick) Wood or wood-look to match entry vertical orientation







SYCAMORE PLACE - FUTURE IMPROVEMENTS FITNESS / GAME AREA CONCEPT



AMENITY SPACE CONCEPT PLAN





GAME ROOM CONCEPT









SYCAMORE PLACE - BACK TO SCHOOL EVENT















MARKET STUDY ANALYSIS

The Sycamore place improvements and proposed adjacent Multi family development are consistent with the Granville Plan.

Key takeaways from this Market Study include:

1. Demand for Market Rate Apartments is Unmet


There are strong indicators that there is sufficient demand for a substantial number of new rental units. The proposed adjacent Multi family development will positively fulfill this need.

2 . Within the next 5 years, there will be a strong demand for non-age restricted housing for young professionals and families.

The senior housing market is fulfilled in this area. The market here can attract more young professionals and will help maintain local employees. This proposed adjacent Multi family development will provide amenity rich and modernized options for all residents.

3 . Granville is very well served with affordable housing units. Housing diversification requires more market rate units.

There is a demand for mixed income developments. Housing diversity provides options and keeps residents close to their community ties. The proposed Multi family development aims to provide housing value back into the community and to benefit local employers.
















MULTI FAMILY CONCEPT PRECEDENTS










MULTI FAMILY CONCEPT PRECEDENTS















LEVELS 02-04



DEVELOPMENT SUMMARY

ZONING: REZONE TO RM6 SETBACKS: FRONT: 15'-0"(MAX.) SIDE: 3'-0 TO -6'-0 REAR: 10'-0"- TO 15'-0" YIELD STUDY OVERVIEW: 1&JR BDR: 96(115) UNITS MIX: 58% 2 BDR: 57(68) UNITS MIX: 35% 3 BDR: 12(14) UNITS MIX: 7% UNITS TOTAL: 220 UNITS BLOG A: 125 UNITS BLOG B: 95 UNITS PARKING TOTAL: 336 STALLS COVERED PARKING: 220 STALLS (1:1 RATIO) PARKING REQUIRED: 330 STALLS @ 1.5 RATIO

LEVEL B



