


1 EXISTING FIRST FLOOR PLAN
SCALE: NTS



2 EXISTING FIRST FLOOR REVERSE CEILING PLAN
SCALE: NTS






Photo 1 - View of Northwest Corner Showing Existing Dormer on West Facade and Existing Front Porch & Handrailing



Photo 2 - Damaged Masonry at Base of Brick Columns Supporting Roof Porch



Photo 3 - Underside of Roof Porch Showing Rotted Wood Joists and Damaged Metal Decking



Photo 4 - West Window on North Facade First Floor Showing Rotted Wood at Header and Sill. Damage to Boxed Beam Shown in Upper Right Corner



Photo 5 - Underside of Roof Porch Showing Damaged Gutter, Soffit, Boxed Beam, and Existing Wood Handrailing



Photo 6 - Underside of East Boxed Beam Showing Rotted Wood from Water Damage



Photo 7 - Underside of East Boxed Beam Showing Rotted Wood from Water Damage



Photo 8 - East Window of North Facade First Floor Showing Damage to Existing Stucco Above Window



Photo 9 - Damaged Wood Header Above First Floor Windows



Photo 10 - Roof Porch Showing Membrane, Asphalt Shingle Roofing, and Wood Handrails



Photo 11 - Underside of Roof Porch Showing Condition of Wood Joists



Photo 12 - Underside of Roof Porch Showing Condition of Wood Joists



Photo 13 - North Elevation