Eitan Herskovitz 3234 N 49th St Milwaukee, WI 53216 H: 414-449-9134 C: 912-604-1417 rabbieitanh@gmail.com

November 11, 2024

To Whom it may concern,

On the evening of October 31, 2024, around 6 PM, a large portion of a tree fell onto our front yard at our home address of 3234 N 49th St Milwaukee, WI 53216. The tree was a City of Milwaukee tree between the sidewalk and the street. (the tree was actually in front of 3228 N 49th St).

The tree branches enveloped our 2015 Toyota Sienna (VIN: 5TDKK3DC4S666096, 75,146 miles). A branch dented the roof, broke the driver's side mirror, and caused numerous dents and scratches across the side and back of the van. Repairs were estimated at no less than \$14,220 (see enclosed 2 *preliminary estimates*) with the possibility of needing and incurring more expenses during the repairs to completely bring the van up to its prior state from before the event.

Please see the enclosed photos of the incident. A friendly neighbor offered to cut away some of the branches shortly after the incident. These photos were taken at the time while the branches were still over and on top of the van. Later in the evening, a crew came from the Dept of Forestry (10 PM) and took pictures as well of the damages. By then though, the branches had already been cleared from around the van.

The forestry crew (who did an excellent and expeditious job clearing the debris) did confirm that there were signs of decay on the tree at the time of failure. There were visible mushrooms at the location of the break. The head of the crew, "Bruce" did confirm this and showed me his documented report on this as well.

I may have proceeded with our own personal insurance but would like to request from the city, as they are whom I believe the responsible party.

Feel free to contact me by phone or email. I should be more or less available all day on my cell phone: 912-604-1417, and certainly by email: rabbieitanh@gmail.com. I would be happy to share the digital photos with you as well, and to discuss this incident with you further.

Thank you,

Eitan Herskovitz

Ein Zaille 11/11/2024

TOWN WOV HILWAUKEE

OFFICE OF CITY ATTURNEY 14 NOV '24 PM04:20



Gerber Collision & Glass -Milwaukee/Douglas Ave.

Highly Wreck - ommended! 6301 W Douglas Ave, Milwaukee, WI 53218 Phone: (414) 466-2111

Workfile ID: df45065c Federal ID: 51-0394062 State ID: N/A Federal EPA: N/A State EPA: N/A

Preliminary Estimate

Customer: HERSKOVITZ, EITAN

Written By: Yaser Shaiban

Insured:

HERSKOVITZ, EITAN

Policy #:

Claim #:

Type of Loss:

Point of Impact: 13 Rollover

Date of Loss:

Days to Repair: 0

Owner:

HERSKOVITZ, EITAN

(912) 604-1417 Cell

Inspection Location:

Gerber Collision & Glass -Milwaukee/Douglas Ave. 6301 W Douglas Ave

Milwaukee, WI 53218

Repair Facility

(414) 466-2111 Business

Insurance Company:

VEHICLE

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

VIN:

5TDKK3DC4FS666096

Interior Color:

Gray

Mileage In:

Vehicle Out:

License:

Exterior Color:

Shoreline Blue Pearl

Mileage Out:

State:

Production Date:

Job #:

CONVENIENCE

10/2015

Condition:

Fair

TRANSMISSION

Automatic Transmission

Intermittent Wipers

Stereo

Overdrive **POWER**

Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors Heated Mirrors Power Driver Seat

DECOR Dual Mirrors Privacy Glass

Console/Storage Overhead Console Air Conditioning

Tilt Wheel Cruise Control Rear Defogger

Keyless Entry Steering Wheel Touch Controls Rear Window Wiper

Telescopic Wheel Climate Control **Dual Air Condition** Backup Camera **Dual Power Sliding Doors**

Home Link **RADIO**

AM Radio FM Radio

Search/Seek CD Player

Auxiliary Audio Connection Satellite Radio

SAFETY

Drivers Side Air Bag Passenger Air Bag

Anti-Lock Brakes (4) 4 Wheel Disc Brakes Traction Control Stability Control

Front Side Impact Air Bags Head/Curtain Air Bags

Hands Free Device

ROOF

Luggage/Roof Rack **SEATS**

Cloth Seats 3rd Row Seat Captain Chairs (4)

WHEELS

Aluminum/Alloy Wheels **PAINT**

Clear Coat Paint

OTHER Rear Spoiler California Emissions

TRUCK

Rear Step Bumper

438754 Page 1 11/7/2024 2:18:24 PM

Customer: HERSKOVITZ, EITAN

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

Line	Оро	er	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	RESTRAINT SYSTE	EMS						
2	R&	l L	RT Head air bag			m	0.7	
3	R&	d l	LT Head air bag			m	0.7	
4	SEATS & TRACKS							
5	R8	M I	RT R&I front seat				0.4	
6	R8	M I	LT R&I front seat				0.4	
7	R8	M I	RT R&I second row seat				0.4	
8	R&	l I	LT R&I second row seat				0.4	
9	R&	kI I	RT R&I third row seat				0.4	
10	R&	kI I	LT R&I third row seat				0.4	
11	ROOF							
12	Rep	pl l	Roof panel	6311108060	1	1,902.52	22.5	4.5
13		,	Add for Clear Coat					1.8
14	Rep	pl l	Bow #5 (HSS)	6314808010	1	68.35	0.5	
15	Rep	pl l	Bow #6 (HSS)	6314908010	1	57.98	0.5	
16	Rep	pl l	Bow #4 (HSS)	6312808010	1	69.24	0.7	
17	Rep	pl I	LT Drip molding	7555208020	1	73.67	Incl.	
18	Rej	pl l	LT Side rail	6340808030	1	666.36	0.4	
19	Rep	pl l	LT End cover rear	6349408020	1	109.47		
20	Rep	pl l	LT End cover front	6349208020	1	104.73		
21	Rep	pl l	Headliner LE, SE gray	6331008959B0	1	2,140.13	Incl.	
22	PILLARS, ROCKER	8 F	LOOR					
23	Re	pl l	LT Roof rail	6111408020	1	275.40 s	5.0	1.5
24		,	Add for Clear Coat					0.3
25	FRONT DOOR							
26	* Rp	or I	LT Door shell (HSS)				3.0	2.1
27		(Overlap Major Adj. Panel					-0.4
28		,	Add for Clear Coat					0.3
29	** Re		A/M LT Black out tape rear section	7595808010	1	21.99	0.2	
30	Re	pl l	LT Belt molding	6821008020	1	42.89	0.3	
		-	Note: PARTS: Part cannot be reused	d/reinstalled.				
31	* Re		LT Mirror assy w/heated, w/o memory, w/o blind spot black	8794008150C1	1	141.15	0.3	0.5
32			Overlap Minor Panel					-0.2
33			Add for Clear Coat					0.1
34	R8		LT Handle, outside painted, w/o Smart key white pearl				0.5	
35	SIDE LOADING DO	OOR						
36	* Rp	or I	LT Door shell w/power (HSS)				<u>3.0</u>	2.2
37			Overlap Major Adj. Panel					-0.4
38	*		Add for Clear Coat					0.4
39	Re	pl	LT Protector	5874408010	1	37.35	0.3	

Customer: HERSKOVITZ, EITAN

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

~~~~				SUBTOTALS		5,927.27	55.8	15.9
58	#	Rpr	D&R Battery				0.3	
57	#	Repl	Corrosion Protection		1	5.00	0.2 -	
56	#	Subl	Hazardous Waste		1	10.00 T		
55	*	Repl	Cover car/bag		1	10.00	0.2	
54	MISCELLANEC	US OF	PERATIONS					
53	*	Rpr	Post-repair scan			m	<u>0.5</u> M	
52	*	Rpr	Pre-repair scan			m	<u>0.5</u> M	
51	VEHICLE DIAG	NOST	TCS					
50	*		Add for Clear Coat					0.1
49			Overlap Minor Panel					-0.2
48		Repl	Molding assy LE, w/rear camera	7680108903	1	115.91	0.3	0.7
47	LIFT GATE							
46		Repl	LT Protector	5874208010	1	18.10	0.2	
45	*		Add for Clear Coat					0.4
44			Overlap Major Adj. Panel					-0.4
43	*	Rpr	LT Side panel w/o blind spot				12.0	2.6
42	SIDE PANEL		rote. Tractor fair carmor be read	ed), en beanear				
41		кері	Note: PARTS: Part cannot be reus		1	37.03	0.5	
41		Repl	chrome LT Belt molding	6823008020	1	57.03	0.3	
40		R&I	LT Handle, outside w/o painted				0.3	

#### **NOTES**

Prior Damage Notes:

Front bumper LF frnder RF Door Rear bumper

#### **ESTIMATE TOTALS**

Category	Basis		Rate	Cost \$
Parts				5,917.27
Body Labor	54.8 hrs	@	\$ 80.00 /hr	4,384.00
Paint Labor	15.9 hrs	@	\$ 80.00 /hr	1,272.00
Mechanical Labor	1.0 hrs	@	\$ 130.00 /hr	130.00
Paint Supplies	15.9 hrs	@	\$ 60.00 /hr	954.00
Body Supplies	51.2 hrs	@	\$ 10.00 /hr	512.00
Miscellaneous				10.00
Subtotal				13,179.27
Sales Tax	\$ 13,179.27	@	7.9000 %	1,041.16
Grand Total				14,220.43

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

#### **Customer: HERSKOVITZ, EITAN**

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8531, CCC Data Date 09/10/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data dealerships with discounted pricing. provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKO, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

## **Customer: HERSKOVITZ, EITAN**

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## **Customer: HERSKOVITZ, EITAN**

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI Shoreline Blue Pearl

## **PARTS SUPPLIER LIST**

Line	Supplier	Description	Price
29	CollisionStoneGuard	#7595808010-0317LD	\$ 21.99
	W22192 11th st	A/M LT Black out tape rear section	
	Trempealeau WI 54661	Quote: 2990157311	
	(608) 782-5301	Expires: 11/14/24	
31	Toyota of Brookfield	#8794008150C1	\$ 141.15
	20655 W. Capitol Dr.	LT Mirror assy w/heated, w/o memory, w/o blind spot black	
	Brookfield WI 53045	Quote: 2993252884	
		Expires: 12/06/24	
48	Toyota of Brookfield	#7680108903	\$ 115.91
	20655 W. Capitol Dr.	Molding assy LE, w/rear camera	
	Brookfield WI 53045	Quote: 2992052721	
		Expires: 12/07/24	

# ANDREW AUTOMOTIVE COLLISION CENTER

Workfile ID: PartsShare: 8d732601 8dWys4

Federal ID:

39-1764755

1621 W. LaSalle St., MILWAUKEE, WI 53209 Phone: (414) 540-2559 FAX: (414) 228-7420

#### **Estimate**

**RO Number:** 

Customer:

Insurance:

Adjuster:

Estimator:

Will Chatfield

Herskovitz, Anton Phone: Claim:

Create Date:

11/6/2024

(912) 604-1417

Loss Date: Deductible:

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI

VIN:

State:

5TDKK3DC4FS666096

Interior Color:

Mileage In:

Vehicle Out:

License:

AJP9923

WI

Exterior Color: Production Date:

Mileage Out: Condition:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FENDER		· · · · · · · · · · · · · · · · · · ·				
2	E01	Remove/Install	LT R&I fender assy				1.9T	Body	
3	E01		WINDSHIELD						
4	E01	Remove/Install	Windshield Toyota w/o rain sensor				0.0T	Body	
5	E01		Urethane Kit	1	20.00T	Other			
6	E01		ROOF						
7	E01	Remove/Replace	Roof panel	1	1,902.52T	OEM	22.5T	Body	4.5T
8	E01		Add for Clear Coat					,	1.8T
9	E01	Remove/Replace	Add for luggage rack				0.6T	Body	
10	E01	Remove/Install	RT Drip molding				0.0T	Body	
11	E01	Remove/Install	LT Drip molding				0.0T	,	
12	E01	Remove/Replace	Headliner LE, SE tan	1	2,192.32T	OEM	0.0T	Body	
13	E01		PILLARS, ROCKER & FLOOR					,	
14	E01	Remove/Replace	LT Hinge pillar	1	392.14T	OEM	9.5T	Body	1.6T
15	E01		FRONT DOOR					,	
16	E01	Remove/Replace	LT Mirror assy w/heated, w/o memory, w/o blind spot pearl white	1	259.33T	OEM	0.3T	Body	
17	E01	Remove/Install	LT R&I door assy				1.3T	Body	
18	E01	Remove/Install	RT R&I door assy					Body	
19	E01		SIDE LOADING DOOR					/	
20	E01	Remove/Install	RT R&I door assy				1.5T	Body	
21	E01	Remove/Install	LT R&I door assy				1.5T	,	
22	E01		SIDE PANEL					,	
23	E01	Repair	LT Side panel w/o blind spot				4.0T	Body	2.6T
24	E01		Overlap Major Adj. Panel					/	(0.4)T
25	E01		Add for Clear Coat						0.4T
26	E01	Remove/Install	Fuel door				0.4T	Body	3.17

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

#### **RO Number:**

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI

27	E01	Remove/Install	LT Side glass Toyota, w/o power, w/o sunshade w/o privacy				0.5T	Body	
28	E01		LIFT GATE						
29	E01	Remove/Install	R&I liftgate assy				0.0T	Body	
30	E01	Remove/Replace	Spoiler	1	296.00T	LKQ	0.7T	Body	1.8T
31	E01		Overlap Major Non-Adj. Panel						(0.2)T
32	E01		Add for Clear Coat						0.3T
33	E01		REAR LAMPS						
34	E01	Remove/Install	LT Tail lamp assy				0.2T	Body	
35	E01		REAR BUMPER						
36	E01	Remove/Install	R&I bumper cover				0.8T	Body	
37	E01		VEHICLE DIAGNOSTICS						
38	E01	Repair	Pre-repair scan				0.5T	Mech	
39	E01	Repair	Post-repair scan				0.5T	Mech	
40	E01	Sublet	HAZARDOUS WASTE	1	5.00T	Other			
41	E01	Remove/Replace	COVER CAR EXTERIOR	1	10.00T	A/M	0.3T	Body	
42	E01	Remove/Replace	CORROSION PROTECTION	1	10.00T	A/M	0.3T	Body	
43	E01		r&i dash				4.0T	Body	
44	E01		*prelim visual est only!*						
45	E01		*teardown necessary*						
46	E01		*additional charges may apply*						
47	E01		*Calibrations maybe necessary*						

<b>Estimate Totals</b>	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts		103.60			5,185.91
Sublet/Miscellaneous					5.00
Labor, Body			78.00	51.6	4,024.80
Labor, Refinish			78.00	12.4	967.20
Labor, Mechanical			180.00	1.0	180.00
Material, Paint			55.00	12.4	682.00
Material, Shop			4.00	38.6	154.40
Subtotal					11,199.31
Sales Tax					660.76
Grand Total	6				11,860.07
Net Total					11,860.07

Estimate Version	Total \$
Original	11,860.07
Insurance Total \$:	11,860.07
Received from Insurance \$:	0.00
Balance due from Insurance \$:	11,860.07
Customer Total \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

## **Estimate**

#### **RO Number:**

2015 TOYO Sienna LE FWD w/7-Passenger Seating w/Auto Access Seat 4D VAN 6-3.5L Gasoline Sequential MPI

Received from Customer \$: 0.00

Balance due from Customer \$: 0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural





















