To whom this may concern:

On Friday evening, April 8th 2022 I was out driving making deliveries. I was traveling westbound on Vine street when I hit a pot hole on 28th street in Milwaukee, WI. At that moment, I was concerned but I was hoping everything was okay with my vehicle. I quickly noticed that may not be the case. I noticed a rattling noise coming from the front driver side. I turned my music off and listened to the vehicle and decided to park it until I can get it looked at. As I drove home, there was a loud rattling noise & the car was swaying to the left every time I used the break pedal. That had never happened before. I immediately called Subaru City right before they closed to see if I could get the vehicle in as soon as possible. They let me bring it in Saturday morning, April 9th, 2022. I received my estimate for my repairs Monday morning, April, 11th 2022. I am contacting you all for compensation for my repairs, any rental cost fees and inconvenience I am / may occur during this process. Thank you for taking the time to read my letter and look at my claim. I look forward to hearing from you all soon.

The estimates of the repairs & pictures will be attached with this letter.


04/12/22

Jennifer Merriweather


jenn.merriweather@gmail.com

414-690-9282


CITY CLERK'S OFF



Photos 30 potholes the street



Both photos above are of the pothole I hit on Friday, April 8th, 2022.



Both photos above are of the pothole I hit on Friday, April 8th, 2022.



This is a picture of three or four other pot holes on same street.



Repair Order Estimate

Printed Date: April 9, 2022

We have performed our multi-point inspection on your vehicle and the following services were recommended.

EXISTING SERVICES

Job	Quote
DRIVEABILITY CUSTOMER STATES WHEN SHE BRAKES CAR VEERS TO THE LEFT AND	PENDING
MULTI-POINT INSPECT CUSTOMER REQUESTS MULTI-POINT INSPECTION	PENDING
LOANER VEHICLE LOANER VEHICLE \$39.95 A DAY VALUE - THIS IS A NO SMOKING VEHICLE	INTERNAL
Existing Services Total	

SUGGESTED SERVICES

Job		Quote
BRAKE FLUID EXCHANGE Customer Requests Subaru Brake Fluid Exchange Recommended Maintenance	ATE ATTENTION	165:43
man and the second seco	Labor Hrs	
	Parts	
	Misc	
	Tax	
	Total	165.43
Job		Quote
P/S FLUSH FLUSH POWER STEERING SYSTEM FLUID	ATE ATTENTION	123.41
	Labor Hrs	77.0
	Parts	
	Misc	
	Tax	
	Total	123.41



p de la company de la comp		Quote
ANS SRV & RELEARN RANSMISSION AND RELEARN	IMMEDIATE ATTENTION	158.24
	Labor Hrs	
	Parts	
	Misc	
	Тах	
	Total	158.24
		Quote
REAR DIFF SVC RONT AND REAR DIFF SERVICE SYNTHETIC	IMMEDIATE ATTENTION FLUIDS ADDITIONAL	219.62
	Labor Hrs	
	Parts	
	Misc	
	IIII30	
	Tax	
	Tax Total	219.62
Company of the State of the Company of the State of State	Total	219.62 Quote
DID T'LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM	STATE OF THE PARTY OF THE PARTY.
LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM	Quote
FLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY.	Quote
FLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs	Quote
LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax	Quote 818.64
LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc	Quote 818.64 818.64
T'LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total	Quote 818.64
T LWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL DO OD /HEEL ALIGNMENT	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax	Quote 818.64 818.64
TLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL OID WHEEL ALIGNMENT WHEEL ALIGNMENT() PULLS LEFT() PULLS	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION RIGHT () STEERING WHEEL NOT STRAIGHT ()	Quote 818.64 818.64 Quote
TLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL BUSH THAT ARE TEARING SIGNIFICANT SIGNIFICANTL BUSH THAT ARE TEARING SIGNIFICANT SIGNIFICANT SIGNIFICANT SIGNIFICANT SIGNIFIC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION RIGHT () STEERING WHEEL NOT STRAIGHT () Labor Hrs	Quote 818.64 818.64 Quote
TLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL BUSH THAT ARE TEARING SIGNIFICANT SIGNIFICANTL BUSH THAT ARE TEARING SIGNIFICANT SIGNIFICANT SIGNIFICANT SIGNIFICANT SIGNIFIC	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION RIGHT () STEERING WHEEL NOT STRAIGHT () Labor Hrs Parts	Quote 818.64 818.64 Quote
TLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL OID THEEL ALIGNMENT WHEEL ALIGNMENT () PULLS LEFT () PULLS	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION RIGHT () STEERING WHEEL NOT STRAIGHT () Labor Hrs Parts Misc Labor Hrs Parts Misc	Quote 818.64 818.64 Quote
TLWR CTRL ARM BSHN REPLACE FRONT LOWER CONTROL ARM BUS DUE TO FAILURE OF FRONT SUB FRAME REC BUSHINGS THAT ARE TEARING SIGNIFICANTL OD WHEEL ALIGNMENT WHEEL ALIGNMENT() PULLS LEFT() PULLS	IMMEDIATE ATTENTION SHING COMMEND REPLACEMENT OF CONTROL ARM LY. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION RIGHT () STEERING WHEEL NOT STRAIGHT () Labor Hrs Parts	Quote 818.64 818.64 Quote



lob		Quote
SPARK PLUGS	IMMEDIATE ATTENTION	483.93
REPLACE SPARK PLUGS		
	Labor Hrs	
	Parts	
	Misc	
	Tax	
	Total	483.93
Job		Quote
ADDITIVE, AND CLEAN THROTTLE PLATES	IMMEDIATE ATTENTION ISTALL FUEL INJECTOR CLEANER, GAS TANK STALL FUEL INJECTOR CLEANER, GAS TANK	200.85
ADDITIVE AND CLEAN THROTTLE PLATES	Labor Hrs	
	Parts	
	Part William Control of Factors	
	I WISC	
	Misc	
	Tax Total	200.85
Job	Tax	200.85 Quote
THE PARTY OF THE P	Tax Total IMMEDIATE ATTENTION	National Conference of the Con
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM	Tax Total IMMEDIATE ATTENTION	Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT.	Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs	Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts	Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total	Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax	Quote 449.41
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total	Quote 449.41 449.41
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN Job HEADLAMP BULB	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION	Quote 449.41 449.41 Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN Job HEADLAMP BULB REPLACE HEADLAMP BULB	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION	Quote 449.41 449.41 Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN Job HEADLAMP BULB REPLACE HEADLAMP BULB	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION COMMEND REPLACEMENT.	Quote 449.41 449.41 Quote
FT AXLE REPLACE FRONT DRIVE AXLE ASSY OEM DRIVER FRONT OUTER AXLE BOOT TORN Job HEADLAMP BULB REPLACE HEADLAMP BULB	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION COMMEND REPLACEMENT. Labor Hrs	Quote 449.41 449.41 Quote
DRIVER FRONT OUTER AXLE BOOT TORN Job HEADLAMP BULB REPLACE HEADLAMP BULB	Tax Total IMMEDIATE ATTENTION RECOMMEND REPLACEMENT. Labor Hrs Parts Misc Tax Total IMMEDIATE ATTENTION COMMEND REPLACEMENT. Labor Hrs Parts	Quote 449.41 449.41 Quote



		Quote
SIDE MARKER BULB EPLACE FRONT SIDE MARKER BULB	IMMEDIATE ATTENTION	54.94
ASSENGER FRONT MARKER BULB OUT RECOMMEN	ND REPLACEMENT.	
	Labor Hrs	ASSYSTEM POR USE CONTROL INC.
	Parts	
	Misc	
	Tax	
	Total	54.94
		Quote
ULB CONCERN OTH FRONT CLEARANCE BULBS OUT RECOMMEND	IMMEDIATE ATTENTION D REPLACEMENT	109.89
	Labor Hrs	The Committee of the Co
	Parts	
	Misc	
	Tax	
	Total	109.89
		Orroto
b TEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI TOUND FRONT SUBFRAME COLLAPSED. RECOMMEND REPLACEMENT OF FRONT SUBFRAME		Quote 1,981.28
DEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI OUND FRONT SUBFRAME COLLAPSED.		
DEFING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DO OUND FRONT SUBFRAME COLLAPSED.	<u> </u>	
DEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI OUND FRONT SUBFRAME COLLAPSED.	E. Labor Hrs	
DEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI OUND FRONT SUBFRAME COLLAPSED.	E. Labor Hrs Parts	
DEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI OUND FRONT SUBFRAME COLLAPSED.	Labor Hrs Parts Misc	
DEERING/SUSPENSION DURING INSPECTION FOR VEERING TO THE LEFT DI OUND FRONT SUBFRAME COLLAPSED.	Labor Hrs Parts Misc Tax	1,981.28

RECOMMENDED NOT DONE

The following services were recommended but not completed during your visit. Please contact us to get these scheduled.

All estimates are good for 30 days from time of estimate. Taxes and other fees are subject to change.

the se is are the jobs that need to

be done related to the damages

Caused by hitting the pot hole on 28th 1 Vine.

Total = 3,353.72 plus tax