

CLEMON R. THAMES

2725-N-38TH ST

MILW, WI. 53210

PH# 414-871-1545

I "Clem R Thames,"

Own a 2001 Buick, "Park Ave." ON

August 20-2000, between 5:30 and 6:00 PM,

I was helping my daughter move. I got a

phone call, a tree had fallen on the

roof of my car. I went home, and the

tree had smashed my car. My car were

Parked in front of 2729-N-38TH ST.

CITY OF MILWAUKEE
10 OCT 21 AM 9:28
RONALD O. LEONHARDT
CITY CLERK

CITY OF MILWAUKEE
RECEIVED
20 OCT 25 PM 1:00
OFFICE OF
CITY ATTORNEY

ADAMS AUTO BODY

2719 North 5th Street
Milwaukee, WI 53212
562-6161



Written By [Signature]
Ins Co _____
Adj _____
Claim _____
No. _____
Pol. _____
No. _____
Ins. _____
Phone _____
Apri _____
Co _____
Apri _____
Name _____
Phone _____

Date In _____ Date Out _____
Damage Estimate Code Key
A-Align N-New P-Paint R-Repair RR-Remove and Replace RI-Right
U-Used S-Straighten C-Center Lr-Lower Lt-Left Op-Open Up-Upper AM-After Market

Name Clemon Thames Date 8/26/10
Address 2725 N. 38th City Milw State WI Zip 53210
Hm Ph 871-1545 Wk Ph _____ ID Number _____
Year 01 Buik Built Model Park Ave 4dr License _____ Speedometer _____

Repair	Replace	Miscellaneous	Paint No.	Subject	Labor Hours	Paint Hours	Parts Price
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							

REPAIR EXCEED VALUE

Value is

6400.00

This estimate is based on our inspection and does not cover any additional parts or labor which may be required after the work has been opened up.

NOT RESPONSIBLE FOR ANY PERSONAL ITEMS LEFT IN CAR

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate the above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or in case of fire or theft, accident or any other cause beyond your control. STORAGE WILL BE CHARGED FORTY-EIGHT HOURS AFTER REPAIRS ARE COMPLETED IN THE EVENT LEGAL ACTION IS NECESSARY TO ENFORCE THIS CONTRACT. I WILL PAY REASONABLE ATTORNEY'S FEES AND COURT COST.

SIGNED
X _____

Terms: STRICTLY CASH unless Arrangements Made.

PARTS	
LABOR	hrs es _____
PAINT	hrs. es _____
PAINT MATERIALS	
MECH	hrs. es _____
FRAME	hrs. es _____
TOWING	STORAGE
MISC.	SUBLET
EPA/WASTE DISPOSAL CHARGE	
SUB TOTAL	<i>6400.00</i>
TAX	
TOTAL	

FOREST HOME AUTO BODY
3135 W. FOREST HOME AVENUE
MILWAUKEE, WISCONSIN 53215
OFFICE: 414-384-6360 FAX: 414-384-6354
FEDERAL ID # 39-1897933

*** PRELIMINARY ESTIMATE ***

09/09/2010 01:25 PM

Owner

Owner: CLEMON thames
Address: 2725 N. 38TH ST.
City State Zip: Milwaukee, WI 53210

Work/Day:
FAX:

Inspection

Inspection Date: 09/09/2010 01:26 PM
Primary Impact: Roof

Inspection Type:
Secondary Impact:

Appraiser Name: MARTY/DEBBIE ZABEL
Address: 3135 W. FOREST HOME AVE.
City State Zip: Milwaukee, WI 53215

Appraiser License # :
Work/Day: (414)384-6360
FAX: (414)384-6354

Repairer

Repairer: FOREST HOME AUTO BODY
Address: 3135 W. FOREST HOME AVENUE
City State Zip: Milwaukee, WI 53215
Email: FORESTAB@SBCGLOBAL.NET

Contact: MARTY & DEBBIE ZABEL
Work/Day: (414)384-6360
FAX: (414)384-6354
Work/Day:

Vehicle

2001 Buick Park Avenue STD 4 DR Sedan
6cyl Gasoline 3.8
4 Speed Automatic

Lic.Plate: 992-PRB
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: WHITE
Ext. Refinish: Two-Stage

Lic State: WI
VIN: 1G4CW54K714173427
Mileage: 160,000
Mileage Type: Actual
Code: S5323A
Int. Color: GRAY
Int. Refinish: Two-Stage

Options

Alarm System
Chromed Alloy Wheels
Cruise Control
Dual Power Seats
Keyless Entry System
Lighted Entry System
Power Door Locks
Power Windows
Side Airbags
Tilt Steering Wheel

Anti-lock Brakes
Climate Control For A/C
Dual Air Conditioning
Heated Front Seats
Leather Seats
Overhead Console
Power Mirrors
Rear Window Defroster
Strg Wheel Radio Control
Tinted Glass

Auto Load Leveling
Compact Disc W/Tape
Dual Airbags
Intermittent Wipers
Leather Steering Wheel
Power Brakes
Power Steering
Rem Trunk-L/Gate Release
Tachometer

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
1	SB	143		Windshield,Tinted	Sublet Repair	\$227.00*			SM
2	EU	365	07	Panel,Bodyside Otr Up LT	Replace Recycled	\$100.00*	+25.00	24.4	SM

3	L	365		Panel,Bodyside Otr Upr LT	Refinish			1.3	RF
					1.1 Surface				
					0.2 Two-stage				
4	EU	366	07	Panel,Bodyside Otr Upr RT	Replace Recycled	\$100.00*	+25.00	19.5	SM
5	L	366		Panel,Bodyside Otr Upr RT	Refinish			1.3	RF
					1.1 Surface				
					0.2 Two-stage				
6	I	208		Door Shell,Front RT	Repair			1.0*	SM
				>> CAN NOT OPEN DOOR					
7	EU	287		Door Assembly,Rear LT	Replace Recycled	\$250.00*	+25.00	2.6	SM
8	L	287	13	Door Shell,Rear LT	Refinish			4.3	RF
					2.1 Surface				
					1.0 Edge				
					0.6 Two-stage setup				
					0.6 Two-stage				
9	RI	321		W/Strip,Belt Outer LT	R & I Assembly			INC	SM
10	RI	309		Handle,RR Door Outer LT	R & I Assembly			0.4	SM
11	EU	341		Panel,Roof	Replace Recycled	\$250.00*	+25.00	14.4	SM
12	L	341		Panel,Roof	Refinish			4.0	RF
					3.3 Surface				
					0.7 Two-stage				
13	E	295		Mldg,Roof Drip LT	12372223 GM Part	\$143.22		INC	SM
14	L	295		Mldg,Roof Drip LT	Refinish			0.4	RF
					0.3 Surface				
					0.1 Two-stage				
15	E	296		Mldg,Roof Drip RT	12372222 GM Part	\$142.98		INC	SM
16	L	296		Mldg,Roof Drip RT	Refinish			0.4	RF
					0.3 Surface				
					0.1 Two-stage				
17	E	872	01	Headliner,Roof	88890767 GM Part	\$643.28		INC	SM
18	SB	369		Back Glass,Heated	Sublet Repair	\$352.00*			SM
19	I	389		Panel,Quarter LT	Repair			6.5*	SM
20	L	389		Panel,Quarter LT	Refinish			2.6	RF
					2.2 Surface				
					0.4 Two-stage				
21	I	390		Panel,Quarter RT	Repair			4.5*	SM
22	L	390		Panel,Quarter RT	Refinish			2.5	RF
					2.3 Surface				
					0.2 Two-stage				
23	RI	554		Taillamp Assembly LT	R & I Assembly			INC	SM
24	RI	555		Taillamp Assembly RT	R & I Assembly			INC	SM
25	EC	M07		Pinstripes-Tape	Replace Economy	\$12.00*		0.5*	SM
26	I	M14		Corrosion Protection	Sublet Repair	\$10.00*		0.3*	SM
27	I	M31		Set-Up For Realignment	Repair			2.0*	FR
28	EC	M60		Hazardous Waste Removal	Replace Economy	\$3.00*			SM
29	I	M69		Glass Clean Up	Repair			1.0*	SM
30	I			UNIBODY REALIGN	Repair			4.5*	SM*
30	Items								

MC Message

01 CALL DEALER FOR EXACT PART # / PRICE
07 STRUCTURAL PART AS IDENTIFIED BY I-CAR
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts	\$929.48	
Other Parts	\$715.00	
Paint Materials	\$537.60	
Line Item Markup	\$175.00	
Parts & Material Total		\$2,357.08
Tax on Parts & Material	@ 5.600%	\$132.00

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$52.00	61.8	17.8	79.6	\$4,139.20
Mech/Elec (ME)	\$64.00				
Frame (FR)	\$58.00		2.0	2.0	\$116.00
Refinish (RF)	\$52.00	16.8		16.8	\$873.60
Paint Materials	\$32.00				

Labor Total	98.4 Hours	\$5,128.80
Tax on Labor	@ 5.600%	\$287.21
Sublet Repairs		\$589.00
Tax on Sublet	@ 5.600%	\$32.98
Gross Total		\$8,527.07
Net Total		\$8,527.07

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53215 Default

Audatex Estimating 6.0.217 ES 09/09/2010 01:33 PM REL 6.0.217 DT 08/01/2010 DB 09/08/2010
Copyright (C) 2009 Audatex North America, Inc.

3.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2009 Audatex North America, Inc.
Audatex Estimating is a trademark of Audatex North America, Inc.

ANDREW AUTOMOTIVE - BODY REPAIR CENTER
1621 W. LA SALLE ST.
MILWAUKEE, WI 53209
PH: 414-540-2559 FX: 414-228-7420

CD LOG NO 29462-1 DATE 09/10/10

SHOP: ANDREW AUTO BODY REPAIR INSP DATE: 09/10/10
ADDRESS: 1621 W. LASALLE ST. CONTACT: DAVID MAERTZ
CITY STATE: GLENDALE, WI PHONE 1: (414)540-2559
ZIP: 53209- FAX: (414)228-7420

OWNER: THAMES, CLEMON HOME PHONE: (414)871-1545
ADDRESS: 2725 N. 38TH ST.
CITY STATE: MILWAUKEE, WI
ZIP: 53210

POINT OF IMPACT: 0

LIC#: STATE: VIN: 1G4CW54K714173427
BODY COLOR: WHITE MILEAGE:
CONDITION: GOOD ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

2001 BUICK PARK AVENUE STD 4DOOR SEDAN 6CYL GASOLINE 3.8
CODE: S5323A/E OPTNS K/24F

OPTIONS:
TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES
STRG WHEEL MTD RADIO CONTROLS

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS	R
I			VEH IS OBVIOUS TOTAL L SUBLET REPAIR		10000.00*				1*

1 ITEMS

FINAL CALCULATIONS & ENTRIES
PARTS & MATERIAL TOTAL

LABOR	RATE	REPLACE HRS	REPAIR HRS
1-SHEET METAL	54.00		

2001 BUICK PARK AVENUE STD 4DOOR SEDAN
CD LOG NO 29462-1

2-MECH/ELEC	102.00
3-FRAME	55.00
4-REFINISH	54.00
5-PAINT MATERIAL	34.00

LABOR TOTAL

SUBLET REPAIRS		10,000.00
TAX ON SUBLET	@	5.600% 560.00
TOWING		
STORAGE		

GROSS TOTAL 10,560.00

NET TOTAL 10,560.00

SHOPLINK UG202 ES CD LOG 29462-1 DATE 09/10/10 11:19:05AM R6.37 CD 08/10

PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53209

HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.



David Maertz

Asst. Bodyshop Mgr./Estimator
Email: Andrewautobody@gmail.com
Direct Line: (414) 247-6557

1621 W. LaSalle St.
Milwaukee, WI 53209

Phone: (414) 540-2559
Fax: (414) 228-7420