OFFICE OF THE CITY CLERK MILWAUKEE, WISCONSIN 200 E Wells Street, Room 205 Milwaukee, WI 53202

STEVE REUPERT	
1630-1632 N 60TH S	ST.
MILWAUKEE, WI 532	08
(630) 703-8443	
sreupert@gmail.com	m

Plaintiff,

VS.

CITY OF MILWAUKEE

Defendant.



STATEMENT OF CLAIM

On Tuesday, August 10th at approximately 8:10 PM a storm same to Milwaukee with winds strong enough to deroot trees. A tree owned by the city of Milwaukee, that lies between the sidewalk and street, directly in front of the plantiffs address (1630-1632 N 60ths St, Milwaukee, WI 53208) was derooted and fell on the home. Damages from the tree to the home include, but may not be limited to, gutters, facia, flashings, railing, shrubs, lawn, structural, siding, and drywall.

PLAINTIFF, STEVE REUPERT is seeking relief for the damages caused by the tree in the sum of \$28,548.33 from the THE CITY OF MILWAUKEE.

Included within this statement of claim are 3 estimates to repair the damage. One of the estimates includes pictures and damages caused when city tree struck the home at 1630-1632 N. 60th St., Milwaukee, WI 53208

I, STEVE REUPERT, can be contacted at the address above, by phone (630) 703-8443, or email, sreupert@gmail.com for any questions regarding the incident.

UPPTICE OF CITY ATTORNEY IN

(Steven G. Reupert)

(Date)

Client:

Steve Reupert

Home:

1630-1632 N 60 Street Milwaukee, WI 53208

Operator:

AFRESHLO

Estimator:

MaryJo Parbs

Company:

A Fresh look Restoration, Remodeling

Business:

8822 W Lincoln Ave

West Allis, WI 53227-2408

Type of Estimate:

hail and wind damage

Date Entered:

8/17/2021

Date Assigned:

Price List:

WIMW8X_AUG21

Labor Efficiency:

Restoration/Service/Remodel

Estimate:

2021-08-17-1445

Home: (630) 703-8443

Business:

(414) 448-6228

E-mail:

afreshlookrestoration@gmail.

com

2021-08-17-1445

2021-08-17-1445

DESCRIPTION	QTY	UNIT PRICE	TOTAL
General Demolition - per hour	27.00 HR @	53.58 =	1,446.66
2. R&R 1/2" drywall - hung, taped, floated, ready for paint	28.00 SF @	3.34 =	93.52
4. Painters - per hour	32.00 HR @	69.80 =	2,233.60
6. Soffit & Fascia Installer - per hour	8.00 HR @	125.17 =	1,001.36
10. R&R Drip edge/gutter apron	1,619.00 LF@	3.22 =	5,213.18
12. R&R Gutter / downspout - aluminum - 6"	55.00 LF@	13.22 =	727.10
14. Gutter / downspout - Detach & reset	55.00 LF @	6.07 =	333.85
41. R&R Porch or deck handrail w/turned balusters	36.00 LF @	42.93 =	1,545.48
40. Painter - per hour	24.00 HR @	69.80 =	1,675.20
39. General clean - up	7.00 HR @	42.81 =	299.67
38. Clean siding - metal or vinyl	3,000.00 SF @	0.34 =	1,020.00
37. Prime & paint metal siding	3,000.00 SF @	0.93 =	2,790.00
36. Paint column - two coats	24.00 LF @	3.89 =	93.36
17. R&R Soffit - metal	42.00 SF @	7.94 =	333.48
43. Upper deck porch. Not sure what the structual engineer will recommend.	1.00 EA @		0.00
18. R&R Fascia - metal - 6"	68.00 LF @	6.67 =	453.56
19. R&R Wood column - 12" diameter	12.00 LF @	65.86 =	790.32
21. R&R Rubber roofing - Fully adhered system - 60 mil	1.00 SQ @	637.32 =	637.32
24. Electrician - per hour	2.00 HR @	110.00 =	220.00
34. Aluminum rake/gable edge trim - mill finish	11.00 LF@	5.23 =	57.53
26. Structural engineer residential evaluation fee	1.00 EA@	500.00 =	500.00
27. Precast railing	12.00 LF @	42.32 =	507.84
29. Tree - removal - per hour (Labor only)	1.00 HR @	53.58 =	53.58
30. Clean tree (potted) - large	1. 00 EA @	44.13 =	44.13
32. Plants - shrubs - deciduous - 5 gallon	3.00 EA @	80.40 =	241.20
Labor Minimums Applied			
DESCRIPTION	QTY	UNIT PRICE	TOTAL
3. Drywall labor minimum	1.00 EA @	407.81 =	407.81
25. Electrical labor minimum	1.00 EA @	55.00 =	55.00

Summary

Line Item Total	22,774.75
Permit	500.00
Material Sales Tax	249.10
Services Mat'l Tax	1.51
Subtotal	23,525.36
Overhead	2,352.56
Profit	2,587.80
Service Sales Tax	82.61
Replacement Cost Value	\$28,548.33
Net Claim	\$28,548.33

MaryJo Parbs

\$ 10 m

Recap of Taxes, Overhead and Profit

0	verhead (10%)	Profit (10%)	Material Sales Tax (5%)	Services Mat'l Tax (5%)	Service Sales Tax (5%)	Manuf. Home Tax (5%)	Storage Tax (5%)
Line Ite	ms						
	2,302.56	2,532.80	249.10	1.51	82.61	0.00	0.00
Addition	nal Charges						
	50.00	55.00	0.00	0.00	0.00	0.00	0.00
Total							
	2,352.56	2,587.80	249.10	1.51	82.61	0.00	0.00

2021-08-17-1445

Page: 4

Recap by Room

Estimate: 2021-08-17-1445 Labor Minimums Applied	22,311.94 462.81	97.97% 2.03%
Subtotal of Areas	22,774.75	100.00%
Total	22,774.75	100.00%

Recap by Category

O&P Items	Total	%
CONT: CLEAN - GENERAL ITEMS	44.13	0.15%
CLEANING	1,319.67	4.62%
GENERAL DEMOLITION	2,473.28	8.66%
DRYWALL	487.61	1.71%
ELECTRICAL	275.00	0.96%
PERMITS AND FEES	500.00	1.75%
FINISH CARPENTRY / TRIMWORK	657.24	2.30%
FRAMING & ROUGH CARPENTRY	1,497.60	5.25%
LABOR ONLY	2,233.60	7.82%
LANDSCAPING	241.20	0.84%
MASONRY	507.84	1.78%
PAINTING	4,558.56	15.97%
ROOFING	5,204.44	18.23%
SOFFIT, FASCIA, & GUTTER	2,774.58	9.72%
O&P Items Subtotal	22,774.75	79.78%
Permits and Fees	500.00	1.75%
Material Sales Tax	249.10	0.87%
Services Mat'l Tax	1.51	0.01%
Overhead	2,352.56	8.24%
Profit	2,587.80	9.06%
Service Sales Tax	82.61	0.29%
Total	28,548.33	100.00%




1-Uprooted Tree

Date Taken: 8/13/2021




2 2-Uprooted tree

Date Taken: 8/13/2021



3-Tree on house

3



4-Tree on house

Date Taken: 8/10/2021



11-Busted railing upper

Date Taken: 8/13/2021


2021-08-17-1445

11



12 12-Busted railing upper

Date Taken: 8/13/2021



13-Upper railing

13


Date Taken: 8/13/2021



14-Upper railing


14

Date Taken: 8/13/2021




15 15-Upper railing

Date Taken: 8/13/2021




16 16-Top porch damage Date Taken: 8/13/2021



17-Damaged railing

17


Date Taken: 8/13/2021



19-Storm samage to fascia

19


Date Taken: 8/13/2021



20-Storm damage rubber roof

20

Date Taken: 8/13/2021




21-End cap damages

Date Taken: 8/13/2021

2021-08-17-1445


21



22-Separation of the bent gutter

22

Date Taken: 8/13/2021




23-Fascia damage Date Taken: 8/13/2021

23




24 24-Fascia damage


Date Taken: 8/13/2021




26 26-Rubber roof Date Taken: 8/13/2021 Rubber roof damaged causing the leak inside of the home.




27 27-Railing Date Taken: 8/13/2021
The railing you see is weak as a result of the weight of the tree. Needs replacing.



28 28-Missing railing Date Taken: 8/13/2021
There was a black metal raining on the stair that the tree took out.




29 29-Column Damage Date Taken: 8/13/2021
The colomn is damaged as a result of the weight of the tree. This supports the left upper deck porch.




30 30-Column Damage Date Taken: 8/13/2021

The colomn is damaged as a result of the weight of the tree. This supports the upper deck porch.



31 31-Separation

There is separation between the soffit and the trim around the door. The weight of the tree was weighing down the upper deck porch causing the separation.




32 32-Upper Porch

Date Taken: 8/13/2021

Here you can see the damage showing the weight from the tree has unsecured the upper deck porch. Needs a structure inspection.



33 33-Fascia Date Taken: 8/13/2021
Weight of the tree has bowed down the structure causing the damage to the fascia and deck.



34-Gutter & Soffit Gutter and soffit damage.

Date Taken: 8/13/2021

2021-08-17-1445

34



35-Gutter & Soffit

35


Date Taken: 8/13/2021



36-Damaged caused by weight


36

Date Taken: 8/13/2021




37 37-20210813_145520


Date Taken: 8/13/2021




38 38-Top Column Date Taken: 8/13/2021
The column has cracked from the weight of the tree. This supports the upper deck porch.



39 39-DamageDamage above the other column.




40 40-Fascia Date Taken: 8/13/2021




41 41-Soffit Soffit separation.

Date Taken: 8/13/2021




42 42-Soffit bowed Soffit has bowed and separated.



43 43-Fascia buckled Date Taken: 8/13/2021

Buckled fascia. Not sure about the condition of the wood underneath it from the weight of the tree when it hit.



44 44-Showing Separation Date Taken: 8/13/2021 Between soffit and fascia separation.

2021-08-17-1445



45 45-Upper deck separating Date Taken: 8/13/2021 Upper deck is separating a bit from the house.




46 46-Left side Date Taken: 8/13/2021 Soffit and fascia damaged. Separation is visual here as well.




47 47-Side gutter Date Taken: 8/13/2021
This gutter was damaged by the tree.

2021-08-17-1445




49 49-End of gutter


Left side damage from the tree.



49 50-Left side Date Taken: 8/13/2021
Showing the damage from the tree to the fascia and the soffit.



Gutter damaged.



51 52-Cracking Date Taken: 8/13/2021 The column on the right side is sitting above this.




53-Showing separation

52

Date Taken: 8/13/2021




53 54-Showing the separation Date Taken: This is part of the upper deck porch.




55-More separation Date Taken: 8/13/2021

54



55 56-Lawn damage


Date Taken: 8/13/2021



56 57-Damaged shrubs



57 58-Missing tree Date Taken: 8/13/2021
Home owner had a smaller tree here. The city tree took that out too.




58 59-Another image Date Taken: 8/13/2021
Another image of where the tree was that the home owner had.



59 60-Damaged shrubs

Date Taken: 8/13/2021



60 61-Damaged shrubs

Date Taken: 8/13/2021



WeatherPro Exteriors

12200 W. Adler Lane West Allis, WI 53214 Phone: 414-543-0929

Company Representative

Heath Swanson Phone: (414) 712-8397

hswanson@weatherproexteriors.com

Vinyl siding, gutters, soffit/fascia, Flat Roof, Railings

Steve Reupert

1630 North 60th Street Milwaukee, WI 53208 (630) 703-8443 Job: Steve Reupert

Siding - Vinyl Section

Furnish and Install Mastic Carvedwood Premium Vinyl Siding (.44).

SIDING DESCRIPTION:

- Exclusive Hang-Tough Technology boosts durability so panels are more resistant to cracking, impact and thermal distortion
- Rollover, Reinforced Nail Hem for easier installation and secure fastening
- Non-toxic pest resistant mineral additives.
- Patented T-2 LOK Panel Locking System delivers a positive locking action with a wider locking mechanism for more contact area
- 5/8" Panel Projection to replicate the appearance of real wood siding
- Durable and extra thick to resist dents from everyday life
- Duranyl 5000 Protection System proprietary technology adds extra UV protection to our deepest, most vivid colors, and protections colors against hard elements and maximizes long-term weatherability.
- Sustainable and recyclable for a better, eco-friendly choice.

PROFILE/REVEAL HEIGHT: 5"
SIDING COLOR: White or light color

CORNER SIZE: Standard

CORNER COLOR: Same as siding

TRIM COLOR: White

Comes with J-Channel trim, accessories and premium 4" corner posts (4").

PROJECT INCLUDES:

- Removal of (1) existing layer of siding down sheathing.
- Sheathing will be inspected for rotten or bad wood.
- Re-nail any loose wood/sheathing. If bad or rotten wood is discovered, it will be replaced at \$90 per sheet of OSB.
- Tyvek brand moisture barrier underlayment furnished and installed
- New flashing over window and door openings as necessary
- All J-channel, light blocks, outlet blocks, and accessories per product system
- All window and door openings shall be flashed per manufacturers instructions and industries best practices when applicable.**

NOTE:

Project may involve the removal of exterior lighting fixtures and/or other similar fixtures. WeatherPro Exteriors recommends installation of new fixtures by a certified professional to further enhance the beauty of your homes exterior.

PROJECT NOTES:

The balcony railings will be supplied by customer, railing install price is included with siding cost. Front porch railings will be replaced and installed with metal equivalent.

LEAD SAFE PROCEDURE: Yes

SIDING WARRANTY:

- Mastic's Industry LEADING V.I.P. Limited Lifetime Warranty
- 200 MPH Wind Resistance Warranty
- WeatherPro Exteriors Lifetime Workmanship Warranty

WEATHERPRO EXTERIORS PROJECT GUIDELINES:

- Remove and clean up of all job related debris and will be disposed of properly.
- Includes all labor, materials, taxes and permits.
- WeatherPro Exteriors is licensed and insured.
- WeatherPro Exteriors follows and maintains all OSHA guidelines and regulations during the production of the project.

Price

\$45,495.00

Soffit/Fascia Section

Furnish and Install NEW Aluminum Soffit and Facia (cladding over existing wood) in customers choice of color,

LOCATION: House FACIA COLOR: White SOFFIT COLOR: White

PROJECT DETAILS:

- Removal and disposal of old soffit/facia material as needed
- Inspection of wood

PROJECT NOTES:
WOOD REPAIR: Yes
STANDARD SOFFIT: Yes
CONTINUOUS HIDDEN VENT SOFFIT: No
CUT IN SOFFIT FOR MAXIMUM AIR INTAKE: Yes if Necessary

WARRANTY:

- 20 Year Coil Warranty
- Limited Lifetime Workmanship Warranty by WeatherPro Exteriors

*Includes: Taxes, Clean-Up and Disposal

Price

\$7,354.00

Gutters Section

LOCATION: House & Garage

COLOR: White GUTTER SIZE: 5" DOWNSPOUT SIZE: 3"x4" GAUGE: 032

PROJECT DETAILS:

- Remove and dispose of current gutter system
- Furnish and Install new seamless gutters system with hand mitered corners with thick aluminum to handle wind, rain and snow
- Hidden hanger system
- New apron or flashing as needed
- Pitch for correct drainage / Direct drainage from house

PROJECT NOTES:

WARRANTY:

- 20 Year Gutter Coil Warranty
- WeatherPro Exteriors Lifetime Workmanship Warranty

Price

\$6,604.00

Roofing - flat Section

Furnish and Install Mule-Hide 60 MIL EPDM Rubber Roof.

- Remove up to (1) existing layers of "low slope" roof system down to the structural wood decking
- Inspect and re-nail any loose wood. If bad or rotten wood is discovered, up tp (2) sheets of OSB will be replaced (Additional charge for repair/replacement)

- Includes 2 Squares of Decking to to holes in current flat roof
- Install fiberboard membrane over decking
- Install NEW pipe boots/flashing
- Install NEW chimney flashing
- Install NEW 60 MIL EPDM Roof and fold over edges into gutter system and secure with termination bars and seal
- Seal seams per manufacture specs and code
- Inspection by Mule-Hide Manufacturer Rep for certification of warranty

CLEANUP:

- 3x magnet sweep throughout the yard.
- Remove and clean up of all job related debris and will be disposed of properly.

WARRANTY:

- Mule-Hide 20 Year Premium Limited Lifetime Warranty
- *Covers: Labor and Material
- WeatherPro Exterior's Lifetime Workmanship Warranty
- Includes all labor, materials, taxes and permits.
- WeatherPro Exteriors is bonded, licensed and insured.
- We follow and maintain all OSHA guidelines and regulations during the production of the project.

Price

\$4,069.00

Sub Total	\$63,522.00
Discount: Cash/Check Discount 15% Off	(\$9,528.30)
Discount: Google Review	(\$5,716.98)
TOTAL	\$48,276.72



CONTRACT

2129 S. 55th St., West Allis, WI 53219 www.CallCreativeConstruction.com 414-397-4072

DC- 110900004 DCQ - 120900026 EDI # WI-20

August 18, 2021

Steve Reupert 1630 N. 60th St. Milwaukee, WI 53208 630-703-8443

Email: sreupert@gmail.com

For Work at: 1630 N. 60th St., Milwaukee, WI 53208

To repair the railing, flashing, other areas damaged by the storm, and a few other spots around the house as agreed between Bingo Emmons of Creative Construction of WI. Inc. and Steve Reupert, owner. This includes repairing the dining room ceiling affected by the leak. Repaired areas to be primed and painted to match existing as close as possible.

Since the building was built before 1978; all lead safe precautions will have to be taken when removing the damaged materials.

Total Amount Due: \$27,700.00

Down payment 1/2

\$13,850.00

Balance due upon completion

\$13,850.00

Contractor

Purchaser

Creative Construction of Wisconsin, Inc. agrees to supply all labor, equipment, and materials to complete the above work. When you contract with Creative Construction of Wisconsin Inc. you employ the latest in equipment, experienced personnel, and complete insurance coverage.

Any additional work will be billed Time and Material to be paid weekly as billed \$127.50 per hour plus materials.

Serving South Eastern Wisconsin for the past 5 Generations





















