


Approximate location of
step-crack tuckpointing



① MS East Elevation at Roof