

*Milwaukee Fire Department

Capital Improvement Committee Asset Overview 2011

*41 Structures

35 Fire Stations + 1 Leased

Repair Facilities

Primary Repair Building
Butler Building
Cold Storage Building



*41 Structures (CONTINUED)

Fire & EMS Training Facilities

Recruit Training Building (w/ Pump Testing Facility)

Fire Training Tower

Fire Education and Historical Museum

- *Average Age of Structures 57 years
- *Oldest Structure Engine 1 140 years
- *Newest Structure Engine 35 14 years

*Age Groupings

0-25 years old - 4 Structures

26-50 years old - 18 Structures

51-75 years old - 8 Structures

76-100 years old - 5 Structures

+100 years old - 6 Structures

- *Basemented Apparatus Floors
 - 15 Total Stations impacted
 - 4 Minor Aesthetic Issues
 - 7 Require More Intensive Eval
 - 1 Shored Up, Needs Replacement



*Fixed Auxiliary Generators
22 Placed and Working
2 Pending in 2012

- *Fueling Sites
 - 21 Total Fill Sites
 - 18 Diesel
 - 6 Unleaded
 - 2 Dual

All meet Comm 10 Standards as of 2011

16 placed at Stations w/ Aux. Generators



*Energy Use Reduction Initiatives

Fire Station Energy Audits

-Working w/ OES (7 Stations)

Solar Hot Water Heaters

- -4 Installed
- -3 Underway or slated for 2012
- -4 in RFP stage



*Facility Inventory - CIP Integration
Major Capital 20 YEAR Replacement Schedule
Paperless Integration for Facility Tracking

*Energy Reduction Team
Active Sustainability Improvements
Intensive Energy Reduction Audits

*Replacement Study
Collective asset replacement study ongoing



20 Year Capital Budget Plan

Legend:

Shop Recruit Train

FI = Floor Replace/Inspection

BI = Boiler Replace/Inspection

RI = Roof Replace/Inspection

RI = Roof Replace/Inspection EU = Electric Upgrade/Inspection HVAC = HVAC Replace/Inspection PT = Paint/Inspection

A/C = Air Conditioner Replace/Inspection
OHD = Overhead Door Replace/Inspection

WD = Window Replace/Inspection

APF = Apparatus Floor Study/Inspection/Replace

WH = Hot Water Heater Replace/Inspection

FDI = Foundation Inspection
FL = Floor Replace/Inspection

MD = Mold

TP = Tuck Piont/Inspection APF = Apparatus Floor Study/Inspection/Replace TP = Tuck Piont/Inspection DI = Door Replace/Inspection											
House	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
Eng 1	FI, A/C	and the same of th									
Eng 2& Admin	FI, A/C, WD										
Eng 3				RI							
Eng 4	TP	HVAC					RI				
Eng 5		EU									
Eng 6	APF										
Eng 7	PT	EU									
Eng 8	EU	WH	BI		1		RI				
Eng 9	FDI, RI										
Eng 10	RI	EU									
Eng 11	RI										
Eng 12										RI	
Eng 13		RI									
Eng 14			RI		RI						
Eng 16		1	RI			<u> </u>				-	
Eng 17	FL, A/C	EU	1								
Eng 18	12,770	RI					 				
Eng 21	DI	WH	PT, WD, DI	1	EU			•		RI	
Eng 22	RI, PT	WD, DI	EU EU	-	100					1111	
Eng 23	NI, FI	VVD, DI	RI			1 1 1 1 1 1 1 1 1				RI	
Eng 25		EU	INI .	<u> </u>		RI "	-			IXI	
Eng 25		150		-		N	<u> </u>				RI
Eng 25		EU		 	RI						INI .
Eng 26 Eng 27		RI	· ·	-	INI .	 					
	DI	KI	EU		<u> </u>	1	-				
Eng 28	RI		IEU .			RI				-	·
Eng 29	NA#1 DI	BI		LINAC	RI	PT	1				
Eng 30	WH, RI	FDI		HVAC WH	KI	PI					
Eng 31	RI	FDI -mes in.		WH		(488/241)				- a wassinto	
Eng 32	KI	-									
Eng 33	51 1/6 51			<u> </u>						-	
Eng 34	FL, A/C, RI	OHD	EU		-						
Eng 35				RI	ļ					-	
Eng 36				RI	<u> </u>		-				
Eng 37				-	RI		-				
Eng 38	RI										
Eng 39						RI	1	1			
Burn Tower	2524		,				1				



Engine 1

Address 784 N Broadway

Year Built 1872 Building Area 14,095 SF

Lot Area

Roof Area 7,048 SF

Floors 2 Foundation Slab

Exterior Wall

Surface Brick Frame Steel

Windows Double hung, aluminum, thermo

Floors Vinyl, wood & Tile

Electrical Main Switch 400 Amp 3 Phase

S & D Voltage 120/208


Heating Boiler, Steam

Cooling Window Air system

Ventalation Roof/Wall Exhaust Fans

Roof Flat Wood Decking & Ex-

Flat, Wood Decking & Frame, Ballasted



Boiler Water Heater A/C Unit HVAC System	Year Installed 2002 N/A	Quantity 2 1	Condition Good Good	Model/Make 5007N/Burnham BT80/AO Smith Window Units	<u>Serial #</u> 64468945/64468942 MA97 - 0620068 - 230	Life Of Component
Concrete Landscape Foundation Exterior Wall	.VA	The see Authors	Good N/A Good Good			The second state of the second
Roof Interior Walls/Paint Flooring Generator Windows Door(s) Overhead Door(s)	2010	1	Excellent Fair Fair N/A Good Good Good	EPDM/Membrane	Garland	30 yr Warranty



Insurance Value: \$2,179,892