

Certificate of Appropriateness

Milwaukee Historic Preservation Commission 200 E. Wells Street, Room B-4 Milwaukee, W1 53202 Phone 414-286-5712 fax 414-286-3004

Property

3014 W. MCKINLEY

Cold Spring Park Historic District

Description of work Remove existing front metal doors; install restored double leaf wood doors at front entrance.

Restore wood side doors on west elevation. Install new wood storms over side doors.

Date issued

1/9/2012

PTS 1D 13197 COA, install new wood doors

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a Certificate of Appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

All work will be done according to attached drawings, photos and specifications supplied by the contactor in the application. All doors will be finished to protect them from the weather.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Paul Jakubovich of the Historic Preservation Department as follows: Phone: (414) 286-5712 Fax: (414) 286-3004 E-mail: pjakub@milwaukee.gov.


If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.mkedcd.org/build, or call-(414) 286-8210

Paul Jakubovieh


Office of the Common Counci/lCity Clerk

Department of Historic Preservation

Copies to: Development Center, Ald. Robert Bauman, Contractor Juanita Ellias, Inspector Joel Walloch (286-8160)



Existing metal front door (not original) to be removed; restored, all wood front doors will be installed in its place





One of two doors restored including new astragal

8. Restoration in Process; Fig. 9. Completed Doors Ready for Installation






Fig. 12 Replacement Stile


Fig. 12 Replacement Stile, Sill, Astragal, showing placement in Sill.




Details of restoration and new millwork for sill and astragal

Figs. 14-16 Side Doors, Details showing damage from weather exposure.







Details of doors showing deterioration



Grown Doors Soly MY Makinley (2) Bock entra. M. Iwonker, WI Laminated Glan . 4 Earsed parcel

Drawing of new all wood storm door for west elevation

Species: White Northern Pine (3dad) 11/4"
Full Mortice of Fenon Joinery.