

## Milwaukee Historic Preservation Commission Staff Report

LIVING WITH HISTORY

HPC meeting date: 4/10/2017 Ald. Nik Kovac District: 3 Staff reviewer: Tim Askin PTS #114226 CCF #161593

Property	2581 N. DOWNER AV., Downer Avenue Historic District	
Owner/Applicant	CSFB 2006-C4 N DOWNER AVE LLC-III ASSET MGMT LLC ATTN MARK CONTRERAS 5221 N O'CONNOR BLVD STE 600 IRVING TX 75039 (Liz Collins, local representative)	Nova Beschta Salon Nova 1437 E Brady St Milwaukee, WI 53202
Proposal	Replace existing single-thickness silicone-seamed storefront with double-paned system with thermally broken aluminum frame.	
Staff comments	The storefront is part of the original Downer original storefronts in addition to the theater the storefronts. One is the subject storefront entry at the intersection of Belleview now oc Belleview. All three of the original storefronts construction with this one and the Belleview elements. This one, however, has had very continuously since 1915, although in the cur consist of two sheets that are butt-jointed wi The proposed system is the TubeLite E1400 glass at center. In no other instance has this changes in building code, it may be the only Staff reluctantly recommends approval. An a for both strength and energy efficiency was and research. However, as this is an unusual storefronts have been successful at meeting appropriate systems, staff would request that precedent.	entrance, along with apartments above t facing Downer, a second is the corner coupied as Pizza Man, and the third faces s have been heavily altered since storefront retaining some limited original large, effectively seamless storefronts rrent installation both large openings th silicone. 20, which has a 4.5" thickness with 1" s been found approvable, however, with option for a glazing area this large. alternative system that could meet code not found in two months of negotiations ally large storefront and smaller g code with different, more historically
Recommendation	Recommend HPC Approval with conditions	
Conditions	Approve with condition of not setting preced both windload capacity and energy efficienc exceed U =.45 per MCO 200-26-1-e-1"; cf. $\epsilon$ calculations by architect in this file).	y ("thermal performance values not to
	Bronze/copper trim at bottom of storefront windows must be retained and reproduced as needed, as it matches that on the Belleview storefront and therefore appears to be the only bulkhead on the building intact to the date of construction. Works with staff to select a standard manufacturer's finish that will best hide the framing or match those used by the other two storefronts within the building.	
Previous HPC action	Applicant has previously been approved by reflect a change in tenancy and occupancy to composed of minor repairs and changes in s	type. They have been primarily
Previous Council action		