



East Side b2

East view of turret



East Side . b1

East View of turret



b3
turret trim





b4
turret trim



East Side C1
Consumption Perch
Feeding



East Side
CZ
Construction Rock
rooting

new base beneath turret
copper replacing fin and restored sailing ID



New edge beneath turret window sills d2
cepper replacing tin and restored trailing



E1
East view turret
restoration complete



E2
East view turret
restoration complete.

