

Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

LIVING WITH HISTORY

Property 729 W. HISTORIC MITCHELL ST. Mitchell Street HD

Description of work Masonry repairs per conditions below and project narrative on following page.

Date issued 8/10/2018 PTS ID 114601 COA: masonry repairs

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

New mortar must match the original mortar in terms of color, texture, grain size, joint width, and joint finish/profile. The compressive strength of the repointing mortar shall be equal or less than the compressive strength of the original mortar and surrounding brick or stone. The replacement mortar shall contain approximately the same ingredient proportions of the original mortar. Mortar that is too hard is subject to premature failure and could damage the masonry. See the city's book *Good for Business*, Masonry Chapters, for more information. In most cases, this means a lime mortar with natural hydraulic cement rather than Portland cement. No joint of a width less than 3/8" may be cleaned of damaged/decomposed mortar with power disc grinders. No over-cutting of the joints is permitted. Remove decomposed mortar back into the wall 2.5 times the height of the joint before repointing. New brick must match as closely as possible the color texture, size, and finish of the original brick. A sample panel of brick and mortar must be reviewed and approved by HPC staff prior to general installation of the material.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: hpc@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements call (414) 286-8210.

City of Milwaukee Historic Preservation Staff

ma asons

Copies to: Development Center, Ald. Jose Perez, Contractor

- PIECE BUFF COCOR INDIVIDE LIMESTONE, PIN IN PLACE (STAINLESS STEEL), MORTAR AND APPLY SEALANT LO PERIMETER
- 2. PIN IN PLACE OTHER FRACTURED STORE POXY.
 PIECES LUB LOTTACH WITH MORTAR OR EPOXY.
 EPOXY SELL THE PERIMETER BUT NOT AT BASE TO LUCUM MOISTURE TO ESCAPE.
- 3. THE BOTTOM FLANCE OF AD I BEAM
 SOPPORTING THE BRICK AND STONE AT THE
 HEAD LEVEL OF THE SECOND STORY MITCHEN
 STREET FACABE IS COMPLETELY RUSTED AWAY.
 REMOVE THE RUSTED STEEL AND INSTAUL NEW
 STEEL ANGLES AS SHOWN ON THE PLAN EVERY
 EFFORT NILL BE MADE TO MINIMIZE BRICK
 OR STONE REMOVAL. ANY REMOVED PIECES
 WILL BE PE-INSTALLED, ANY PIECES BEYOND
 PEPAIR WILL BE REPLACED WITH NEW PIECES
 TO MATCH EXISTING TIE STONE & BRICK TO STRUCTURE.
- 4. STRLICHTEN CENTER PICKSTOCS LS MUCH LS POSSIBLE.
- 5. TUCK POINT LU OPEN MORTUR JOINTS.

Project description/scope.

10 pages of annotated photos and diagrams follow.





PILASTER @ LEFT OF CENTER-NORTH FACADE


REPLIE BRICKS, MORTLE, STONE, SUPPORT & TIE BLOCK TO STRUCTURE




PILLSTER @ RIGHT OF CENTER - NORTH FLOCKDE

REPAIR BRICKS, MORTLE, STONE, SUPPORT & TIE BLCK TO STRUCTURE










* PIN IN PLACE MITH STAINLESS
STEEL ROPS & MORTAR


EXISTING PEDIMENT

INSERT REPLACEMENT
PEDIMENT TO MATCH EXISTING.
(INDIANA LIMESTONE-BUFF COLOR)*



TOP WEST @ NW

TOP HORTH @ NW



BLODGETT ENGINEERING LLC

STRUCTURAL CONSULTING ENGINEERS


W169 N10815 Redwood Lane Germantown, WI 53022 blodgetteng@wi.rr.com Tel/Fax: 262.293.9923 JOB 737 W. MITCHELL ST.

SHEET NO._____OF

CALCULATED BY DATE

LINTEL REPAIR:

* STEEL PLATE AND BOTTOM FLANGES ARC RUSTED SEVERELY ABOVE WINDOWS.



EXISTING CONSITIONS

STEEL BEAM (ONLY BETWEEN COLUMNS)

* INSTALL 6×6×1/4" (MIN) ANGLE
PENDING MORE ACCURATE MEASUREMENT
OF HOLIZONTAL MOVEMENT
(UP TO L8×8×3/8" MAY DE NEEDED)

RESET/REPOINT BRICK-

L6×6×1/4"

PROPOSED DETAIL

BOLTED TO EXISTING

BOTTOM FLANGE ABOVE COLUMNS TO REMAIN

REMOVE STEEL AT

CORRODO ALLAS

LI3.57 TALL BEAM A

BLODGETT ENGINEERING LLC

STRUCTURAL CONSULTING ENGINEERS

W169 N10815 Redwood Lane Germantown, WI 53022 blodgetteng@wi.rr.com Tel/Fax: 262.293.9923 