



LIVING WITH HISTORY

Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

 Description of work Null. Numbers correspond to items in ORD-20-03121 SOUTH. Porch support structure has failed. Restore the porch to a safe condition. (Meet strur requirements of building inspector. No new structural material shall be visible from the yard sidewalk) EAST: Replace mortar missing from exterior wall. Repair masonry per conditions below SOUTH: Replace defective handrail on porch steps per standard attached design EAST: Install new trim and/or new wood storm window as required by inspector, per materia requirements below. New pieces shall be exact replicas of the molding pattern of the origina Side SOUTH: Replace siding to match, per material requirements below. South Side WEST & EAST: Install new half-round metal gutters, current gutters are too shallow. Alum encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. EAST & SE: Replace defective fascia boards. (East and Southeast areas) EAST: Repair or replace defective storm windows ALL: Paint previously painted surfaces in a workmanlike manner. 	
 requirements of building inspector. No new structural material shall be visible from the yard sidewalk) 3. EAST: Replace mortar missing from exterior wall. Repair masonry per conditions below 4. SOUTH: Replace defective handrail on porch steps per standard attached design 5. EAST: Install new trim and/or new wood storm window as required by inspector, per materi requirements below. New pieces shall be exact replicas of the molding pattern of the origina Side 6. SOUTH: Replace siding to match, per material requirements below. South Side 7. WEST & EAST: Install new half-round metal gutters, current gutters are too shallow. Alun encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st 8. EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. 9. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows 	
 SOUTH: Replace defective handrail on porch steps per standard attached design EAST: Install new trim and/or new wood storm window as required by inspector, per materi requirements below. New pieces shall be exact replicas of the molding pattern of the origina Side SOUTH: Replace siding to match, per material requirements below. South Side WEST & EAST: Install new <u>half-round</u> metal gutters, current gutters are too shallow. Alun encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows 	
 5. EAST: Install new trim and/or new wood storm window as required by inspector, per materia requirements below. New pieces shall be exact replicas of the molding pattern of the origina Side 6. SOUTH: Replace siding to match, per material requirements below. South Side 7. WEST & EAST: Install new half-round metal gutters, current gutters are too shallow. Alun encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st 8. EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. 9. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows 	
 requirements below. New pieces shall be exact replicas of the molding pattern of the original Side 6. SOUTH: Replace siding to match, per material requirements below. South Side 7. WEST & EAST: Install new half-round metal gutters, current gutters are too shallow. Alune encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st 8. EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. 9. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows 	
 WEST & EAST: Install new <u>half-round</u> metal gutters, current gutters are too shallow. Alun encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. EAST & SE: Replace defective fascia boards. (East and Southeast areas) EAST: Repair or replace defective storm windows 	
 encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is at northwest corner to protect rafter tails from water damage. Do not match existing gutter st 8. EAST: Install standard aluminum downspouts where necessary. Do not cover windows, or c building siding or trim. 9. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows 	
9. EAST & SE: Replace defective fascia boards. (East and Southeast areas) 10. EAST: Repair or replace defective storm windows	required yle.
10. EAST: Repair or replace defective storm windows	
11. ALL: Paint previously painted surfaces in a workmanlike manner.	
12. ALL; Protect all wood trim with paint or other approved coating applied in a workmanlike i	nanner.
Date issued5/26/2020PTS ID114932 COA: Required Repairs	

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. **The following conditions apply to this certificate of appropriateness:**

Wood

All finish wood must be smooth and free of knots and must be painted or treated with an opaque stain upon completion. Note: when new, bare wood is left exposed to the exterior elements for a period of only a week or two, the life the of the paint job subsequently applied to it will be decreased. The use of a naturally decay-resistant wood species for exterior finish applications is required for porch areas. Using western white pine or Ponderosa pine is "at your own risk" because this wood has no natural decay resistance and can deteriorate in some exterior settings in just a few years.

Paint

Use any standard latex, acrylic, oil, or milk paint.

Masonry

- New mortar must match the original mortar in terms of color, texture, grain size, joint width, and joint finish/profile. The compressive strength of the repointing mortar shall be equal or less than the compressive strength of the original mortar and surrounding brick or stone. The replacement mortar shall contain approximately the same ingredient proportions of the original mortar. Mortar that is too hard is subject to premature failure and could damage the masonry. See the city's books As Good As New or Good for Business, Masonry Chapters, for more information. In most cases, this means a lime mortar with natural hydraulic cement rather than Portland cement. No joint of a width less than 3/8" may be cleaned of damaged/decomposed mortar with power disc grinders. No over-cutting of the joints is permitted. Remove decomposed mortar back into the wall 2.5 times the height of the joint before repointing.
- New brick must match as closely as possible the color texture, size, and finish of the original brick.
- A sample panel of brick and mortar must be reviewed and approved by HPC staff prior to general installation of the material.
- UNDER NO CIRCUMSTANCES SHALL UNPAINTED MASONRY BE PAINTED, BE GIVEN A WATERPROOFING TREATMENT, OR CLEANED BY ABRASIVE MEANS; THIS STATEMENT SUPERSEDES ANY OTHER WORDING IN THIS DOCUMENT INDICATING THE CONTRARY.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Dean Doerrfeld of the Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: Dean.Doerrfeld@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, <u>www.milwaukee.gov/build</u>, or call (414) 286-8210.

-> /m

City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Robert Bauman, Contractor, Inspector D. Belasco (286-3558)



ITEMS 2, 3, 4, & 6. Front Porch, photo of current conditions





ITEMS 5 & 10. New storm windows must have a wood frame. Match either style shown in the images on this page.

ITEMS 6 & 8. Illustrated here, but no staff notes. See conditions section on wood requirements.



ITEMS 6, 7, 8, & 9. Install new half-round metal gutters, current gutters are too shallow. Aluminum is encouraged. Gutter mounts/straps must be installed UNDER roofing shingles. New fascia is required at northwest corner to protect rafter tails from water damage. Do not match existing gutter style.