



Image 29 - Date: 01-16-2014 - Damaged Northwest Corner and Missing Trim Under Existing Storefront



Image 30 - Date: 01-16-2014 - North Elevation (Damaged and Missing Trim Under Existing Storefront)



*Image 31 - Date: 01-16-2014 – North Elevation (Existing Metal Pilaster with Capital)*



*Image 32 - Date: 01-16-2014 – North Elevation (Wood Pilaster without Capital)*



Image 33 - Date: 01-16-2014 – North Elevation (Storefront Base)



Image 34 - Date: 01-16-2014 – North Elevation (Storefront Missing Aluminum Trim)



Image 35 - Date: 01-16-2014 – North Elevation (Storefront Missing Aluminum Trim)



Image 36 - Date: 01-16-2014 – East Elevation (Storefront & Wood Column)



Image 37 - Date: 01-16-2014 – East Elevation (Wood Column)




Image 38 - Date: 01-16-2014 – East Elevation (Looking South)




*Image 41 - Date: 01-16-2014 – East Elevation (Windows & Doors Boarded Up)*



*Image 42 - Date: 01-16-2014 – South Elevation (Windows Boarded Up)*



*Image 43 - Date: 01-16-2014 – South Elevation (Windows Boarded Up)*



*Image 44 - Date: 03-26-2014 – South Elevation (Existing Stairs)*

