


I, Lathonda Prather, would like to apply for an appeal on the decision made in regards to the accident involving my Jeep and a city truck.

Lathonda Prather

MILWAUKEE

2019 SEP 11 A 9:38
MILWAUKEE City Clerk
200 East Wells Street Rm. 205
MILWAUKEE, WI 53202

RECEIVED
OFFICE OF CITY ATTORNEY
SEP 13 2019
4:30 A.M./P.M.



53202-557099



7/31/19

On May 3, 2019 around 2 p.m. I
was side swipe By a city garbage
truck Between 10th - 11th Clark in
Milwaukee WI
City truck Plate # 78817
My Plate # AFB - 7095

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 2 - 2019

3:20 A.M./P.M.

CITY CLERK'S OFFICE
JUL 31 PM 12:11
OFF OF RECORD

LaRhonda Prather
1332 W. Ring St.
Milwaukee, WI 53206
PratherLaRhonda@yahoo.com
#(262)613-4544

LaRhonda Prather

Date: 7/23/2019 12:31 PM
 Estimate ID: 111
 Estimate Version: 0
 Preliminary
 Profile ID: * Mitchell

ADAMS AUTO BODY

2719 N. 5th Street, Milwaukee, WI 53212
 (414) 562-6161
 Fax: (414) 562-2123
 Email: adamsautobody@sbcglobal.net

Damaged Assessed By: Cleo Adams
 Classification: Audit

RECEIVED
 OFFICE OF CITY ATTORNEY

Deductible: UNKNOWN

Owner: Larhonda Prather
 Address: 1332 W. Ring. Street, Milwaukee, WI 53206
 Telephone: Home Phone: (262) 613-4544

AUG 2 - 2019

3:20 A.M. (P.M.)

CITY CLERK'S OFFICE
 2019 JUL 31 PM 12:11
 OFFICE OF THE CITY CLERK

Mitchell Service: 912530

Description: 2005 Jeep Liberty Limited
 Body Style: 4D Ut
 VIN: 1J4GL58K75W561898
 OEM/ALT: O

Drive Train: 3.7L Inj 6 Cyl 4WD

Search Code: None

Options: PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
 REAR WINDOW DEFOGGER, AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL
 TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG, LUGGAGE RACK, FOG LIGHTS
 ALUM/ALLOY WHEELS, TIRE INFLATION/PRESSURE MONITOR, ANTI-THEFT SYSTEM
 LEATHER STEERING WHEEL, CD PLAYER, POWER ADJUSTABLE EXTERIOR MIRROR, 4WD OR AWD
 PRIVACY GLASS, FIRST ROW BUCKET SEAT, CLOTH SEAT, 4 WHEEL DRIVE
 KEYLESS ENTRY SYSTEM, REAR BENCH SEAT

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Door</u>							
1	200739	REF	BLEND	L Rear Door Outside			C 0.9
<u>Side Body</u>							
2	200902	BDY	REPAIR	L Quarter Outer Panel	Existing		4.5* #
3		REF	REFINISH	L Quarter Panel Outside			C 2.0
4	204091	BDY	REMOVE/REPLACE	L Rear Quarter Wheel Opening Flare	5JH69TZZAE	157.00	INC
5		REF	REFINISH	L Rear Quarter Wheel Opening Flare			C 0.8
<u>Rear Bumper</u>							
6		BDY	OVERHAUL	Rear Bumper Assy			2.8 #
7	203612	BDY	REMOVE/REPLACE	Rear Bumper Cover	** QUAL REPL PART	120.00	* INC #
8		REF	REFINISH	Rear Bumper Cover			C 2.0
<u>Additional Costs & Materials</u>							
9	936008		ADD'L COST	Paint/Materials		216.60	*
10	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
<u>Additional Operations</u>							
11		REF	ADD'L OPR	Clear Coat			1.6

ESTIMATE RECALL NUMBER: 06/03/2019 14:48:44 111
 Mitchell Data Version: OEM: MAY_19_V

Software Version: 7.1.237

Copyright (C) 1994 - 2019 Mitchell International
 All Rights Reserved

Page 1 of 2

Private Part
 3315

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	7.3	60.00	0.00	0.00	438.00 T	Taxable Parts	277.00
Refinish	7.3	60.00	0.00	0.00	438.00 T	Sales Tax @ 5.600%	15.51
					Taxable Labor	Total Replacement Parts Amount	292.51
			@ 5.600 %		876.00		
					Labor Tax		49.06
Labor Summary	14.6				925.06		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					219.60	Customer Responsibility	0.00
Sales Tax			@ 5.600%		12.30		
Total Additional Costs					231.90		
					I. Total Labor:		925.06
					II. Total Replacement Parts:		292.51
					III. Total Additional Costs:		231.90
					Gross Total:		1,449.47
					IV. Total Adjustments:		0.00
					Net Total:		1,449.47

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.