



Missing Storms to be replaced with wood storms to match

Deteriorated storm frames to be replaced/ rebuilt.

Drip edges to be replaced/ repaired.

Missing basement windows to be replaced with singular panes of glass or glass block.