



1041



1037



1035



G 16
14 15
F

R R







1031 E Ogden Ave Rear Porch

Handrails, bottom rails & newel post sleeves were replaced in 2025, but it was determined by the carpenter, once he took things apart, that further work was necessary on the steps themselves. The handrails were put back on for safety before winter weather came, but the remainder of the step work will be completed in 2026.



1033 E Ogden Ave Rear Porch

Handrails, bottom rails & newel post sleeves were replaced in 2025, but it was determined by the carpenter, once he took things apart, that further work was necessary on the steps themselves. The handrails were put back on for safety before winter weather came, but the remainder of the step work will be completed in 2026.