

To Whom It May Concern:

I am writing this letter in regards to a denied claim that originally was issued on August 22, 2016. I would like to appeal the decision and request a hearing to discuss this case. Thank you

Disciple Abb Hall  
P.O. Box 12665  
Milwaukee, WI 53212  
414-254-9354

CITY OF MILWAUKEE  
2017 JAN 27 A 11:20  
CITY CLERK'S OFFICE

My name Disciple: AB Hall  
Mailing address PO Box 12665,  
Milwaukee, Wisconsin 53212

August 27, 2016

RECEIVED

AUG 30 2016

OFFICE OF  
CITY ATTORNEY

On August, 22, 2016

I was Headed eastbound on North Avenue the 4601 block

About 3:30 PM I hit a deep hole.

And my Front end of my truck went out of wreck.

On August 24 when I had to Drive my truck to Waukesha Wisconsin on the highway it was shaking like crazy so I had to get off the highway and take the street to my destination.

It's a must I have to be there in Waukesha Wisconsin every Monday Wednesday and Friday I must be there no exceptions, so I took my truck in to get it looked at August 25 and my idle arm and ball joint need to be replaced the mechanic told me all would have to be repaired before this truck would be safe to drive on the streets

I can't pay for these types of repairs. Because what the streets have done to my truck, I have hit so many Holes but this particular Deep hole cause a lot of damage.

I have the truck for my personal needs and to run errands to make ends meet I receive enough money to barely pay my bills and to survive legally.

Sincerely

*Disciple: AB Hall*



www.AndrewAutomotive.com

ANDREW Toyota Scion
1620 W. Silver Spring Drive
Glendale, WI 53209
Tel #: 414.228.1450



CELL: 414-254-9354

Table with columns: CUST NO., TAX EXEMPT NUMBER, CUST. P. O. NO., SHIP VIA, PAY, SOLD BY, INVOICE DATE, INVOICE NO. Values: 148140, 414-254-9354, 899804, CASH, 1998, 08/25/16, PQ9727 TOR

BILL TO

DISCIPLE HALL
PO BOX 12665
MILWAUKEE, WI 53212-0665

SHIP TO

Main parts invoice table with columns: SHIP QTY, B.O. QTY, PART NUMBER/DESCRIPTION, ESN, LIST, NET, AMOUNT. Includes items like JOINT-ASSY, ROD ASSY, SHACKLE KIT, BOLT, PIN KIT, SPRING ASSY.

DISCLAIMER OF WARRANTIES
Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose...

No Refunds Without This Invoice.
No Returns After 5 Days.
15% Handling Charge On All Returned Parts.
No Returns on Special Order Items or Electrical Parts.

SUBTOTAL 2539.41
RESTOCK CHARGE 0.00
TAX 142.21
FREIGHT 0.00
PAY THIS AMOUNT 2681.62

\*\* PRICE QUOTE \*\*
16:38:54 PAGE 1 OF 1
NET505

CUSTOMER COPY. DIRECT LINE: (414) 228-1192 or 1-800-735-8495 / DIRECT FAX: (414) 228-6230

Customer Copy

PARTS INVOICE

RECEIVED

AUG 30 2016

OFFICE OF CITY ATTORNEY

Handwritten notes: - Left upper ball joint is loose, Right outer tie rod is loose, unable to tell if any things else is loose, NOT SAFE TO DRIVE, Rec. start w/ replacing left upper ball joint and right outer tie rod end, L/R tie rods on inner side were too bad to, - Right leaf spring broken, Rec. replace both rear leaf springs

Table with columns: SERVICE ADVISOR, CALL PARTS DEPT. TIME, RETURN CALL TIME, PARTS SPECIFIER, ATTACH LABOR FLAGS

# WJ Kuhn Automotive & Collision Center

Date: 08/25/2016 14:35:15

Customer: Disciple Hall  
PO Box 12665  
Milwaukee Wi 53212

Home: 414-254-9354

Mobile:

Work:

Email:

**RECEIVED****AUG 30 2016**OFFICE OF  
CITY ATTORNEY

For: 1996 Toyota T100 3.4L Eng Base

TYPE	DESCRIPTION	PART #	QTY	PRICE	RATE	HOURS	LINE TOTAL
Labor	BALL JOINT - Remove & Replace [DOES NOT include alignment.] 4WD One Side,Upper (2.9)	-	-	-	\$85.00	5.8	\$493.00
Labor	BALL JOINT - Remove & Replace [DOES NOT include alignment.] Lower,One Side (2.4)	-	-	-	\$85.00	4.8	\$408.00
Parts	BALL JOINT 4WD Lower,Left	43340-39245	1.0	\$78.37	-	-	\$78.37
Parts	BALL JOINT 4WD Lower,Right	43330-39835	1.0	\$78.37	-	-	\$78.37
Parts	BALL JOINT 4WD Upper,Left	43360-39085	1.0	\$78.37	-	-	\$78.37
Parts	BALL JOINT 4WD Upper,Right	43350-39085	1.0	\$78.37	-	-	\$78.37
Parts	IDLER ARM 4WD	45490-39375	1.0	\$115.39	-	-	\$115.39
Parts	PITMAN ARM - [For Land Cruiser Model FJ40, Excludes Wagon, Refer to Drag Link End.] 4WD	45401-35240	1.0	\$160.93	-	-	\$160.93
Labor	PITMAN ARM - Remove & Replace 4WD	-	-	-	\$85.00	0.9	\$76.50
Labor	IDLER ARM - Remove & Replace [DOES NOT include alignment.] 4WD	-	-	-	\$85.00	0.7	\$59.50
Labor	TIE ROD &/OR END - Remove & Replace [Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed. NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some models. If removal of the Rack and Pinion Gear is necessary, use Steering Gear (Complete) - R&R plus	-	-	-	\$85.00	1.8	\$153.00

	combinations.] 4WD,Recirculating Ball Type Gears All Four						
Parts	TIE ROD END 4WD Outer,Tie Rod Ends,Each	45046- 39385	2.0	\$54.83	-	-	\$109.66
Parts	TIE ROD END 4WD Tie Rod Assembly,Each	45460- 39505	2.0	\$140.16	-	-	\$280.32
Parts	Alignment		1.0	\$79.99	-	-	\$79.99

Estimates are an approximation of charges to you, and they are based on the anticipated details of the work to be done. It is possible for unexpected complications to cause some deviation from the estimate. If additional parts or labor are required you will be contacted immediately.

Labor:	\$1,190.00
Parts:	\$1,059.77
Shop Supplies:	\$50.00
Hazardous Materials:	\$0.00
Labor Taxes:	\$69.44
Parts Taxes:	\$59.35
<b>TOTAL:</b>	<b>\$2,428.56</b>

Customer Signature: \_\_\_\_\_

**8511 South Howell Ave. Oak Creek, WI 53154 414-762-7900**  
**www.wjkuhn.com**  
**Be sure to visit us on Facebook**

**RECEIVED**  
**AUG 30 2016**  
 OFFICE OF  
 CITY ATTORNEY

CITY OF MILWAUKEE  
2016 AUG 29 AM 11:58  
CITY CLERK'S OFFICE

To City Hall

CLAIM