

This photo shows a portion of the flat roof that is need of repair. The old tar over tin roof has deteriorated, causing leaking in the home below.

This portion of roof and flashing will also be repaired, as the current flashing has come away from the brick exterior.



Ariel view of where repairs will be limited to.