



**Lonnie Schwab**  
Resident Vice President -- Milwaukee Branch

P.O. Box 327  
Brookfield, WI 53006-0327  
Phone 262.786.1800  
FAX 262.786.4767, Underwrtg, Audit, Mktg & Risk Impr  
FAX 262.786.3812, Claims, Accounting & Misc Dept  
www.emcinsurance.com

September 27, 2006

Milwaukee City Clerk  
via fax #: 1-414-286-8550

Re: Sherwood Temkin  
CI File #: 06-V-127  
Our File #: 337304—LL

To Whom It May Concern:

Please be advised that we wish to appeal the decision made on this case.

We do not feel our policyholder was more at fault than the officer involved. We would like to continue pursuing our claim against the City of Milwaukee.

Please advise our next step. Thank you.

Sincerely,

Lynn Lesko  
262-786-1809 Ext: 284



06-V-127

P.O. Box 327  
Brookfield, WI 53008-0327  
Phone 262.786.1800  
FAX 262.786.4767, Underwrtg, Audit, Mktg & Risk Impr  
FAX 262.786.3812, Claims, Accounting & Misc Dept  
www.emcinsurance.com

CITY OF MILWAUKEE  
RECEIVED

2006 AUG -2 PM 3:14

OFFICE OF  
CITY ATTORNEY

July 25, 2006

City of Milwaukee  
200 E. Wells St  
Milwaukee, WI 53202

RE: Claim Number: 337304--LL  
Our Insured: Sherwood Temkin  
Date of Loss: 5/29/06  
Amount of Damages: \$ 6268.16  
Your Driver: Christopher Conway

To Whom It May Concern:

Our records show that one of your officers was involved in an accident with our insured at 91<sup>st</sup> and Good Hope. The facts indicate that your driver was responsible for this accident.

Please accept this letter as notice of our subrogation rights. We are looking to you for reimbursement.

We have enclosed our supporting documents for your review.

Sincerely,

Lynn Lesko  
Claims Adjuster 1-800-236-1810 Ext 284  
EMC Insurance Companies



EMPLOYERS MUTUAL CASUALTY COMPANY  
MILWAUKEE BRANCH  
16455 W. BLUEMOND RD.  
BROOKFIELD, WI 53005  
(800)247-2128

\*\*\* ESTIMATE \*\*\*

06/05/2006 10:36 AM

**Owner:**

Owner: PORT SHELL MOLDING

**Control Information**

Claim #: 337304 Insured Policy #:  
Loss Date/Time: 05/28/2006 Loss Type: Collision  
Deductible: \$500.00  
Insured: PORT SHELL MOLDING  
Claim Rep: LYNN LESKO Work/Day: (262)786-1800x284  
Address:

**Inspection**

Inspection Date: 06/05/2006 10:00 AM Inspection Type: Independent  
Primary Impact: Front Secondary Impact:  
Appraiser Name: SCOTT BEEGHLEY Appraiser License #:  
Address: Work/Day: (800)247-2128x2252  
City State Zip: FAX: (800)688-5623  
Email: Scott.C.Beehley@EMCINS.com

**Repairer**

Repairer: Pinkey's Auto Body Contact:  
Address: 3859 N. Richards Work/Day: (414)962-3380  
City State Zip: Milwaukee, WI 53212 FAX: (414)962-0670  
License #: Regulation ID: 39-0985331

**Remarks**

Agreed price with: Pinkey @ Pinkey's Auto Body 6/5/06  
Possible hidden damage, advise after teardown  
This is not an authorization to repair, authorization must come from owner.  
No supplements will be accepted without prior approval.

**Vehicle**

2000 Subaru Outback STD 4 DR Wagon  
4cyl Gasoline 2.5 DOHC  
4 Speed Automatic

Lic Expire: VIN: 4S3BH6750Y7664470  
Prod Date: Mileage: 47,461  
Veh Insp#: Mileage Type: Actual  
Condition: Code: F2245A

**Options**

AM/FM Stereo Tape Air Conditioning Aluminum/Alloy Wheels  
Anti-lock Brakes Bodyside Cladding Cruise Control

06/05/2006 10:36 AM

Page 1 of 4

Claim #: 337304

Dual Airbags	Fog Lights	Ground Effects Package
Heavy Duty Suspension	Intermittent Wipers	Keyless Entry System
Overhead Console	Power Brakes	Power Door Locks
Power Drivers Seat	Power Mirrors	Power Steering
Power Windows	Rear Window Defroster	Rear Window Wiper/Washer
Roof/Luggage Rack	Split Folding Rear Seat	Tachometer
Tilt Steering Wheel	Tinted Glass	Tutone Paint
Velour/Cloth Seats		

## Damages

Line	Op	Guide	MC	Description	MFR. Part No.	Price	ADJ%	B%	Hours	R
1	EC	5	46	Bumper,Front >> Keystone 414-463-1019	QUALITY REPL. PART	\$227.00*			1.4	SM
2	UM	6	46	Cover,Front Bumper >> Keystone 414-463-1019	Replace Reman/Rebuilt	\$191.00*			1.0	SM
3	L		6	Cover,Front Bumper	Refinish				2.6	RF
4	E	1055		Clip,Frt Bumper	MULTI-PART	\$8.40			INC	SM
5	E		9	Absorber,Front Bumper	57705AE02A	\$39.95			INC	SM
6	E		12	Brkt,Front Bumper Mtg LT	57707AE22A	\$15.85			INC	SM
7	E		13	Brkt,Front Bumper Mtg RT	57707AE21A	\$16.27			INC	SM
8	E		18	Brkt,Front Bumper Mtg RT	57707AE17A	\$11.25			INC	SM
9	E		32	Brkt,Front Bumper Mtg RT	57765AE00A	\$3.57			INC	SM
10	E		28	Grille Assembly	91121AE04A	\$149.95			INC	SM
11	E		22	Emblem,Grille	93013AE030	\$37.42			0.2	SM
12	E		41 46	Headlamp Assy,Halogen LT	84001AE15A	\$299.95			INC	SM
13	E		42 46	Headlamp Assy,Halogen R	84001AE14A	\$299.95			0.2	SM
14	N		973	Headlamps Aim	Additional Labor				0.4	SM
15	E		83	Panel,Hood	57220AE00B	\$369.95			1.5	SM
16	L		83	Panel,Hood	Refinish				3.9	RF
17	E		89	Supt,Hood Lock Vert	53040AE00A	\$30.73			INC	SM
18	E		197 01	Label,Hood	14808AF350	\$17.45			0.1	SM
19	I		75 07	Panel,Radiator Side LT	Repair				1.5*	SM
20	L		75	Panel,Radiator Side LT	Refinish				0.3	RF
21	I		76 07	Panel,Radiator Side RT	Repair				2.0*	SM
22	L		76	Panel,Radiator Side RT	Refinish				0.3	RF
23	E		72 07	Crsmbr,Rad Panel Upr	53060AE00A	\$74.95			5.5	SM
24	L		72	Crsmbr,Rad Panel Upr	Refinish				0.5	RF
25	E		74 07	Crsmbr,Rad Pnl Lower	51231AE00A	\$53.27			2.1	SM
26	L		74	Crsmbr,Rad Pnl Lower	Refinish				0.3	RF
27	E		87 07	Crsmbr,Rad Pnl Lower	53060AE06A	\$49.95			INC	SM
28	L		87	Crsmbr,Rad Pnl Lower	Refinish				0.3	RF
29	EC		755	Radiator >> Keystone 414-463-1019	QUALITY REPL. PART	\$217.00*			0.5	SM
30	N		989	A/C Evac Rechrq & Rcvr	Additional Labor				1.8	ME
31	EC		731	Condenser,A/C >> Keystone 414-463-1019	QUALITY REPL. PART	\$175.00*			INC	ME
32	EC		714	Fan Assembly,A/C >> Keystone 414-463-1019	QUALITY REPL. PART	\$94.00*			0.4	ME
33	I		106 07	Pnl,Inr Fender Front RT	Repair				1.5*	SM
34	L		106	Pnl,Inr Fender Front RT	Refinish				0.6	RF
35	I		115 07	Side Member,Front LT	Repair				2.0*	SM
36	L		115	Side Member,Front LT	Refinish				0.6	RF
37	I		116 07	Side Member,Front RT	Repair				4.0*	SM
38	L		116	Side Member,Front RT	Refinish				0.4	RF
39	I		103	Fender,Front LT	Repair				1.5*	SM
40	L		103	Fender,Front LT >> Refinish within panel	Refinish				1.6	RF
41	E		104	Fender,Front RT	57120AE06A	\$219.95			1.2	SM
42	L		104	Fender,Front RT	Refinish				2.3	RF

Claim #: 337304

Line	Op	Quote	MC	Description	MFR Part No	Price	ADJ%	B%	Hours	R
43	RI	59		Cladding,Front Fender LT	R & I Assembly				0.3	SM
44	RI	60		Cladding,Front Fender RT	R & I Assembly				0.3	SM
45	E	1702		Cover,Timing Belt	13570AA12B	\$30.47			1.4	ME
46	E	1703		Cover,Timing Belt LT	13574AA10A	\$19.38			INC	ME
47	E	1700		Belt,Drive	73323AC000	\$11.95			0.7	ME
48	E	1763		Belt,Drive	809218260	\$14.95			INC	ME
49	RI	138		Deflector,Rocker Panel LT	R & I Assembly				INC	SM
50	RI	139		Deflector,Rocker Panel RT	R & I Assembly				INC	SM
51	BR	208		Door Shell,Front RT	Blend Refinish				1.0	RF
52	RI	242		Midg,Front Door Belt RT	R & I Assembly				0.3	SM
53	RI	68		Cladding,Front Door RT	R & I Assembly				0.3	SM
54	RI	230		Mirror,Outer R/C RT	R & I Assembly				0.3	SM
55	RI	228		Handle,Front Door Otr RT	R & I Assembly				1.2	SM
56	N	M18		Set-Up And Measure	Additional Labor				1.5*	SM*
				>> Check frame						
57	EC	M20		Anti-Freeze-Coolant	QUALITY REPL. PART	\$14.00*				SM
58	EC	M21		Refrigerant	QUALITY REPL. PART	\$25.00*				SM
59	L			Clear Coat	Refinish				2.5*	RF*
60	SB			Hazardous Waste Removal	Sublet Repair	\$2.00*				SM*
61	EC			Flex additive	QUALITY REPL. PART	\$8.00*				SM*
62	EC			Corrosion Protection	QUALITY REPL. PART	\$10.00*			0.3*	SM*
63	EC			Cover Car Exterior	QUALITY REPL. PART	\$5.00*				RF*
64	TT			Two-tone	Two-Tone				1.0*	RF*

64 Items

MC	Message
01	CALL DEALER FOR EXACT PART # / PRICE
07	STRUCTURAL PART AS IDENTIFIED BY I-CAR
46	PRINTABLE ALTERNATE PARTS COMPARE

**Estimate Total & Entries**

Gross Parts	\$1,775.56
Other Parts	\$966.00
Paint Materials	\$515.20
Parts & Material Total	\$3,256.76
Tax on Parts & Material	@ 5.600% \$182.38

Labor	Rate	Replace	Repair	Total	
		Hrs	Hrs	Hrs	
Sheet Metal (SM)	\$48.00	16.7	14.4	31.1	\$1,492.80
Mech/Elec (ME)	\$70.00	2.5	1.8	4.3	\$301.00
Frame (FR)	\$48.00				
Refinish (RF)	\$48.00	18.4		18.4	\$883.20
Paint Materials	\$28.00				

Labor Total	53.8 Hours	\$2,677.00
Tax on Labor	@ 5.600%	\$149.91
Sublet Repairs		\$2.00
Tax on Sublet	@ 5.600%	\$0.11
Gross Total		\$6,268.16
Less: Deductible		\$500.00-
Net Total		\$5,768.16

Alternate Parts Y/04/00/00/04/02 CUM 04/00/00/04/02 Zip Code: 53217 Wisconsin-Milwaukee

Claim #: 337304

Recycled Parts Y/O/O Zip Code: 53005

ADP Estimating 4.0.426 ES 06/05/2006 11:36 AM REL 4.0.426 DT 05/01/2006 DB 06/01/2006

Copyright (C) 2006 ADP Claims Solutions Group, Inc.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

- |                            |                                |                            |
|----------------------------|--------------------------------|----------------------------|
| * = User-Entered Value     | E = Replace OEM                | NG = Replace NAGS          |
| EC = QUALITY REPL. PART    | OE = Replace PXN OE Srpls      | UE = Replace OE Surplus    |
| ET = Partial Replace Labor | EP = QUALITY REPL. PART        | EU = LIKE KIND & QUAL.PRT  |
| TE = Partial Replace Price | PM = Replace PXN Reman/Rebit   | UM = Replace Reman/Rebuilt |
| L = Refinish               | PC = Replace PXN Reconditioned | UC = Replace Reconditioned |
| TT = Two-Tone              | SB = Sublet Repair             | N = Additional Labor       |
| BR = Blend Refinish        | I = Repair                     | IT = Partial Repair        |
| CG = Chipguard             | RI = R & I Assembly            | P = Check                  |
| AA = Appearance Allowance  | RP = Related Prior Damage      |                            |



This report contains proprietary information of ADP and may not be disclosed to any third party (other than the insured and claimant) without ADP's prior written consent.

Copyright (C) 2006 ADP Claims Solutions Group, Inc.

The ADP Logo is a registered trademark of ADP of North America, Inc.

Detail for payment H02707478 as of 14:36:56 on 07/25/06

Claim: DA60-200337304 Status: Paid

Issue at: Milwaukee

Amount: \$5,768.16

Authorized by: LYNN-L

Overlimit Authorized by:

Last Update by: LYNN-L Last Update CSC: Milwaukee

Method of payment: Computer issued

Payee Code: Insured

Payee Name: Port Shell Molding & Tembros Engineering Inc and Pinkney's  
Capital Auto Body

Send to Code: Insured

Send to Address: PORT SHELL MOLDING  
604 HICKORY ST  
PEWAUKEE, WI 53072-3548

In payment of: collision loss less \$500 deductible

---Reserve Information---

*Cl Reserve Name	Type	Amount	Payment type	VST	Suffix	VST Name	Days Pd	Type of check
01 Coll	LOSS	5,768.16	Other					EMC
*			SUBT					
		5,768.16						

--Flags--  
Send to address changed  
Payee changed

LL 07/25/06 14:37:04