

# CERTIFICATE OF APPROPRIATENESS APPLICATION FORM

Incomplete applications will not be processed for Commission review.

Please print legibly.

	Pabst Sign in Pabst Brewery HD	)	
ADD	RESS OF PROPERTY:		
The b	oridge and sign structure spans b	petween two properties: 1009 W. Ju	uneau & 1203 N. 10th
NAM	E AND ADDRESS OF OWN	ER:	
Name	e(s): The Brewery Neighborhood	Improvement District No. 1	
Addre	ess: 1125 N. 9th Street, Suite J		
City: ,	Milwaukee	State: WI	ZIP: 53233
Emai	erin@thebrewery.org		
Teler	phone number (area code & n	number) Daytime: <u>414-899-2817</u>	Evening:
		•	-
APPI	LICANT, AGENT OR CONTR	RACTOR: (if different from own	er)
Name	e(s): Erin Stenum		
Addre	ess: 1125 N. 9th Street, Suite J		
City: Milwaukee			
City:_	Milwaukee	State: WI	ZIP Code: <u>53233</u>
	Milwaukee  : erin@thebrewery.org	State: WI	ZIP Code: <u>53233</u>
Emai	erin@thebrewery.org		
Emai	erin@thebrewery.org	State: WI  number) Daytime: 414-899-2817	
Emai Telep	I: erin@thebrewery.org  phone number (area code & n  ACHMENTS: (Because proje	number) Daytime: 414-899-2817	ZEvening:
Emai Telep ATTA at 414	l: erin@thebrewery.org  phone number (area code & n  ACHMENTS: (Because proje 4-286-5712 for submittal requ	number) Daytime: 414-899-2817 ects can vary in size and scope, uirements)	ZEvening:
Emai Telep	I: erin@thebrewery.org  phone number (area code & n  ACHMENTS: (Because proje	number) Daytime: 414-899-2817 ects can vary in size and scope, uirements)	ZEvening:
Emai Telep ATTA at 414	I: erin@thebrewery.org  chone number (area code & note that the number (ar	number) Daytime: 414-899-2817 ects can vary in size and scope, uirements)	Z Evening:  please call the HPC Office
Emai Telep ATTA at 414	i: erin@thebrewery.org  chone number (area code & note that note has been determined by the code of th	number) Daytime: 414-899-2817 ects can vary in size and scope, uirements)	Evening:  please call the HPC Office  (annotated photos recommende ed to 11" x 17" or 8 ½" x 11")
Emai Telep ATTA at 414	i: erin@thebrewery.org  chone number (area code & note that note has been determined by the code of th	ects can vary in size and scope, uirements)  PROJECTS: reas & all sides of the building (rawings (1 full size and 1 reducts and drawings is also requested.	Evening:  please call the HPC Office  (annotated photos recommende ed to 11" x 17" or 8 ½" x 11")
Emai Telep ATTA at 414	i: erin@thebrewery.org  chone number (area code & note that the number (ar	ects can vary in size and scope, uirements)  PROJECTS: reas & all sides of the building (rawings (1 full size and 1 reducts and drawings is also requested iffications (see next page)	Evening:  please call the HPC Office  (annotated photos recommende ed to 11" x 17" or 8 ½" x 11")
Emai Telep ATTA at 414	chone number (area code & noted to the number (area code to the number (area code) and the nu	ects can vary in size and scope, uirements)  PROJECTS: reas & all sides of the building (rawings (1 full size and 1 reducts and drawings is also requested iffications (see next page)	Evening:  please call the HPC Office  (annotated photos recommende ed to 11" x 17" or 8 ½" x 11") ed.

PLEASE NOTE: YOUR APPLICATION CANNOT BE PROCESSED UNLESS
BOTH PAGES OF THIS FORM ARE PROPERLY COMPLETED
AND SIGNED.

### 5. DESCRIPTION OF PROJECT:

Tell us what you want to do. Describe all proposed work including materials, design, and dimensions. Additional pages may be attached via email.

# **Bridge Decking**

All existing wood decking and beams should be reviewed for decay in future. All wood members (both deck and joists) with decay should be replaced with new wood members of same size and strength. Until such compromised members are replaced, a temporary protection measure (e.g., barricade, plywood, etc.) should be undertaken as a safety measure.

#### Steel Trusses

All main steel trusses and transverse open web joists including welded joints should be cleaned to remove rust and coated with rust inhibitive paint (minimum 2 coats). A new steel member or steel reinforcement is recommended for the existing sign supporting member with a section loss shown in photographs P12 and P13. Similar recommendation is also made for the truss panel point shown in photograph P11. The trusses bearing condition at the north end requires further review from the roof of Building 21 to determine the cause of splice plate detachment and missing rivets. Plug weld is recommended at the missing rivets. The cracked connector in guardrail connection should be removed and replaced or apply new welds. Cleaning and painting is also recommend to existing stair at the south end with corrosion.

# Truss Supports

Tuck pointing is strongly recommended in the existing building wall area identified in photograph P17 supporting the south ends of the trusses. Prior to tuck pointing, remove all existing deteriorated and loose mortar up to 1" in depth in the brick joints and clean. At the north truss supporting ends, sealing existing cracks in stone coping, pointing loose and cracked mortar (by removing loose mortar and cleaning) are also priority repair items. This repair will stop any moisture infiltration into existing building wall.

6.	SIGNA	TURE	OF A	PPLIC	CANT:
----	-------	------	------	-------	-------

Erin Sternin	
Signature	
Erin Stenum	September 20, 2023
Please print or type name	Date

This form and all supporting documentation MUST arrive by 4:00 pm (11:59 pm via email) on the deadline date established to be considered at the next Historic Preservation Commission Meeting. Any information not provided to staff in advance of the meeting will not be considered by the Commission during their deliberation. Please call if you have any questions and staff will assist you.

## Mail or Email Form to:

Historic Preservation Commission City Clerk's Office 841 N. Broadway, Rm. B1 Milwaukee, WI 53202

PHONE: (414) 286-5712 or 286-5722 hpc@milwaukee.gov www.milwaukee.gov/hpc

Or click the SUBMIT button to automatically email this form for submission.

SUBMIT