

Department of Neighborhood Services

Inspectional services for health, safety and neighborhood improvement

Martin G. Collins Commissioner

Tracy Williams
Chief Operations Officer

April 29,2005

Mr. Ronald D. Leonhardt, City Clerk 200 E. Wells Street, Room 205 Milwaukee, WI 53202

Mr. Leonhardt:

Re: 1570 W. National Av., Parkway Hotel

Please consider this a formal objection to the renewal of the hotel license, # 04 15299, at the above captioned location. The Department of Neighborhood Services has noted violations of section 275-20-7-q-5 and 275-20-7-q-7 as grounds for that objection.

Additionally, we have significant pending life/safety orders that come due prior to this renewal. We also reserve our right to object based on those orders.

Sincerely,

Ronald W. Roberts, Supervisor

Commercial Fire Inspection Division

Phone: 286-3862 Fax: 286-0437

E-mail: rrober@milwaukee.gov.

Subscribed + Sworn to before me This Indday of May 2005

My Commisseonsepperes: 1/20/20


Attachments

cc Martin Collins, Commissioner
David Krey, Supervisor, DNS Environmental
License Division
Vincent Bobot, Assistant City Attorney
Alderman James N. Witkowiak

SONALD OF MILWAUKEE

OS APR 29 PM 4: 4.1

ROMALD OF MILWAUKEE



City of Milwankee Department of Neighborhood Services Environmental Section

Hotel/Motel AU. 1570 M License AR 25 2005/2:06 Pr Application/Renewal July 1, 2005 – June 30, 2006

4001 S 6th St, 2nd floor, Milwaukee, WI 53221 (414) 286-5771

My Commission expires: 2-11-6

2627 N Richmon Chicago, IL 606			Fee \$250.00	
Licensed Pren	nises: 1570 W Nat	ional Ave	Zip Code 532	
Business Name: ID No. 04 15299	, se	Phone No. 64 No. of Persons	5-4410 s Permitted 52	
Preferred Mailing	3 Address <u>2617</u>	N. Richmo	and St.	Market Market and American Am
**Applic	ation and fee must be	received prior to	April 1 or a \$75 late fo	ee will be charged
Legal Licensee	Agent/Manag	ger Add	iress of Licensec	Phone Number
Applicant Type:	(Indicate one of the f	following)		,
☐ Individual	☐ Partnetship	Corporation	on Other L	LC
Milwaukee County, a l management and cont	box is not acceptable. However, local representative inside the rol of the premises. Please process and — please list full n	<u>Milwoukee County limits</u> ovide this information on	must <u>be authorized by the ox</u> page 2 if applicable.	ner/operator 10 exercise of
	artnership, Corporati of all Partners, Office			ume, address, phone
	any partners, officers of minor traffic violation	is, list details below		pal code convictions
building code). T	nere is no statute of lim y the Police Departmen			a voomie in mit ooloon.
building code). T	y the Police Departmen	t. Use a separate sl	neet if necessary.	tion of Case

License No.

Page 2

Electised Fremises: 1370 W National Ave	Business Name: Parkay Hotel
Name Nancy Nicholson	
Address 1570 W. National Ave.	
Phone (414) 645-4410	Date of Birth3-25-56
Name Dean Stanley	
Address 2617 NJ. Richmond St.	Chicago IL 60647
Address 2617 NJ. Rich Mond St. Phone (773)235-3580	Date of Birth 1-14-64
Name	-
Address	
Phone	
Name	
Address	
Phone	Date of Birth
Name	
Address	
Phone	Date of Birth

NOTE – PROVIDE FULL NAME, INCLUDING MIDDLE INITIAL, HOME ADDRESS AND HOME PHONE. YOU MUST INDICATE A STREET ADDRESS. A POST OFFICE BOX IS NOT ACCEPTABLE. HOWEVER, YOU MAY INDICATE A PREFERRED MAILING ADDRESS.

PLEASE ATTACH ADDITIONAL PAGE(8) IF NECESSARY

Sort by: Inspection date

Tract: Open/All:All

										Orig		_	Last		
Curr	Cens						Insp		-	Inspect	•	Curr	Status		
Distr	Trct	Address	\$			Taxkey	Type	Serial #	Viols	Date	Date	Status	Date	Inspect	or
705	157	1570	1572	w NATIONAL	ΔV	433~9991-200	REF	4975631	29	041505	051805	U	041805	RADMER,	ROBERT
200	157	1570	1572	W NATIONAL		433-9991-200	REF	4977171	13	041505	042405	U	041905	CLEARY,	THOMAS
200	157	1570	1572	W NATIONAL		433-9991-200	REF	4977172	3	041505	050305	U	041905	CLEARY,	THOMAS
200	157	1570	1572	W NATIONAL		433-9991-200		4977173	194	041505	060305	U	041905	CLEARY,	THOMAS
200	157	1570	1572	W NATIONAL		433-9991-200	REF	4977174	1	041505	071805	U	041905	CLEARY,	THOMAS
808	157	1570	1572	W NATIONAL		433-9991-200	COM	4977961	18	041505	051905	Ü	041905	ZOLADKI	EWICZ,
608	157	1570	1572	W NATIONAL		433-9991-200	COM	4980001	13	041505	052105	U	042105	EIGHME,	GREG
608	157	1570	1572	W NATIONAL		433-9991-200	COM	4980002	1	041505	042205	U	042105	EIGHME,	GREG
425	157	1570	1572	W NATIONAL		433-9991-200	PER	4983451	21	041505	051105	U	042005	BENDER,	COREY
318	157	1570	1572	W NATIONAL		433-9991-200	REF	4729621	3	101804	102104	D	101804	ALANIZ,	RICHAR
410	157	1570	1572	W NATIONAL		433-9991-200	COM	4581101	2	062904	070804	Α	070804	CARTER,	HENRY
430	157	1570	1572	W NATIONAL		433-9991-200	PER	4431001	4	031804	090304	Α	090304	FLORES,	MELISS
430	157	1570	1572	W NATIONAL		433-9991-200	PER	4431002	12	031804	120904	Α	120904	FLORES,	MELISS
680	157	1570	1572	W NATIONAL		433-9991-200	PED	4237541	1	091503	011304	Α	011304	WILCOX,	PAUL M
680	157	1570	1572	W NATIONAL		433-9991-200	PED	4237551	1	091503	011304	Α	011304	WILCOX,	PAUL M
880	157	1570	1572	W NATIONAL		433-9991-200	SI	4193051	1	081103	101703	Α	101703	NOWAK,	MARK
428	157	1570	1572	W NATIONAL		433-9991-200	FIR	4028321	4	040203	041103	Α	041103	MCKEAN,	TOM
428	157	1570	1572	W NATIONAL		433-9991-200	FIR	4028322	16	040203	071603	A	071603	MCKEAN,	TOM
428	157	1570	1572	W NATIONAL		433-9991-200		4028323	1	040203	041103	Α	041103	MCKEAN,	TOM
460	1) {	1570	1.016.	M WALLOWYE		,						-			

Total: 19 Records

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Electrical Section 841 N. Broadway Milwaukee, WI 53202

DEPARTMENT COPY

Serial #: 004975631 Inspection Date: April 15, 2005

District #: 705 CT: 157

rhse-ref

Recipients:

MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, REG AGENT, 901 S WHITNEY WAY, MADISON, WI 53711

MILWAUKEE PARKWAY, LLC, 2627 N RICHMOND ST, CHICAGO, IL 60647 NANCY NICHOLSON - OPERATOR, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 30 days of service of this order.

- 222-01
 Comm 16.09 Properly refasten service entrance raceway to building.
- 222-01
 Comm 16.12 (NEC 215.5) Provide calculations used in determining conductor sizes used for service installation. (Permit is not required.)
- 3. 222-13 Electrical permit is required. Have a licensed electrician obtain a permit.
- 222-01
 Comm 16.12 (NEC 210.23) Provide proper size branch circuit for connected loads.
- 222-01
 Comm 16.12 (NEC 334.12(A)(1-12)) Remove non-metallic cable as this wiring method is not approved for this location.
- 6. 222-01
 Comm 16.12 (NEC 400.8(1)) Remove flexible electric cord wiring where used as substitute for fixed wiring of structure. (Permit is not required.)
- 222-01
 Comm 16.12 (NEC 300.15) Provide box or fitting at each conductor splice connection point.

OFFICIAL NOTICE OF VIOLATION

- 8. 222-01 Comm 16.12 (NEC 300.15) Provide box and cover so that exposed conductors are properly enclosed.
- 222-01
 Comm 16.12 (NEC 300.11(A)) Provide approved means for properly securing in place all raceways according to their respective articles. (Permit is not required.)
- 10. 222-01 Comm 16.12 (NEC 314.23(A-D)) Provide approved means for properly securing in place all enclosures within the scope of Article 370.
- 11. 222-01
 Comm 16.12 (NEC 314.16) Provide proper size box to provide free space for all conductors enclosed in box.
- 12. 222-01
 Comm 16.12 (NEC 314.25) Provide approved covers, face plates or canopies where missing throughout building. (Permit is not required.)
- 13. 222-01
 Comm 16.12 (NEC 110.12(A)) Effectively close unused openings in boxes, raceways, auxiliary gutters, cabinets and equipment cases or housing to afford protection substantially equal to the wall of the equipment.
- 14. 222-01
 Comm 16.12 (NEC 250.104(A)) Provide effective bond between interior metal water system and service grounding system.
- 15. 222-01
 Comm 16.09 Repair or replace all defective switches and receptacles located throughout building.
- 16. 222-01 Comm 16.09 Repair or replace defective fixtures.
- 17. 222-01
 Comm 16.18 Install or use all equipment in the exact manner and for the exact purpose indicated by the manufacturer's instructions, marking, listing or labeling.
- 18. 222-01
 Comm 16.12 (NEC 110.12) Install all electrical equipment in a neat and workmanlike manner.
- 222-01
 Comm 16.12 (NEC 110.13(A)) Firmly secure electrical equipment to the surface on which it is mounted.
- 20. 222-01
 Comm 16.12 (NEC 410.16(C)) Provide approved means of fastening fluorescent fixtures to framing members of suspended ceiling. (Permit is not required.)
- 21. 222-01
 Comm 16.12 (NEC 110.14(A)) Provide approved equipment for termination of more than one conductor on an individual terminal and/or for termination of aluminum conductors.

Serial #: 004975631 Inspection Date: April 15, 2005

1570-1572 W NATIONAL AV

- 22. 222-01 Comm 16.12 (NEC 200.10) Rearrange wiring so that proper polarity is maintained at receptacle.
- 23. 222-01 Comm 16.12 (NEC 110.22) Properly identify each feeder or branch circuit at the point where it originates.
- 24. 222-01
 Comm 16.12 (NEC 110.26(A)) Rearrange equipment so that proper working clearances can be attained.
- 25. 222-01
 Comm 16.12 (NEC 110.26(B)) Remove materials stored in work space area around electrical equipment which is required to be accessible at all times. (Permit is not required.)
- 26. 222-01 Comm 16.12 (NEC 240.4) Provide proper size overcurrent protection for conductors.
- 27. 222-01 Comm 16.12 (NEC 240.51 & 240.54) Install type "S" fuses and adapters for all branch circuits due to evidence of over-fusing.
- 28. 222-01, 200.32-3-a
 Provide quadruple fee electric wiring permit for electrical work started before first obtaining an electrical permit.
- 29. 275-62
 Provide at least one convenience outlet in each room (excluding fixture adapters).

For any additional information, please phone Assistant Supervisor Robert E. Radmer at [414]-286-2522 between the hours of 7:00am-3:00pm Monday through Friday.

Per Commissioner of Neighborhood Services By-

Robert E. Radmer Assistant Supervisor

FAILURE TO COMPLY

Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

RIGHT TO APPEAL

You may file an appeal within 20 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission within 20 days of service of this order. If service of this order is made by mail, the appeal shall be received within 30 days or by the compliance date plus 5 days, not to exceed 30 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

1570-1572 W NATIONAL AV Serial #: 004975631
Inspection Date: April 15, 2005

TENANT RENT WITHHOLDING

Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

REINSPECTION FEES

In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filing an appeal.

TRADUCCION EN ESPAÑOL

Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

- 4 -

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Code Enforcement - Commercial 841 N. Broadway Milwaukee, Wisconsin 53202

DEPARTMENT COPY

Serial #: 004977171 Inspection Date: April 15, 2005

> District #: 200 CT: 157

> > hotl-ref

Recipients:
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS - R/A, 901 S WHITNEY WAY, MADISON WI 53711
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, INC - R/A, 2627-N RICHMOND ST, CHICAGO IL 60647
NANCY NICHOLSON - OPERATOR, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

AKA: The Parkway Hotel

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 5 days of service of this order.

Interior

First Floor Common Hall Common hall

1. 214-3
The center of smoke detectors hung on walls shall be a minimum of 6 inches and a maximum of 12 inches from the ceiling.

RELOCATE THE SMOKE DETECTORS TO AN ACCEPTABLE HEIGHT.

Unit:#51 Third Floor

General

2. 214-27 Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

OFFICIAL NOTICE OF VIOLATION

Unit:#52 Third Floor

General

Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#50 Third Floor

General

4. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#35 Second Floor

General

Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#33 Second Floor

General

6. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#29 Second Floor

General

7. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#21 Second Floor

General

8. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#7 First Floor

General

9. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#6 First Floor

General

10. 214-27
Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#36 Second Floor

General

214-27 11. Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#28 Second Floor

General

12. 214-27 Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

Unit:#24 Second Floor

General

214-27 13. Provide, install and properly maintain approved smoke detector(s) installed in a manner and location consistent with its listing and at least one detector in the basement and on each floor level except unfinished attic or storage areas and within 6 feet of each sleeping area. If a floor level contains 2 or more sleeping areas, each sleeping area shall be provided with a smoke detector.

For any additional information, please phone Thomas Cleary at [414]-286-5910 between the hours of 7:00am-10:00am or 3:15-3:45pm Monday through Friday.

Per Commissioner of Neighborhood Services By-

Thomas Cleary

FAILURE TO COMPLY

Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

TENANT RENT WITHHOLDING Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

REINSPECTION FEES

In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filling an appeal.

You may file an appeal within 5 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission by the compliance date. If service of this order is made by mail, the appeal shall be received by the compliance date plus 5 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order than the Department about a reputable presument and the date of the issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

Violations of Chapter 295 of the Milwaukee Code of Ordinances must be appealed to the Board of Zoning Appeals, 809 N. Broadway, 1st floor, Milwaukee, Wisconsin 53202, phone 414-286-2501. All appeal applications must include the required information outlined in sec. 295-311-6.

TRADUCCION EN ESPAÑOL

Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

DEAN W STANLEY - PREFERRED CONTACT, 2627-N RICHMOND ST, CHICAGO IL 60647

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Code Enforcement - Commercial 841 N. Broadway Milwaukee, Wisconsin 53202

DEPARTMENT COPY

Serial #: 004977172 Inspection Date: April 15, 2005

District #: 200 CT: 157

hoti-ref

Recipients:
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS - R/A, 901 S WHITNEY WAY, MADISON WI 53711
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, INC - R/A, 2627-N RICHMOND ST, CHICAGO IL 60647
NANCY NICHOLSON - OPERATOR, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

AKA:The Parkway Hotel

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 14 days of service of this order.

Fire Prevention

- 1. 214-3 IFC 703.2 Repair or replace defective fire door assembly. (west exit door harware defective.)
- 2. 214-3
 All unmonitored fire alarm systems are required to be functionally tested on a quarterly basis by the property owner or the owner's representative. Qualified service personnel shall perform an annual test of the system. A written report of the required testing shall be maintained and made available to the code official.

General

3. 275-20-7-h
The operator and building owner of every licensed dwelling facility shall be responsible for the sanitary maintenance of all walls, floors and ceilings and for the maintenance of a sanitary condition in every other part of the licensed dwelling facility, and they shall be further responsible for the sanitary maintenance of the entire premises where the entire structure or building within which the licensed dwelling facility is contained is leased or occupied by the operator and the building owner.

YOU ARE THEREFORE ORDERED TO RESTORE ALL HOTEL UNITS, APARTMENTS, COMON AREAS AND SECURED AREAS TO A SANITARY CONDITION.

OFFICIAL NOTICE OF VIOLATION

The City of Milwaukee - Department of Neighborhood Services

1570-1572 W NATIONAL AV

For any additional information, please phone Thomas Cleary at [414]-286-5910 between the hours of 7:00am-10:00am or 3:15-3:45pm Monday through Friday.

Per Commissioner of Neighborhood Services By-

Thomas Cleary

FAILURE TO COMPLY

Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

TENANT RENT WITHHOLDING

Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

REINSPECTION FEES

In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filling an appeal.

You may file an appeal within 14 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission by the compliance date. If service of this order is made by mail, the appeal shall be received by the compliance date plus 5 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

Violations of Chapter 295 of the Milwaukee Code of Ordinances must be appealed to the Board of Zoning Appeals, 809 N. Broadway, 1st floor, Milwaukee, Wisconsin 53202, phone 414-286-2501. All appeal applications must include the required information outlined in sec. 295-311-6.

TRADUCCION EN ESPAÑOL

Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

DEAN W STANLEY - PREFERRED CONTACT, 2627-N RICHMOND ST, CHICAGO IL 60647

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Code Enforcement - Commercial 841 N. Broadway Milwaukee, Wisconsin 53202

DEPARTMENT COPY

Serial #: 004977173 Inspection Date: April 15, 2005 District #: 200

CT: 157

hotl-ref

Recipients:
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS - R/A, 901 S WHITNEY WAY, MADISON WI 53711
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, INC - R/A, 2627-N RICHMOND ST, CHICAGO IL 60647
NANCY NICHOLSON - OPERATOR, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

AKA: The Parkway Hotel

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 45 days of service of this order.

Fire Prevention

- 214-19
 Repair or replace defective rail(s) on fire escape platform.
- 214-19
 Paint fire escape-properly prepare all surfaces by removing scale and rust.
- 3. 214-19
 Repair or replace defective rail on fire escape platform.
- 4. 214-19
 - Fire escapes must be critically examined. Provide a report by a registered architect or structural engineer. A report (2 copies) must be submitted to the Commissioner of Neighborhood Services by the architect or engineer showing the structural condition of the fire escape and its supports. All noted defects on the written report shall be corrected within 30 days of the date of the report. A follow-up report is to be submitted to the Commissioner of Neighborhood Services by the architect or engineer indicating that all defects have been corrected.

General

5. 275-20-7-n-2
Transoms shall be of 1.5 inch solid wood or shall be covered with 16 gauge sheet metal screwed or otherwise securely fastened to the transom or the equivelent of 1/2 inch plywood or hardboard secured to the existing transome or a labeled 20 minute transom and frame.

YOU ARE THEREFORE ORDERED TO REPLACE THE EXISTING TRANSOMS WITH TRANSOMS THAT MEET THE REQUIREMENTS OF THE CODE ABOVE.

Exterior

South Side Front

- 6. 275-32-3
 Replace mortar missing from exterior wall (tuckpoint).
- 7. 275-32-4-a Repair or replace defective window sills. (1st floor).

West Side

- 8. 275-32-3
 Replace mortar missing from exterior wall (tuckpoint). Replace step crack by center stairwell.
- 9. 275-32-3 Restore foundation to a rodentproof condition. (by exit door).
- 10. 275-32-2 Repair crack in foundation wall. (by exit door).

Interior

Basement

- 11. 275-55-2
 Replace missing floor drain cover.
- 12. 275-32-3-f Seal chimney opening in basement.
- 13. 275-32-3-F
 Repair or replace loose or defective chimney cleanout door.

First Floor Common Hall Common hall

- 14. 214-3
 IFC 1011.2 Hallways must be kept free of all storage of material, trash, or any other obstruction that could hamper easy exiting in case of fire. Remove any obstruction immediately.
- 15. 275-33-3-a Replace missing ceiling tile. (by south stairs).

16. 214-3 Provide and install a self-closing device for the fire door.

Second Floor Common Hall Common hall

- 17. 275-33-3-a Repair defective ceiling plaster and paint. (by north exit).
- 18. 275-33-3-a Replace missing ceiling tile.
- 19. 214-3
 Replace the door to the north stairwell with a rated fire door.

Third Floor Common Hall

- 20. 275-62-3 A recent inspection indicated electrical wiring improperly installed or defective that is potentially hazardous. Restore to a safe condition. (open junction box.)
- 21. 214-3 IFC 1010.3 Exit signs shall be illuminated at all times.
- 22. 214-3 Replace illegal exit light.

Center Second Floor Common Stairs

- 23. 275-33-5-a Repair or replace defective stair handrail. (1st to 2nd floor and 2nd to 3rd floor.)
- 24. 275-33-3-a Repair or remove defective carpeting. (from 2nd to 1st floors.)

North Common Stairs

- 25. 275-32-3-g Replace defective stair tread. (between 1st and 2nd floors).
- 26. 275-32-3-g
 Replace defective stair riser. (between 1st and 2nd floors.)
- 27. 275-32-3-g
 Repair defective stair stringer and replace any missing or defective stair treads and stair risers. (Call 286-2513 for information regarding the required permit.) (2nd to 3rd fllor).
- 28. 275-33-3-a Repair or remove defective carpeting. (landing between 1st and 2nd floors.)
- 29. 275-33-3-a
 Replace or resecure loose metal stair noseing.

First Floor Mens common bathroom

Bathroom

30. 275-33-3-a Replace defective floor covering to provide a surface easily cleanable and impervious to water.

Second Floor

Bathroom 2nd floor womens common bathroom.

31. 275-53
Remove obstruction from toilet to restore to proper operating condition.

East Third Floor Storage room.

- 32. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.
- 33. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)

Third Floor Mens common bathroom

Bathroom

34. 275-20-1.5 HFS 195-05(e) Replace missing sign for mens bathroom.

Third Floor Womens common bathroom

Bathroom

- 35. 275-42-3 Provide adequate ventilation for toilet room.
- 36. 275-53
 Remove obstruction from toilet to restore to proper operating condition.
- 37. 275-42-3 Provide adequate ventilation for bathroom.
- 38. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.

Unit:#41 Third Floor

Sleeping Room

39. 275-32-4-a Repair or replace defective window sash. (will not stay open).

Serial #: 004977173 Inspection Date: April 15, 2005

Unit:#40 Third Floor

Sleeping Room

40. 275-62-3 A recent inspection indicated electrical wiring improperly installed or defective that is potentially hazardous. Restore to a safe condition. (open junction box).

41. 275-33-3-a
Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.

Unit:#43 Third Floor

Sleeping Room

42. 275-62-2
Repair or replace defective electric outlet.

Unit:#45 Third Floor

Bathroom

43. 275-53
Replace defective drain on lavatory basin (permit required for installation; call 286-3361 if you need permit information).

Unit:#47 Third Floor

Sleeping Room

44. 275-33-6
Repair or replace defective door frame.

Unit:#46 Third Floor

General

45. 214-27
The center of all smoke detectors hung on walls shall be between 6 inches and 12 inches of the ceiling.

Unit:#51 Third Floor

Sleeping Room

46. 275-34-1 Replace or remove broken mirror.

Unit:#52 Third Floor

Sleeping Room

47. 275-62-2
Repair or replace defective electrical fixture.

Serial #: 004977173 Inspection Date: April 15, 2005

1570-1572 W NATIONAL AV

Unit:#53 Third Floor

Bathroom

48. 275-53

Replace defective drain on lavatory basin (permit required for installation; call 286-3361 if you need permit information).

49. 275-33-6

Repair or replace defective door frame.

Unit:#55 Third Floor

Sleeping Room

50. 275-32-4-a

Repair or replace defective window frame. (Window will not stay open).

Unit:#56 Third Floor

Sleeping Room

51. 275-33-3-a

Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)

Unit:#57 Third Floor

Sleeping Room

52. 275-33-3-a

Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.

Unit:#59 Third Floor

Sleeping Room

53. 275-33-3-a

Repair and repaint water damaged ceiling plaster.

54. 275-33-4

Restore wall to a watertight condition and repair and paint plaster.

55. 275-33-6

Replace missing door knob.

Bathroom

56. 275-53

Replace defective drain on lavatory basin (permit required for installation; call 286-3361 if you need permit information).

Unit:#58 Third Floor

Sleeping Room

57. 275-33-3-a

Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.

Unit:#39 Second Floor

Sleeping Room

- 58. 275-62-2
 Repair or replace defective electric outlet.
- 59. 275-33-3-a
 Replace defective ceiling tile.
- 60. 275-33-6
 Replace defective room door.
- 61. 275-33-3
 Repair or replace defective baseboards.
- 62. 275-33-3-a
 Replace or remove defective floor covering.
- 63. 275-32-4-a
 Restore window to a weathertight condition.
- 64. 275-32-4-a
 Repair or replace defective window sash.
- 65. 275-32-4-a
 Repair or replace defective window latch.
- 66. 275-42-4
 Provide at least one window screen for each habitable room.

Unit:#38 Second Floor

- 67. 275-33-6
 Repair or replace defective door frame.
- 68. 275-33-3-a
 Replace defective ceiling tile.
- 69. 275-33-6
 Replace defective door hardware. Remove padlock hasp.
- 70. 275-33-3
 Repair or replace defective baseboards.

Serial #: 004977173 Inspection Date: April 15, 2005

1570-1572 W NATIONAL AV

- 71. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.
- 72. 275-33-3-a
 Replace or remove defective floor covering.
- 73. 275-32-4-a Restore window to a weathertight condition.
- 74. 275-42-4 Provide at least one window screen for each habitable room.
- 75. 275-33-6
 Repair or replace defective door hardware including the door jam where the lock hasp rests.

General

76. 275-53-1 Properly seal all open drains and water pipes.

Unit:#37 Second Floor

Sleeping Room

- 77. 275-62-2
 Repair or replace defective electrical fixture.
- 78. 275-33-6
 Repair or replace defective door frame. This includes the damaged jam.
- 79. 275-33-6 Replace defective door hardware.
- 80. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner. Around unsealed plumbing pipes.
- 81. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.) By miror up from unsealed plumbing.
- 82. 275-33-3-a
 Replace or remove defective floor covering.

General

83. 275-53-1
Properly seal all open drains and water pipes.

Unit:#35 Second Floor

Sleeping Room

- 84. 275-33-6
 Repair or replace defective door frame. This includes the damaged jam.
- 85. 275-33-3-a
 Replace defective ceiling tile.
- 86. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.
- 87. 275-33-3-a Replace or remove defective floor covering.
- 88. 275-32-4-a Restore window to a weathertight condition.
- 89. 275-32-4-a Repair or replace defective window latch.
- 90. 275-42-4 Provide at least one window screen for each habitable room.

General

91. 275-53-1 Properly seal all open drains and water pipes.

Unit:#33 Second Floor

Sleeping Room

- 92. 275-62-2
 Repair or replace defective electrical fixture.
- 93. 275-33-6
 Repair or replace defective door frame. This includes the damaged jam.
- 94. 275-33-6
 Repair or replace defective door hardware. This includes the hasp.

General

95. 275-81-1-a
Restore dwelling unit to clean and sanitary condition.

Unit:#31 Second Floor

Sleeping Room

96. 275-33-3-a Replace defective ceiling tile.

Serial #: 004977173 Inspection Date: April 15, 2005

- 97. 275-33-6
 Replace defective door hardware. This includes the door hasp.
- 98. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner. Around plumbing fixtures.
- 99. 275-32-4-a
 Restore window to a weathertight condition.
- 100. 275-32-4-a
 Repair or replace defective window latch.
- 101. 275-42-4
 Provide at least one window screen for each habitable room.
- 102. 275-22-2
 Provide proper numbers for all second class dwelling units.

Unit:#29 Second Floor

Sleeping Room

- 103. 275-33-3-a Replace defective ceiling tile.
- 104. 275-33-3-a Replace or remove defective floor covering.
- 105. 275-42-4
 Provide at least one window screen for each habitable room.

Unit:#27 Second Floor

General

- 106. 275-53-1 Properly seal all open drains and water pipes.
- 107. 275-22-2 Provide proper numbers for all 2nd class dwelling units.

- 108. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.
- 109. 275-32-4-a Restore window to a weathertight condition.
- 110. 275-42-4
 Provide at least one window screen for each habitable room.

111. 275-32-4-a Replace broken window pane.

Unit:#25 Second Floor

Sleeping Room

- 112. 275-33-6 Repair or replace defective door frame.
- 113. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.
- 114. 275-32-4-a Restore window to a weathertight condition.
- 115. 275-32-4-a Repair or replace defective window sash.
- 116. 275-32-4-a Repair or replace defective window frame.
- 117. 275-42-4
 Provide at least one window screen for each habitable room.

Unit:#23 Second Floor

Sleeping Room

118. 275-33-3-a
Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.) Hole in the ceiling.

Unit:#21 Second Floor

General

119. 275-82-2 Exterminate mice.

- 120. 275-33-6
 Repair or replace defective door frame. This includes door jamb.
- 121. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.) By windows.
- 122. 275-32-4-a Restore window to a weathertight condition.
- 123. 275-32-4-a
 Repair or replace defective window latch.

124. 275-33-3-a
Repair defective floor. Replace any missing or broken floor boards. By radiator and windows.

Unit:#20 Second Floor

Sleeping Room

- 125. 275-33-6
 Repair or replace defective door frame. This include the jamb.
- 126. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner. By radiator.
- 127. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.
- 128. 275-33-6
 Repair or replace defective door hardware.
- 129. 275-32-4-a Restore window to a weathertight condition.
- 130. 275-42-4 Provide at least one window screen for each habitable room.

Unit:#7 First Floor

- 131. 275-33-6
 Repair or replace defective door frame. This includes the jamb.
- 132. 275-33-3-a Replace defective ceiling tile.
- 133. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.
- 134. 200-11-4 Every habitable room requires a window for light and ventilation. Discontinue the illegal use of a room without a window as habitable space.
- 135. 275-21-4 Discontinue the preperation of food in a hotel room.
- 136. 275-22-2 Provide proper numbers for all second class dwelling units.

Unit:#6 First Floor

Sleeping Room

- 137. 275-33-3-a Replace defective ceiling tile.
- 138. 275-33-3-a
 Replace or remove defective floor covering. Where red tape is present.

Kitchen

139. 275-33-3-a
Replace defective floor covering to provide a surface easily cleanable and impervious to water.

Bathroom

- 140. 275-53 Replace defective toilet tank cover.
- 141. 275-33-3-a
 Repair and repaint water damaged ceiling plaster.

Unit:#5 First Floor

Sleeping Room

- 142. 275-33-3-a
 Replace defective ceiling tile. Water damaged tiles.
- 143. 275-33-3
 Repair or replace defective baseboards.
- 144. 275-33-3-a
 Replace or remove defective floor covering. By radiator.

Unit:#2 First Floor

Sleeping Room

- 145. 275-33-3-a
 Replace defective ceiling tile.
- 146. 275-33-3-a Replace or remove defective floor covering. By door.

Second Floor Storage room south of room #36

147. 275-33-3-a Replace defective ceiling tile.

Serial #: 004977173 Inspection Date: April 15, 2005

1570-1572 W NATIONAL AV

- 148. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.
- 149. 275-33-3-a Replace missing ceiling tile.
- 150. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)
- 151. 275-33-3-a Replace or remove defective floor covering.
- 152. 275-32-4-a Restore window to a weathertight condition.

Second Floor Common Bathroom 2nd floor center

Bathroom

- 153. 275-62-2 Replace defective electrical switch.
- 154. 275-33-3-a Replace defective ceiling tile.
- 155. 275-33-3-a
 Replace defective floor covering to provide a surface easily cleanable and impervious to water.
- 156. 275-33-3-a
 Paint wall to provide an easily cleanable surface. (Wall is to be properly prepared and paint applied in a workmanlike manner.)
- 157. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)
- 158. 275-33-3 Replace missing door.
- 159. 275-32-4-a Repair or replace defective window sash. (sash cords missing).
- 160. 275-20(1.5 HFS 195.05(6)(d) Provide soap, single-service towels or other approved means of drying hands.
- 161. 275-32 (3)
 Repair or replace defective toilet compartment partitions.

Unit:#36 Second Floor

Sleeping Room

- 162. 275-33-3-a
 Repair or replace defective wall covering to provide an easily cleanable surface.
- 163. 275-33-3-a Replace missing ceiling tile.
- 164. 275-33-6
 Repair or replace defective door hardware.
- 165. 275-32-4-a Restore window to a weathertight condition.
- 166. 275-32-4-a
 Repair or replace defective window sash.
- 167. 275-42-4
 Provide at least one window screen for each habitable room. (sash cords missing).
- 168. 275-34-3 Provide storm windows for each habitable room.
- 169. 275-32-4-a Replace broken window pane.
- 170. 275-21-4 Discontinue the preparations of food in the hoel rooms.
- 171. 275-20-7-n Lack of proper required room separation.

Unit:#32 Second Floor

- 172. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)
- 173. 275-32-4-a
 Repair or replace defective window sash. (sash cord missing).
- 174. 275-34-3 Provide storm windows for each habitable room.
- 175. 275-20-7-n Lack of proper required room separation.

Unit:#28 Second Floor

Sleeping Room

- 176. 275-33-3-a
 Repair plaster on ceiling and paint to provide a cleanable surface. (Repair and painting to be done in a workmanlike manner.)
- 177. 275-33-3-a Replace or remove defective floor covering.
- 178. 275-32-4-a Repair or replace defective window sash. (Sash cords missing).
- 179. 275-20-7-n Lack of proper required room separation.

Unit:#26 Second Floor

Sleeping Room

- 180. 275-33-3-a
 Repair defective plaster wall and paint so as to provide a cleanable surface. Wall must be properly prepared and repair and painting done in a workmanlike manner.
- 181. 275-33-3-a Replace or remove defective floor covering.
- 182. 275-32-4-a
 Repair or replace defective window sash. (Sash cords missing).
- 183. 275-33-3-a
 Repair defective plaster in closet and paint. (Repair and painting to be done in a workmanlike manner.)
- 184. 275-20-7-n Lack of proper required room separation.

Unit:#24 Second Floor

- 185. 275-62-3
 A recent inspection indicated electrical wiring improperly installed or defective that is potentially hazardous. Restore to a safe condition. (Secure outlet box to the conduit).
- 186. 275-33-3-a
 Replace defective ceiling tile.
- 187. 275-33-1
 Repair or replace defective wall molding trim.
- 188. 275-32-4-a
 Repair or replace defective window sash. (Sash cords missing).

Serial #: 004977173 Inspection Date: April 15, 2005

- 189. 275-32-4-a Replace broken window pane.
- 190. 275-20-7-n Lack of proper required room separation.

Licensed Premise

- 191. 200-11-2
 Right of entry. You are hereby ordered to permit the inspection of your property for the purpose of checking for code violations that may affect the health and safety of the public. Failure to do so may generate a Special Inspection Warrant. Rooms #3, 4,30, 49, storage room on the 2nd floor, and the office in the basement.
- 192. 275-20-9-a Provide approved flame resistant mattress or approved flame resistant mattress cover. All units.
- 193. 275-20-10
 Provide shades or drapes for rooming unit or second class dwelling unit. All units should be checked to repair or replace any defective blinds and install shades or drapes where none are in place.
- 194. 275-20-7-n
 Lack of proper required room separation. Doors shall be of 1.5 inch solid wood, or the door shall be covered with 16 gauge sheet metal screwed or otherwise securely fastened to the door, or the equivelent of 1/2 inch plywood or hardboard secured to the existing door, or a labeled 20 minute door and a door frame with a munimum reating of 20 minutes. All door panels shall be tightly fitted to the frames and shall be maintained in a structurally sound condition.

For any additional information, please phone Thomas Cleary at [414]-286-5910 between the hours of 7:00am-10:00am or 3:15-3:45pm Monday through Friday.

Per Commissioner of Neighborhood Services By-

Thomas Cleary

FAILURE TO COMPLY Failure to comply with the order as Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

TENANT RENT WITHHOLDING
Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

1570-1572 W NATIONAL AV

REINSPECTION FEES

In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221, Please be aware that there is a fee required when filing an appeal.

LEAD PAINT CAUTION

Defective painted surfaces were noted on this inspection. Lead based paint was commonly used in buildings built prior to 1978 and precautions must be taken when renovating painted surfaces in such buildings. For information regarding lead safe repair practices, contact the Milwaukee Health Department at 286-0387.

RIGHT TO APPEAL

You may file an appeal within 20 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission within 20 days of service of this order. If service of this order is made by mail, the appeal shall be received within 30 days or by the compliance date plus 5 days, not to exceed 30 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filling this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

Violations of Chapter 295 of the Milwaukee Code of Ordinances must be appealed to the Board of Zoning Appeals, 809 N. Broadway, 1st floor, Milwaukee, Wisconsin 53202, phone 414-286-2501. All appeal applications must include the required information outlined in sec. 295-311-6.

TRADUCCION EN ESPAÑOL

Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

DEAN W STANLEY - PREFERRED CONTACT, 2627-N RICHMOND ST, CHICAGO IL 60647

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Plumbing Section 841 N. Broadway Milwaukee, WI 53202

DEPARTMENT COPY

Serial #: 004977961 Inspection Date: April 15, 2005 Section ID#: COMP #6/05 Letter Date: April 19, 2005 by: Daniel Zoladkiewicz Phone: [414]-286-8218 District #: 808 CT: 157

hotl-com

Recipients:
MILWAUKEE PARKWAY LLC, NATIONAL REGISTERED AGENTS, INC R/A, 2627 N RICHMOND, CHICAGO, IL 60647
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, INC R/A, 901 S WHITNEY WAY, MADISON, WI 53711
NANCY NICHOLSON - OPERATOR, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 30 days of service of this order.

Wisconsin Statutes Section 145.06 ALL PLUMBING WORK MUST BE CORRECTED BY A LICENSED MASTER PLUMBER. Section 225-3 Milwaukee Code of Ordinances A PLUMBING PERMIT IS REQUIRED FOR ALL PLUMBING WORK.

Violations

General

1. 225-3-1&4 Obtain a proper plumbing permit for all violations except for those in which "permit is not required" is so indicated.

Basement

- 225-01, Comm 82.21(2)(a)(f), Comm 82.41 Install an approved backflow protection device serving the condenser and laundry tray.
- 225-01, Comm 82.21(2)(i), Comm 82.30(4)(e) Properly seal the unused drain, waste and vent connections in building with approved materials.
- 4. 225-01, Comm 82.40(8)(f) Install an approved water hammer arrestor serving the clothes washer.

OFFICIAL NOTICE OF VIOLATION

The City of Milwaukee - Department of Neighborhood Services

- 5. 225-33-5 Install an approved vent or flue pipe serving the water heater.(At chimney) (Permit is not required.)
- 6. 225-01, Comm 82.21(2)(a)(f), Comm 82.40 Repair or replace the defective water distribution piping. (In boiler room)

First Floor

- 7. 225-01, Comm 82.40(8)(g) Install an approved thermostatic mixing valve or an individually controlled pressure balanced mixing valve serving the shower. (Common bathroom and manager bathroom)
- 8. 225-01, Comm 82.21(2)(a)(f) Repair the defective faucet serving the lavatory. (Common bathroom) (Permit is not required.)

Second Floor

- 9. 225-01, Comm 82.32 Install an approved trap serving the lavatory. (South bathroom)
- 10. 225-01, Comm 82.21(2)(a)(f), Comm 82.30(4)(e) Properly seal the open waste connection allowing sewer gas to enter the building. (Lavatories in rooms #21, 27, 33, 35, and 37)
- 11. 225-01, Comm 82.40(8)(g) Install an approved thermostatic mixing valve or an individually controlled pressure balanced mixing valve serving the 3 showers.
- 12. 225-01, Comm 84.20(4) Properly secure, support or reset the water closet. (North bathroom)
- 13. 225-01, Comm 84.20(5)(m) Install an approved water closet seat. (Permit is not required.) (2 in north bathroom)

Third Floor

- 14. 225-01, Comm 82.21(2)(a)(f) Remove stoppage from drain, waste and vent lines. (Permit is not required.) (Lavatory in south bathroom)
- 15. 225-01, Comm 82.21(2)(a)(f), Comm 82.30(4)(e) Properly seal the open waste connection allowing sewer gas to enter the building. (Lavatories in rooms #45, 47, 51, 53, and 59)
- 16. 225-01, Comm 82.40(8)(g) Install an approved thermostatic mixing valve or an individually controlled pressure balanced mixing valve serving the 3 showers. (North and south bathrooms)
- 17. 225-01, Comm 82.41(2)(3), Comm 84.20(4)(b) Replace and properly install the faucet, ballcock, or the fill valve which is submerged and creating a cross connection serving the water closet. (South bathroom)
- 18. 225-01, Comm 84.20(4) Properly secure, support or reset the water closet. (North bathroom) (Fix on wood blocks)

Serial #: 004977961 Inspection Date: April 15, 2005

For any additional information, please phone Daniel Zoladkiewicz at [414]-286-8218 between the hours of 7:00am-9:00am Monday through Friday.

Per Commissioner of Neighborhood Services By-

Daniel Zoladkiewicz

FAILURE TO COMPLY Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

RIGHT TO APPEAL You may file an appeal within 20 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission within 20 days of service of this order. If service of this order is made by mail, the appeal shall be received within 30 days or by the compliance date plus 5 days, not to exceed 30 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

TENANT RENT WITHHOLDING Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

REINSPECTION FEES
In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filing an appeal.

RETROACTIVITY RULE In accordance with Section 225-02, Comm 82.21, 82.30, 82.31 and 82.41 shall apply retroactively if upon inspection of any part of an existing plumbing system a condition is identified that tends to create a potential health hazard.

TRADUCCION EN ESPAÑOL Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Construction Section 841 N. Broadway Milwaukee, WI 53202

DEPARTMENT COPY

Serial #: 004980001 Inspection Date: April 15, 2005 District #: 608 CT: 157

hotl-com

Recipients:
MILWAUKEE PARKWAY LLC, NATIONAL REGISTERED AGENTS, INC.-REG AGENT, 2627 N RICHMOND,
CHICAGO, IL 60647-0000
MILWAUKEE PARKWAY, LLC, ATTN: NATIONAL REGISTERED AGENTS, 901 S WHITNEY WAY, MADISON
WI 53711
DEAN W STANLEY, 2627-N RICHMOND ST, CHICAGO IL 60647
NANCY NICHOLSON, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 30 days of service of this order.

- 1. 275-61-1-a Repair leaks in boiler system.
- 275-32-3-f
 Replace defective smoke pipe on furnace or boiler and seal to chimney.
- 275-61-1-b
 You are hereby ordered to maintain a temperature of at least 67 degrees within each dwelling unit 24 hours each day as long as unit remains occupied.
- 214-3
 IFC 703.1 Repair holes in furnace or boiler room fire retarding enclosure.
- 5. 275-32-3-f
 Repair defective chimney in basement.
- 6. 275-32-3-f Seal chimney opening in basement.
- 7. 275-32-3-f
 Replace the missing chimney cleanout cover.
- 223-3-5
 Repair or replace unsafe and hazardous and maintain in a safe condition. Repair floor support for individual room radiatiors on all floors.

OFFICIAL NOTICE OF VIOLATION

The City of Milwaukee - Department of Neighborhood Services

Serial #: 004980001 Inspection Date: April 15, 2005

RIGHT TO APPEAL

You may file an appeal within 20 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission within 20 days of service of this order. If service of this order is made by mail, the appeal shall be received within 30 days or by the compliance date plus 5 days, not to exceed 30 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

Violations of Chapter 295 of the Milwaukee Code of Ordinances must be appealed to the Board of Zoning Appeals, 809 N. Broadway, 1st floor, Milwaukee, Wisconsin 53202, phone 414-286-2501. All appeal applications must include the required information outlined in sec. 295-311-6.

TRADUCCION EN ESPAÑOL

Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

- 3 -

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE **DEPARTMENT OF NEIGHBORHOOD SERVICES**

Construction Section 841 N. Broadway Milwaukee, WI 53202

DEPARTMENT COPY

Serial #: 004980002 Inspection Date: April 15, 2005

District #: 608 CT: 157

hoti-com

Recipients: MILWAUKEE PARKWAY LLC, NATIONAL REGISTERED AGENTS, INC.-REG AGENT, 2627 N RICHMOND, CHICAGO, IL 60647-0000 MILWAUKEE PARKWAY, LLC, ATTN: NATIONAL REGISTERED AGENTS, 901 S WHITNEY WAY, MADISON WI 53711 DEAN W STANLEY, 2627-N RICHMOND ST, CHICAGO IL 60647 NANCY NICHOLSON, 1570 W NATIONAL AV, MILWAUKEE, WI 53204

Re: 1570-1572 W NATIONAL AV

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed emergency conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below.

The emergency repairs must be completed within 24 hours of service of this order or contractors will be hired under authority granted in the essential service ordinance 200-21, or the rent withholding ordinance 200-22.

Please call inspector when the violation is corrected.

1. 275-61-2 Defective heating system. Restore to operating condition.

For any additional information, please phone Greg Eighme at [414]-286-2537 between the hours of 7:00am-9:00am Monday through Friday.

Per Commissioner of Neighborhood Services By-

Greg Eighme

FAILURE TO COMPLY

Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$150 to \$10,000 in the manner provided in Section 200-19.

TENANT RENT WITHHOLDING Uncorrected violations on properties may allow tenants to deposit their rent in an escrow account in the Department of Neighborhood Services under Section 200-22. The Commissioner may withdraw monies from such escrow accounts to make repairs to protect the health, safety and welfare of tenants.

OFFICIAL NOTICE OF VIOLATION

The City of Milwaukee - Department of Neighborhood Services

REINSPECTION FEES

In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filing an appeal.

RIGHT TO APPEAL

You may file an appeal within 1 days. The Milwaukee Code of Ordinances requires that a written appeal of this order be received by the Standards and Appeals Commission by the compliance date. If service of this order is made by mail, the appeal shall be received by the compliance date plus 5 days. For further information, contact the Code Appeals Secretary, Municipal Building, 1st Floor, 841 N. Broadway, Milwaukee, Wisconsin 53202, phone 414-286-2503. There is a fee for filing this application. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

Violations of Chapter 295 of the Milwaukee Code of Ordinances must be appealed to the Board of Zoning Appeals, 809 N. Broadway, 1st floor, Milwaukee, Wisconsin 53202, phone 414-286-2501. All appeal applications must include the required information outlined in sec. 295-311-6.

TRADUCCION EN ESPAÑOL Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.

INSPECTION REPORT AND ORDER TO CORRECT CONDITION

CITY OF MILWAUKEE DEPARTMENT OF NEIGHBORHOOD SERVICES

Environmental Health Section 4001 S. 6th St. Milwaukee, WI 53221

DEPARTMENT COPY

Serial #: 004983451 Inspection Date: April 15, 2005 District #: 425 CT: 157

hoti-per

Recipients:
DEAN W STANLEY, 2627-N RICHMOND ST, CHICAGO IL 60647
PARKAY HOTEL, ATTN: NANCY NICHOLSON, 1570 W NATIONAL AVE, MILWAUKEE, WI 53204
MILWAUKEE PARKWAY, LLC, NATIONAL REGISTERED AGENTS, INC-RA, 901 SOUTH WHITNEY WAY,
MADISON, WI 53711
NATIONAL REGISTERED AGENTS, INC, DANE COUNTY TITLE COMPANY INC-RA, 901 S WHITNEY,
MADISON, WI 53711

Re: 1570-1572 W NATIONAL AV

AKA:Parkay Hotel

Taxkey #: 433-9991-200

A recent inspection of the premises at the above address revealed conditions that violate the Milwaukee Code of Ordinances. You are hereby ordered to correct each violation listed below within 21 days of service of this order.

- 79-12
 Remove and properly dispose of all litter, refuse and debris from the premises.
 Maintain the premises free of litter, refuse and debris in such a manner that it does not violate this section.
- 2. 275-62-3
 Discontinue the use of extension cords as a substitute for proper wiring. Extension cords noted in basement, including laundry room and rooms 6, 25, and 35.
- 275-23-11
 Provide proper numbers for all rooming units.
- 4. 214-3
 IFC 310 Replace missing fire exit sign. Third floor hallway has illegal exit sign, replace with acceptable exit sign.
- 214-3
 IFC 906.7 Fire extinguisher must be securely mounted in accordance with this code. Extinguisher in office must be mounted on wall.
- 6. 275-33-5-a
 Repair or replace defective stair handrail. Loose handrail middle stairway, third floor. Loose handrail first floor stairway to basement.

OFFICIAL NOTICE OF VIOLATION

- 7. 275-33-3-b
 Repair defective bathroom floor and provide a surface impervious to water. Tile damaged by doorway in multiple bathrooms.
- 8. 275-33-6 Replace missing door knob. Room 59.
- 9. 275-33-3 Replace missing door. Second floor bathroom.
- 10. 275-81-1-a
 Restore dwelling unit to clean and sanitary condition.
- 11. IFC 404.2 Emergency Plan and Preparedness: Submit a copy of hotel emergency preparedness plan to the Department of Neighborhood Services, 4001 S 6th St, Second Floor, Milwaukee, WI 53221, for review.
- 12. Admin 254.83
 Room Rates Posted. Maximum room rates must be posted in all rooms. Rooms 46, 48, 50, 28, and 29 did not have room rates.
- HFS 195.09 (1)
 Emergency Route Orientation: All guest rooms shall have an emergency route diagram that is specific to that room, posted on the inside door, and properly orientated.
- 14. HFS 195.05(6)(d)
 Soap and Towels: Soap, single-service towels, or other approved means of drying hands shall be provided in each toliet room.
- 15. HFS 195.05(6)(e)
 Room Designations: The door leading into each toliet room shall be marked to identify whether it is for men or women.
- 16. HFS 195.09(2)(e) Window Screens: All windows that can be opened in sleeping rooms shall be screened, using 16 mesh or finer material.
- 17. HFS 195.10(2)
 Room Maintenance: The floors, walls, and ceilings of all rooms shall be maintained in a clean and sanitary condition and in a good state of repair. Room 59, damaged ceiling tiles. Second floor bathroom, damaged ceiling tiles. First floor bathroom, damaged ceiling. Room 33 is not in a clean and sanitary condition due to guest storage.
- 18. MCO 214-27
 Smoke Detector Maintenance: Maintain smoke detectors in all guest rooms.
 Smoke detectors non-functional or missing in rooms 50,51,33,28, and 06.
- MCO 68-01 Provide toliet paper in all bathrooms.
- 20. HFS 195.10
 Maintenance: Third floor women's bathroom stall door does not clear toliet when opened. Loose ceiling light fixture in hallway by room 56.

Serial #: 004983451 Inspection Date: April 15, 2005

1570-1572 W NATIONAL AV

21. Admin 254.76 Smoking Negligence Posted: Notice To Guests Penalty For Careless Smoking Habits shall be posted in all guest rooms.

For any additional information, please phone Corey Bender at [414]-286-2610 between the hours of 7:30am-9:00am Monday through Friday.

Per Commissioner of Neighborhood Services By-

Corey Bender

REINSPECTION FEES
In accordance with Section 200-33-48, a fee may be charged for any reinspection, except no fee shall be charged for the final reinspection when compliance is recorded. The fee is \$50 for the first reinspection, \$75 for the second, \$150 for the third, and \$300 for the fourth and all subsequent reinspections. Reinspection fees shall be a lien upon the real estate where the reinspections were made and shall be assessed and collected as a special tax. If you wish to contest the assessment of a reinspection fee, contact the inspector, and, if necessary, the inspector's supervisor. If no agreement is reached, an appeal form will be mailed to you, which you can complete and send to the City's Administrative Review Appeals Board. Any question regarding the actual appeal process, please contact the Administrative Review Appeals Board at (414) 286-2221. Please be aware that there is a fee required when filing an appeal.

FAILURE TO COMPLY Failure to correct the violations noted herein within the time set, or failure to comply with the order as modified by an appellate board and maintain compliance, may subject you to prosecution and to daily penalties of \$50 to \$10,000 in the manner provided in Section 61.

RIGHT TO APPEAL
This order may be appealed provided an application for appeal is received within 20 days of service. For further information, contact 286-8674 to obtain information about your appeal rights. Failure to appeal an order issued by the Department shall create a rebuttable presumption that a violation existed on the date of the issuance of the order (200-17-8).

TAX LIEN If not corrected within the compliance period, the nuisance may be corrected by the City and the cost thereof will be charged as a tax lien against the property.

TRADUCCION EN ESPAÑOL Si Ud. necesita ayuda para la traducción de esta información, comuníquese con el 'Centro Hispano' Council for the Spanish Speaking, Inc., 614 W. National Avenue, Milwaukee, WI 53204. Teléfono: (414)384-3700.