	SCOPE OF WORK	Scope Date:				
	Yvonne Bell Gooden - 2576 N Grant BI Tel: (414) 449-2112	Sept. 8th, 2	025			
	Rehab Specialist: John Burke					
	Loan Officer: Sam Overton	Program:				
	First inspection date: 9/4/2025 Prior version dates:	STROM	IG Homes			
	Both the "Rehabilitation and Technical Specifications and Performance Standard for the City of Milwaukee - February, 2006" and the "NIDC Addendum to Specifications," dated 8/23/07 & 5/13/08, are incorporated into this scope by reference. These items provide an outline of materials requirements & performance expectations. Updated copies can be obtained from NIDC @ 809 N Broadway-3rd Flr.					
	Lead Related Work: Any task that a disturbs previously painted surface shall be performed by properly certified personnel and follow the State of Wisconsin Department of Health Services Administrative Code Chapter DHS 163 regarding the certification for the identification, removal and reduction of lead-based paint hazards (Pb).					
	And, if applicable: O YES NO					
	Any task that disturbs a previously painted surface requires Milwaukee Health Department notification (Pb-N). Window rep properly certified personnel and requires a Milwaukee Health Department Permit (Pb-A).	lacement shall be	e performed by			
	Miscellaneous: The contractor is responsible to field verify all measurements, the amount of materials needed, and the number any item in this scope calls for a certain manufacturer, model number, or approved equivalent of a particular item, and the both NIDC and the owner must approve the substitution in writing as a part of the contract.		- 1			
Line #	Scope of Work Item	Code	Estimate			
	HISTORIC PRESERVATION	,				
1	<u>Historic Preservation Note:</u> A.) This residence is in the North Grant Boulevard Historic District. All exterior repairs and material installations are to be consistent with the requirements of the district, and match the original design of the property. This scope of work has been approved by the Milwaukee Historic Preservation Commission (HPC) and any changes to the indicated repairs in this scope, will need re-approval by the commission. Therefore, the contractor and homeowner are not to make any changes without first consulting the Rehab Specialist for this project. B.) The contractor and owner shall work together to provide any material samples to the HPC as necessary for compliance with the Certificate of Appropriateness, prior to commencing the repair.	Note				
			NOTE			
	HOUSE					
2	Roof Replacement: Tear off the existing shingles and replace the entire roof - all roof surfaces; main roof, entry porches, etc. Install 'W' flashing at all valleys. The roof currently has a base layer of OSB sheathing. Repair any damaged OSB/decking areas, due to water leakage. Install new flashing at the dormers. Provide ice and water shield a minimum of 3 feet wide at all roof edges, and valleys, install synthetic roofing felts, and metal drip and apron flashing. Install new roof vents per code. Provide all necessary flashings, 3-tab historic shingles with a minimum 25 year warranty. Color is to be dark, with minimal color contrast and minimal shadow lines. Recommendations; 1.) Owens Corning "Supreme", or 2.) Certainteed "XT-25", or 3.) GAF "Royal Sovereign". The specific color and material selection shall be approved by the HPC.	CV				
			\$18,000			

4 Built-In Box Gutters: The existing gutters consist of EPDM membranes over the existing deteriorated metal box gutters. Remove the existing gutter system. Repair all underlying structural members, lookouts, and finish boards. Correct any sagging roof edges. Install new metal "built in" box gutters, flashed underneath the new roof system, and over the edge of outer roof fascia. Apply appropriate sealant at all joints and seams, color matched to the gutter. Re-connect to the existing downspouts. 5 Soffit and Fascia Repairs: A.) Remove and replace all 1x construction grade-pine boards and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing. Paint the unpainted surface, at one soffit location. Colors per owner. 55,500 6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new cof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas;				
4 Built-In Box Gutters: The existing gutters consist of EPDM membranes over the existing deteriorated metal box gutters. Remove the existing gutter system. Repair all underlying structural members, lookouts, and finish boards. Correct any sagging roof edges. Install new metal "built in" box gutters, flashed underneath the new roof system, and over the edge of outer roof fascia. Apply appropriate sealant at all joints and seams, color matched to the gutter. Re-connect to the existing downspouts. 5 Soffit and Fascia Repairs: A.) Remove and replace all 1x construction grade-pine boards and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing. Paint the unpainted surface, at one soffit location. Colors per owner. 55,500 6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new cof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas;	3	warranty, or provide all information and assistance necessary (material purchases, date of purchase, warranty forms/application etc.) for the owner to apply for the shingle warranty. The contractor is to install the required products as necessary to establish the manufacturers warranty; starter strips, flashings, underlayment, roof vents, etc. All	NOTE	
deteriorated metal box gutters. Remove the existing gutter system. Repair all underlying structural members, lookouts, and finish boards. Correct any sagging roof edges. Install new metal "built in" box gutters, flashed underneath the new roof system, and over the edge of outer roof fascia. Apply appropriate sealant at all joints and seams, color matched to the gutter. Re-connect to the existing downspouts. 5 Soffit and Fascia Repairs: A.) Remove and replace all 1x construction grade-pine boards and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing. Paint the unpainted surface, at one soffit location. Colors per owner. 6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 9 Plaster and Paint Repairs: Remove loose plaster in the basement, first floor, second floor. CV All alarms: Install a combination smoke/C		materials shall be installed according to manufacturers requirements.		\$150
Soffit and Fascia Repairs: A.) Remove and replace all 1x construction grade-pine boards and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing. Paint the unpainted surface, at one soffit location. Colors per owner. 6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. 10 INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 9 CFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground facility and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	4	deteriorated metal box gutters. Remove the existing gutter system. Repair all underlying structural members, lookouts, and finish boards. Correct any sagging roof edges. Install new metal "built in" box gutters, flashed underneath the new roof system, and over the edge of outer roof fascia. Apply appropriate sealant at all joints and seams,	,	\$8,000
and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing. Paint the unpainted surface, at one soffit location. Colors per owner. 55,500 6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; second floor North bedroom closet, and attic finished ceiling. 5550 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 6FCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and		Soffit and Eastin Popairs: A \ Pomovo and roplace all 1x construction grade pine heards	CV Db	70,000
6 Downspouts: Re-connect the gutters to the existing story inlets. Make any other repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. CV Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. All alarms shall be sealed battery, 10 year lithium ion units. 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	3	and replace with clear (select) boards. Repair or replace all damaged fascia and soffit boards. Apply paintable caulking at all gaps and cracks. Scrape, prime paint, and finish paint the entire fascia. B.) Paint the areas of soffit being repaired, to match existing.	CV, PD	
repairs to the existing downspouts as necessary. 7 Chimney Repairs: A.) Reflash the chimney with metal flashing color matched to the new roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. CV Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. All alarms shall be sealed battery, 10 year lithium ion units. 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and				\$5,500
roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content, color matched to the existing mortar. C.) Replace the broken chimney cap. 8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. All alarms shall be sealed battery, 10 year lithium ion units. \$550 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	6		CV, Pb	\$500
8 Rear Entry Porch Canopy: A.) Remove and replace the roof structural components (joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 5550 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	7	roof. B.) Tuck point the chimney with Type "N" soft mortar, with a high lime content,	CV	\$4,000
(joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and paint to match existing. C.) Note: this porch is to receive new shingled roofing, per Work Item #2. INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. All alarms shall be sealed battery, 10 year lithium ion units. \$550 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and			DEDIAIT	34,000
INTERIOR GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. \$550 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. \$225 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	0	(joists, soffit supports, etc.) and roof decking, but retain bottom ceiling and soffits. Install new perimeter trim boards, to match the historic profile. B.) Re-flash the roof into the masonry, with metal step flashing following the mortar joints. C.) Prep and	CV	
GENERAL 9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and		Item #2.		\$3,500
9 Plaster and Paint Repairs: Remove loose plaster and paint at all areas which possibly contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and		INTERIOR	·	
contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas; Second floor North bedroom closet, and attic finished ceiling. 10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. CV All alarms shall be sealed battery, 10 year lithium ion units. 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and		GENERAL		
10 Alarms: Install a combination smoke/CO alarm in the basement, first floor, second floor. All alarms shall be sealed battery, 10 year lithium ion units. \$225 11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	9	contribute to lead (Pb) contamination. All patches are to match the existing finish of the adjacent surfaces. Spot prime paint and finish paint the patched areas. Noted Areas;	CV, Pb	ĊĘĘĄ
All alarms shall be sealed battery, 10 year lithium ion units. Secondary Sealed battery, 10 year lithium ion units. GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	10		CV	\$550
11 GFCI Receptacles: Replace the existing electrical receptacles at wet areas with ground fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	10		CV	¢າາ⊏
fault protected receptacles at the following locations; one at the kitchen sink counter, and one in the 2nd floor bathroom. Make all necessary corrections to the wiring and	11		DERMIT	رععد
		fault protected receptacles at the following locations; one at the kitchen sink counter,	•	
boxes at these locations, and instance over places.		boxes at these locations, and install cover plates.		\$400

	owner signature		
	owner signature	Date.	
	Owner Approval:	Date:	
	Attachments: none		
	Alternate Scope Es	stimate:	\$12,000
	ALTERNATE BID SUMMARY		
	entire system to ensure functionality.	PERMIT	\$12,000
ALT-1	Boiler Replacement: Replace the existing boiler. Make any repairs necessary for the	CV,	
	ALTERNATE WORK ITEMS		
	Scope Es	imate:	\$43,275
	SE BID SUMMARY (Note: Contractors are to provide line item estimates with their bid.) Scope Estimate:		642.277
	thumb turn deadbolt.		\$125
16	Double Keyed Deadbolt: Replace the double keyed deadbolt at the rear entry with a	CV	
	FIRST FLOOR		7-20
15	Laundry Tub Faucet: Replace the laundry tub faucet.	CV	\$225
	of the rear entry. Correct all wiring and box issues. BASEMENT		3400
	area, and at the rear entry - at the top of the basement stair, and at the exterior canopy		\$400
14	<u>Light Fixtures - Electrical Repairs:</u> Install a new light fixture in the basement laundry	CV	
	Replace with BX armored cable wiring, or protect by placing it within conduit.		\$200
	damaged where it is exposed under the kitchen sink. Correct to a code compliant state;	PERMIT	
13	<u>Dishwasher Electrical:</u> NM wiring has been used for the dishwasher, and can be	CV,	7 -/- 30
	floor receptacle, (1) switch at kitcen sink counter, and (1) switch at 3rd floor room.		\$1,500
	plates. Locations; (3) switches at base of 2nd floor stair, (3) switches at rear entry, (1) 1st		
	wiring and boxes at these locations, replace old switches/receptacles and install cover		
	fixture boxes, and/or the fixture is damaged. Make all necessary corrections to the		
	switches which do not have cover plates, appear to be set inappropriately within their	CV	
12	Receptacles/Switches - Electrical Repairs: There are multiple electrical receptacles and	PERMIT,	