



Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

Property

2721 N. LAKE DR. N. Lake Drive HD

Description of work

Masonry:

Portico:

- Tuckpoint throughout
- Replace bricks where necessary - will match as closely as possible
- Repair rubber membrane above portico to prevent additional water intrusion, address any gutter problems with drainage from roof of portico
- Remove plastic beadboard from underside of portico. Repair/replace original wood ceiling.

House:

- Tuckpoint throughout
- Brick repair - particularly to north and west sides
- Remove failing caulk around decorative windows and replace to prevent additional water intrusion
- Repair decorative concrete - esp around windows and on Juliet balconies
- Gently power wash house to remove vines

Extensive “before” photos are on file and can be found in Legistar ccf 210937

Date issued

10/5/2021

PTS ID 115196 COA: MASONRY & RELATED REPAIRS

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

Abrasive cleaning methods are prohibited on historic buildings by Wisconsin state law. Exceptions can only be granted in writing by the Wisconsin Historical Society. Chemical and power-washing are acceptable methods of cleaning that the city can approve. Pressure at the nozzle is not to exceed 800psi, 400-600psi is usually adequate for cleaning, though it may take more time and more passes than higher pressures. **Pressure washing is to be**

conducted ONLY with fan tips with a spread of 15-50 degrees, maximum 800psi at the tip, flow rate less than 8gpm, and from a distance from the surface of a minimum of 12" inches.

New mortar must match the original mortar in terms of color, texture, grain size, joint width, and joint finish/profile. The compressive strength of the repointing mortar shall be equal or less than the compressive strength of the original mortar and surrounding brick or stone. The replacement mortar shall contain approximately the same ingredient proportions of the original mortar. Mortar that is too hard is subject to premature failure and could damage the masonry. See the city's books As Good As New or Good for Business, Masonry Chapters, for more information. In most cases, this means a lime mortar with natural hydraulic cement rather than Portland cement. No joint of a width less than 3/8" may be cleaned of damaged/decomposed mortar with power disc grinders. No over-cutting of the joints is permitted. Remove decomposed mortar back into the wall 2.5 times the height of the joint before repointing. When installing new flashing at a masonry feature, the flashing must be stepped or cut into the mortar joints. The bricks may not be cut to install flashing at an angle.

New brick must match as closely as possible the color texture, size, and finish of the original brick.

A sample panel of brick and mortar must be reviewed and approved by HPC staff prior to general installation of the material.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Dean Doerrfeld of the Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: Dean.Doerrfeld@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.milwaukee.gov/build, or call (414) 286-8210.



City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Nik Kovac, Contractor , Inspector Paul Wolfgramm (286-2590)