Driveway condition 933-35 N. 31 St. Supplement to application for Certificate of Appropriateness



Photo above shows center section of driveway that will be replaced with concrete.



Photo at left shows section of driveway closest to the garage and the center section (circled), which will be replaced. Photo at right shows section of driveway closest to N. 31<sup>st</sup> St. Retaining walls along this portion of driveway will not be affected.