

DATE: September 29, 2025

TO: City Clerk

FROM: Julian Woodruff

RE: Repair Claim from Manhole Cover Damage to Vehicle

CITY OF MILWAUKEE  
2025 OCT -2 P 1:12  
CITY CLERK'S OFFICE

August 4th approximately 6:43pm

I was heading East on Capitol Drive, near 23<sup>rd</sup> Street. The sewer cover was spinning around on the street like a quarter. This is a major hazard and dangerous. The manhole cover spun into my passenger side lower front causing damage to the bumper, wheel well liner, tire and wheel rim. The damage occurred at 23<sup>rd</sup> Street and Capitol Drive. I parked at 22<sup>nd</sup> Street and Capitol to survey the damage take pictures. I expect to have my vehicle repaired and the cost covered by the city.

Attached are two estimates by local body shops. The incident occurred on 8/4/2025

Respectfully,




Julian Woodruff


9899 S Glenmoor Court

Oak Creek, WI 53154-5037

(414)687-8092

WoodruffJulian92@gmail.com





**Royal Auto Body LLC**  
 2775 S. Chase Avenue  
 Milwaukee, WI 53207  
 Business Phone: (414) 350-3777  
 ukranger7@hotmail.com

**Estimate**  
 Est # 43  
 ID # 16331303  
 Estimator: Ivan Zaiats

**Vehicle Info**

2021 Honda -Passport EX-L  
 5FN9F8H54MB033901  
 Ext. Color: BLACK  
 License: AJV-5050 WI  
 Mileage In/Out: 97830.0/0.0  
 Body Type: 4 Door Utility  
 Engine: 3.5L 6 Cyl Gas Injected  
 Drive Type: AWD  
 Production Date: AUG-2021

**Owner**

JULIAN WOODRUFF  
 (414) 687-8092  
 OAK CREEK,

**Insurance Company**

Inspection Date: 09/01/2025

**Shop Info**

Tax ID: 41-2128791

Oper	Description	Part Number	Price	Labor
<b>FRONT BUMPER</b>				
1	R&I FRONT BUMPER COVER ASSY (FRT BUMPER COVER)			Included
2	Replace R FRT BUMPER SIDE COVER	HO1017100C	\$202.00	Included 1.2 hrs. Paint panel 0.5 hrs. Refinish
3	Replace FRT BUMPER COVER	HO1015121C	\$187.00	Included
4	Overhaul O/H FRONT BUMPER COVER ASSY (INCLUDES R&I) (FRT BUMPER COVER ASSY)			4.4 hrs. Body
5	Replace R FRT BUMPER COVER GARNISH	HO1039149	\$35.00	Included
6	Replace R FRT BUMPER COVER GARNISH	HO1047110	\$52.00	Included
<b>GRILLE</b>				
7	Replace GRILLE	HO1200250	\$89.00	0.4 hrs. Body
<b>FRONT LAMPS</b>				
8	Replace R FRT COMBINATION LAMP ASSEMBLY	HO2503172	\$927.00	0.5 hrs. Body
9	Check/Adjust AIM LAMPS (HEADLAMPS)			0.4 hrs. Body
10	Replace R FRT SIGNAL LAMP HOUSING	71116-TGS-A00	\$20.30	0.4 hrs. Body
11	Replace R FRT SIGNAL LAMP ASSEMBLY	HO2531131C	\$67.00	Included
12	Replace R FRT FOG LAMP	HO2593144	\$221.00	Included
13	Check/Adjust AIM FOG LAMPS			0.4 hrs. Body
<b>FRONT FENDER</b>				
14	Replace R FENDER LINER	HO1249162C	\$79.00	0.4 hrs. Body
15	Replace R FENDER WHEEL OPENING MLDG	HO1291109C	\$50.00	0.3 hrs. Body
<b>FRONT INNER STRUCTURE</b>				
16	Repair FRT BODY RADIATOR SUPPORT -S			4 hrs. Body 2.5 hrs. Paint panel 1.5 hrs. Refinish 1 hrs. Clearcoat, 0.5 hrs. Edging
<b>WHEEL</b>				
17	Other INHOUSE REPAIR - ALLOY WHEEL	42700-TGS-A62	\$299.99	
18	R&I ALLOY WHEEL			0.3 hrs. Body
<b>OTHER</b>				
19	Other ADAS PRE-SCAN			0.5 hrs. Mechanical

		Final charge may vary, based on vehicle - Per Invoice		
20	Other	ADAS POST-SCAN		0.5 hrs. Mechanical
		Final charge may vary, based on vehicle - Per Invoice		
21	Replace	NEW TIRE 245/50/R20 CONTINENTAL ECO PLUS - DISCOUNT TIRE	Item #42630	\$290.40
22	Other	FOUR WHEEL ALIGNMENT SubletSublet		\$129.99
23	Other	HAZARDOUS WASTE REMOVAL SubletNontaxed		\$5.00
24	Replace	COVER CAR FOR OVERSPRAY		\$5.00 0.3 hrs. Body
25	Replace	CORROSION PROTECTION		\$15.00
26	Replace	FLEX ADDITIVE per bumper cover		\$15.00

## Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	11.8	\$76.00	\$896.80	✓
Body Supplies	11.8	\$56.00	\$660.80	✓
Clearcoat Labor	1.5	\$76.00	\$114.00	✓
Mechanical Labor	1.0	\$149.99	\$149.99	✓
Paint Labor	4.2	\$76.00	\$319.20	✓
Paint Supplies	5.7	\$56.00	\$319.20	✓
Aftermarket Parts			\$1,909.00	✓
Nontaxed			\$5.00	
OEM Parts			\$310.70	✓
Other Parts			\$334.99	✓
Sublet			\$129.99	
Taxable Amount			\$5,014.68	
Tax	7.9%		\$396.16	
Nontaxable Amount			\$134.99	
Grand Total			\$5,545.83	

## Part Source Vendors

Lines	Vendor	Email	Phone	Fax	Address
2, 3, 5, 6, 7, 8, 11, 12, 14, 15	KEYSTONE - MILWAUKEE, WI		(414) 463-1019	(414) 463-1217	9532 W.CARMEN AVENUE MILWAUKEE , WI 53225

**MEMO'S BODY SHOP LLC**  
 4319 W NORTH AVE,  
 MILWAUKEE, WISCONSIN 53208  
 (414)391-0742 | (414)943-2396  
 (414)509-4287 | Guillermobodyshop3@gmail.com

000565

NAME Julian Woodruff

ADDRESS \_\_\_\_\_

Email WoodruffJulian92@gmail.com

DATE 09/19/15  
 PHONE (414) 687-8092  
 DATE PROMISED \_\_\_\_\_

MAKE OF CAR	YEAR - MODEL	BODY TYPE	LICENSE NO.	SERIAL NO.	COLOR CODE	MILEAGE
HONDA	21" PASADENA	EX-L				

REPAIR	REPLACE	DESCRIPTION OF REPAIRS & REPLACEMENT	PARTS & MATERIAL	LABOR	REFINISHING
		R+R Lower bumper cover LKO	\$220		
		R+R R Fog lamp housing OEM	\$22		
		R+R R Fog lamp bezel OEM	\$45		
		R+R R Fog lamp OEM	\$325		
		R+R R Signal lamp OEM	\$85		
		R+R Trim moulding bezel OEM	\$73		
		R+R RF wheel opening moulding OEM	\$70		
		R+R wheel 20in OEM	\$663		
		R+R Tire 245/50/R20	\$213		
		↳ Cross Contact Continental			
		Mount & Balance	\$30		
		Repair Bumper end cap 2.0hr	\$18	\$140	
		Repair R Fender 1.0hr		\$70	
		Repair Core support 3.0hr	\$25	\$210	
		↳ Spot Refinish	\$30	\$35	
		Paint & Refinish	\$85	\$546	
		2 - wheel Alignment	\$125		
		<b>WORK SUB-LET</b>			
		<b>TOWING</b>			
		<b>TOTALS</b>			\$3030

**\$3,269**

THIS ESTIMATE IS BASED ON A VISUAL INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEGUN. AS WORN OR DAMAGED PARTS WHICH WERE NOT EVIDENT ON FIRST INSPECTION MAY BE UNCOVERED. THEREFORE THIS ESTIMATE DOES NOT COVER SUCH SITUATIONS. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS GOOD FOR A PERIOD OF 90 DAYS.

THIS WORK AUTHORIZED BY \_\_\_\_\_

Where State Law Requires Additional Qualifications of This Estimate The Proper Form Must Be Attached.

SALES TAX \$239  
 GRAND TOTAL \$3,269

**REPAIR ORDER AND ESTIMATE FORM**

