# Milwaukee Historic Preservation Commission November 7, 2022





If you wish to speak on an issue or have your opinion noted by the commission, please fill out a form at the door and hand it to us

## 1. 220754

Resolution relating to a Certificate of Appropriateness for window replacement on the lower levels at 1015 N. 9th Street, St. Benedict the Moor Roman Catholic Church, an individually designated historic property, for the Province of St. Joseph of the Capuchin Order...



St. Benedict the Moor Roman Catholic Church





St. Benedict the Moor 930 West State Street Milwaukee, Wisconsin

**EXTERIOR ELEVATION - EAST** 3/32" = 1'-0"







EAST ELEVATION OVERALL






TYPICAL EXISTING EAST WINDOW - INTERIOR




TYPICAL EAST WINDOW & DETAILS





SCOPE OF WINDOW REPLACEMENT WITHIN BOX ONLY





WEST ELEVATION OVERALL












#### C HORIZONTAL SECTION



A ELEVATION

B SECTION

2 PROPOSED WEST WINDOWS

#### INTERIOR FEATURES AND PERFORMANCE

#### RICH WOOD INTERIOR Offers beauty and warmth with six wood species and ten interior finish options. NARROW CHECKRAIL **EXCLUSIVE AUTOLOCK** Provides a sleek aesthetic Activates when the sashes are at 1 15/16 inches to maximize closed, locking the window. daylight opening while maintaining historical accuracy. FIRST-RATE ENERGY EFFICIENCY Meets ENERGY STAR® TILT WASH standards in energy efficiency Allows easy access to with multiple glass options for exterior glass for cleaning various regions, climates, and and maintenance. weather needs. SASH BALANCE SYSTEMS Enables smooth operation at the largest sizes.

#### EXTERIOR FEATURES AND PERFORMANCE



#### SUPERIOR WEATHER PERFORMANCE

LC-PG50 on most sizes. Optional commercial (CW) performance and IZ3 certified coastal performance on most sizes.

#### DESIGN VERSATILITY

An array of simulated divided lite patterns, interior and exterior color options, ten hardware finishes, and archtop models.

#### ALUMINUM INTER-LOCK

Eliminates drafts and improves the window's overall structural integrity.

17

MARVIN SIGNATURE\* COLLECTION



MKB Architects, LLC 1918 N. Mendell Street Chicago, Illinois 60642 www.mkbdesign.net 773 235 3800

City of Milwaukee Historic Preservation Commission City Clerk's Office 841 N, Broadway, Rm B1 Milwaukee. Wisconsin 53202

Re: St Benedict the Moor Catholic Church basement windows

October 28, 2022

In response to your request, the general contractor, Pepper Construction was asked to identify and compare costs for different options to address the replacement of the basement windows on the east and west facades of St Benedict the Moor Church

The following options and costs are:

Option A: Restore existing wood windows and add storm windows: \$82,139

Option B: Replace existing windows with aluminum clad windows: \$67,508

Option C: Replace exiting windows with new wood windows for paint: \$70,645

These costs are for the windows only. Other costs involved such as permits, dumpsters, GC fees, etc. would be similar for each option.

For budgetary, energy, and maintenance reasons we ask that a Certificate of Appropriateness be granted for Option C: replace the existing windows with new wood windows for paint. This allows for a more energy efficient window that can be opened when necessary. In restoring the existing windows, storms would be needed year-round to help with heating and cooling costs and would not allow ventilation when needed.

Thank you for your consideration,


James Lear MKB Architects Although the architects have indicated the new windows will be all wood, the church wants to install aluminum clad windows for ease of maintenance.

## 2. 220755

Resolution relating to a Certificate of Appropriateness for the construction of a new house at 2409 N. Terrace Avenue, in the North Point North Historic District, for Terrace 2409 LLC.



2409 N. Terrace will be here






### SITING

- ~50' SETBACK FROM CURB IS AVERAGE FOR TERRACE AVENUE
- WIDTH OF HOUSES ON BLOCK
- HOUSES THAT HAVE ATTACHED GARAGE

(This is from a review of one of the 2 prior new houses)



## SITING AND FORM AND SCALE



FRONT SETBACK + 20%

FRONT SETBACK, AVG ADJ +/- 20%

FRONT SETBACK - 20%

FRONT SETBACK 27.5 + 30.6 = 58.1 / 2 = 29.05' AVG.

29.05 x 0.2 = 5.81'

Range: 23.24' to 34.86'

Applicant will utilize a 24 foot setback.



Other two new houses built on former St. Mary's Hospital land





Context with neighboring houses




11/7/2022 20

## TERRACE AVENUE CONTEXT (NORTH)





















NE HIGH
SCALE: NTS



4 SE HIGH
A4.2 SCALE: NTS



3 SW HIGH A4.2 SCALE: NTS



## MATERIALS











October version

November version





Reclaimed Brick Examples

Powers Realty - Properties - 8151 N Seneca Rd Fox Point, WI 53217



Rocket Homes

8118 Currie Ave, Wauwatosa, WI, 53213 | MLS #1805858 | RocketHomes

Images may be subject to copyright. Learn More

telated images

See mo



This Colonial was just listed in southern Fox Point by the Stallé Realty Group of Keller Williams Northshore.





#### THERMALLY MODIFIED WOOD

- 1. HEAT AND STEAM USED TO PRESERVE WOOD (390 DEGREES)
- 2. NO HARMFUL CHEMICALS OR ELEMENTS

11/7/2022 2





Standing seam zinc for roofs and cladding





































Review of landscape will come later

## 3.220800

Resolution relating to a Certificate of Appropriateness for rebuilding the rear porch at 2549 N. terrace Avenue, in the North point North Historic District, for Maria K. Roloff TOD
































Landscape architect has agreed to use all-wood elements in his project


# 4.220801


Resolution relating to a Certificate of Appropriateness for the repair of masonry at the front porch and other locations, at 1060 E. Juneau Avenue, in the First Ward Triangle Historic District, for GMC Miller House LLC, MRC Miller House...




1979 Survey Photo



















# 5.220950


Resolution relating to a Certificate of Appropriateness for the addition of a revised design for a deck and stairs at 1307 East Brady Street, in the Brady Street Historic District, for Jeno Cataldo...






Survey Photo









PROPOSED DEMOLITION ELEVATION - NORTH
3/16" = 1'-0"

PROPOSED DEMOLITION ELEVATION - EAST
3/16" = 1'-0"









Corner Trim Boards and Structural Lumber Finish: Treated wood lumber, all finished wood will be smooth and free of knots and have no visible injection marks. Paint with opeque stain to match existing building.



New Wood Siding: Board size and color to match existing building.



New Decorative Wood Railings: Wood railings, poets, rails,

balusters, railing cape and finishes to match existing wood railing located above Donia sign on the North face of the building.



Handrall and Guardrall Material: Matte Black powder-costed aluminum reling system with ADA handrails at the new stair going up to the second level. This stair starts 11'-1" behind the front face of the existing building.



Continue Historic Details at Deck: Replicate existing trims,

porties and plasters at new exterior deck. Paint new trim to match existing finish scheme.





Adding a built-in planter will help to further define the space as well and contribute to a welcoming ambiance.

String Lighting: To help illuminate the restaurant entrance and the nee stair to the second floor. Adding lighting will help define the space as its own area and create a more welcoming ambiance then the current FINISH PALLET

CoA 2.5 | 10/11/2022

### Kahler Slater

JC Capital Dorsla


1305 EAST BRADY STREET MILWAUKEE, WI 53202



### Current proposal

## Previous proposal

1305 EAST BRADY STREET MILWAUKEE, WI 53202





Previous proposals that were denied by the HPC





Railing Alternative:
wood railing to match
existing railing above
Dorsia sign on the north
face of the building. All
finished wood will be
smooth and free of knots
and have no visible
injection marks. Paint with
opaque stain to match
existing railing.

Corner Trim Boards and Structural Lumber Finish:
Treated wood lumber, all finished wood will be smooth and











