
Milwaukee Historic Preservation Commission November 7, 2022







If you wish to speak on an issue or have your opinion noted by the commission, please fill out a form at the door and hand it to us

1. 220754

Resolution relating to a Certificate of Appropriateness for window replacement on the lower levels at 1015 N. 9th Street, St. Benedict the Moor Roman Catholic Church, an individually designated historic property, for the Province of St. Joseph of the Capuchin Order...



St. Benedict the Moor Roman Catholic Church





EXTERIOR ELEVATION - EAST 3/32" = 1'-0"





dict the Parish

EXTERIOR ELEVATION - WEST 3/32" = 1'-0"





EAST ELEVATION OVERALL



TYPICAL EXISTING EAST WINDOW - INTERIOR



TYPICAL EAST WINDOW & DETAILS








- SCOPE OF WINDOW REPLACEMENT WITHIN BOX ONLY




11/7/2022







C HORIZONTAL SECTION



INTERIOR FEATURES AND PERFORMANCE

RICH WOOD INTERIOR

Offers beauty and warmth with six wood species and ten interior finish options.

NARROW CHECKRAIL

Provides a sleek aesthetic at 1 ¹% inches to maximize daylight opening while maintaining historical accuracy.

TILT WASH

Allows easy access to exterior glass for cleaning and maintenance.



EXCLUSIVE AUTOLOCK Activates when the sashes are closed, locking the window.

FIRST-RATE ENERGY EFFICIENCY Meets ENERGY STAR* standards in energy efficiency with multiple glass options for various regions, climates, and weather needs.

SASH BALANCE SYSTEMS Enables smooth operation at

the largest sizes.

EXTERIOR FEATURES AND PERFORMANCE

DURABLE CLADDING Extruded aluminum exterior cladding with an AAMA verified 2605 finish and backed by a 20-year warranty against chalking and fading

EXPANSIVE SIZES Larger than 5 feet wide by

10 feet high.

TRADITIONAL SILL BEVEL The 14-degree bevel provides optimal water management while maintaining a classic look.

SUPERIOR WEATHER PERFORMANCE

LC-PG50 on most sizes. Optional commercial (CW) performance and IZ3 certified coastal performance on most sizes.

DESIGN VERSATILITY

An array of simulated divided lite patterns, interior and exterior color options, ten hardware finishes, and archtop models.

ALUMINUM INTER-LOCK

Eliminates drafts and improves the window's overall structural integrity.



MKB Architects, LLC 1918 N. Mendell Street Chicago, Illinois 60642 www.mkbdesign.net 773.235.3800

City of Milwaukee Historic Preservation Commission City Clerk's Office 841 N, Broadway, Rm B1 Milwaukee, Wisconsin 53202

Re: St Benedict the Moor Catholic Church basement windows

October 28, 2022

In response to your request, the general contractor, Pepper Construction was asked to identify and compare costs for different options to address the replacement of the basement windows on the east and west facades of St Benedict the Moor Church

The following options and costs are:

Option A: Restore existing wood windows and add storm windows:	\$ 82,139
Option B: Replace existing windows with aluminum clad windows:	\$ 67,508
Option C: Replace exiting windows with new wood windows for paint:	\$ 70,645

These costs are for the windows only. Other costs involved such as permits, dumpsters, GC fees, etc. would be similar for each option.

For budgetary, energy, and maintenance reasons we ask that a Certificate of Appropriateness be granted for Option C: replace the existing windows with new wood windows for paint. This allows for a more energy efficient window that can be opened when necessary. In restoring the existing windows, storms would be needed year-round to help with heating and cooling costs and would not allow ventilation when needed.


Thank you for your consideration,

James Lear MKB Architects


Although the architects have indicated the new windows will be all wood, the church wants to install aluminum clad windows for ease of maintenance.

2. 220755

Resolution relating to a Certificate of Appropriateness for the construction of a new house at 2409 N. Terrace Avenue, in the North Point North Historic District, for Terrace 2409 LLC.



2409 N. Terrace will be here



TERRACE AVENUE HOME MILWAUKEE, WI

SITING


- ~50' SETBACK FROM CURB IS AVERAGE FOR TERRACE AVENUE
- WIDTH OF HOUSES ON BLOCK
- HOUSES THAT HAVE ATTACHED GARAGE

(This is from a review of one of the 2 prior new houses)



SITING AND FORM AND SCALE





FRONT SETBACK + 20%

FRONT SETBACK, AVG ADJ +/- 20%

FRONT SETBACK - 20%

FRONT SETBACK 27.5 + 30.6 = 58.1 / 2 = 29.05' AVG. 29.05 x 0.2 = 5.81' Range: 23.24' to 34.86'

Applicant will utilize a 24 foot setback.



Other two new houses built on former St. Mary's Hospital land



Context with neighboring houses






TERRACE AVENUE CONTEXT (NORTH)



















MATERIALS











October version

November version







Powers Realty - Properties - 8151 N Seneca Rd Fox Point, WI 53217

Reclaimed Brick Examples



👩 Rocket Homes

8118 Currie Ave, Wauwatosa, WI, 53213 | MLS #1805858 | RocketHomes

Images may be subject to copyright. Learn More

Related images



This Colonial was just listed in southern Fox Point by the Stallé Realty Group of Keller Williams Northshore.





THERMALLY MODIFIED WOOD


- 1. HEAT AND STEAM USED TO PRESERVE WOOD (390 DEGREES)
- 2. NO HARMFUL CHEMICALS OR ELEMENTS

Standing seam zinc for roofs and cladding






















11/7/2022









THE UNDERGROUND UTLITY INFORMATION SHOWN ON THIS MAP IS BASED ON FIELD MARKIN AND INFORMATION TURNISHED BY UTLITY COMPANIES AND THE LOCAL MUNICIPALITY. WHILE THIS INFORMATION IS BULEVED TO BE RELIABLE, ITS ACCURACY AND COMPLETENESS CANN HE GLIMBARTER

FENCE


TREE TO REMAN

*

MUL OZ'S

CONC MALK CANNED SEWER-

.....



Review of landscape will come later

3.220800 Resolution relating to a Certificate of Appropriateness for rebuilding the rear porch at 2549 N. terrace Avenue, in the North point North Historic District, for Maria K. Roloff TOD

Google Photo


Survey Photo 1980





















Landscape architect has agreed to use all-wood elements in his project


4.220801


Resolution relating to a Certificate of Appropriateness for the repair of masonry at the front porch and other locations, at 1060 E. Juneau Avenue, in the First Ward Triangle Historic District, for GMC Miller House LLC, MRC Miller House..




1979 Survey Photo


















5.220950


Resolution relating to a Certificate of Appropriateness for the addition of a revised design for a deck and stairs at 1307 East Brady Street, in the Brady Street Historic District, for Jeno Cataldo..






Survey Photo







CoA 2.3 | 10/11/2022



PROPOSED DEMOLITION ELEVATION







where some have been at the late JC Capital Kahler Slater Dorsia 1305 EAST BRADY STREET MILWAUKTE, WI 53202

New Wood Siding:

Board size and color to

metch existing building.

G). Built-in Planter:

Continue Historic Details at Deck: Replicate existing trime, corbeis and plasters at new exterior deck. Paint new trim to match excisting

finish scheme.

Adding a built-in planter will help to further define the space as well and contribute to a welcoming ambiance.

String Lighting: To help illuminate the restaurant entrance and the new stair to the second floor. Adding lighting will help define the space as its own area and create a more welcoming ambiance then the current conditions. **FINISH PALLET**

CoA 2.6 | 10/11/2022

New Decorative Wood Railings: Wood railings, posts, rails,

belusters, railing caps and finishes to match existing

wood miling located above


Dones sign on the North face of the building.

67



Current proposal

Previous proposal





Previous proposals that were denied by the HPC





Railing Alternative: wood railing to match existing railing above Dorsia sign on the north face of the building. All finished wood will be smooth and free of knots and have no visible injection marks. Paint with opaque stain to match existing railing

Corner Trim Boards and Structural Lumber Finish: Treated wood lumber, all finished wood will be smooth and free of knots and have no visible injection marks. Paint with

