

Request for a hearing

C.I. File No. 1030-2013-2881

I would like to appeal the decision by the City of Milwaukee that they are not responsible for the damage to my vehicle by a Public Works vehicle on July 18, 2013. I believe fully that the driver of the city vehicle was not paying attention and due to that hit my vehicle on the rear passenger panel area. Please notify me by mail once a date is set.

Thank you

Sincerely,

Matthew Bramm

CITY OF MILWAUKEE
RECEIVED

2013 DEC 30 PM 3:22

OFFICE OF
CITY ATTORNEY

02

CITY OF MILWAUKEE
13 DEC 30 PM 12:59
CITY CLERK'S OFFICE

To whom it may concern,

This is an account of the events that happened on July 18, 2013 concerning my vehicle and a Department of Public Works vehicle that hit me as I was coming off of the highway at the Locust St. exit and merging onto N 8th St. I believe what happened was that I changed lanes coming off the highway to the right hand lane at the same time as the city vehicle was changing lanes into that lane going left. The driver of the city vehicle though was behind me and turned into my vehicle as can be seen in the photos the police took.

I am sure it was an accident on his part and I am only seeking money from the city for the amount needed to repair my vehicle as indicated by quotes from two different auto body repair shops. Total Auto Body in Grafton is a company I am familiar with and I know they do good work. Their quote is for \$3,366.23 so that would be the amount that I am making this claim for.

If you have any questions please contact me.

My phone number is 920 889 1518 and my email address is mcbramm@gmail.com. The city vehicle in question is #22869.

Thank you,

Matthew Bramm

RECEIVED

NOV 19 2013

OFFICE OF
CITY ATTORNEY

CITY OF MILWAUKEE
2013 NOV 18 AM 11:39
CITY CLERK'S OFFICE

DOUBLE A AUTO BODY, LLC.
 20 NORTH 14TH STREET
 P.O. BOX 586
 OOSTBURG, WI 53070-0586
 PHONE: (920)564-3534 FAX: (920)564-6187

CD LOG NO 7067-1 DATE 08/16/13

SHOP: DOUBLE A AUTO BODY INSP DATE: 08/16/13
 ADDRESS: 20 NORTH 14TH STREET CONTACT: DALE SCHREURS
 PO BOX 700586 PHONE 1: (920)564-3534
 CITY STATE: OOSTBURG, WI FAX: (920)564-6187
 ZIP: 53070- EMAIL: DOUBLEAAUTOBODY@FRONTIER.COM
 EMAIL: DOUBLEAAUTOBODY@FRONTIER.COM

OWNER: BRAMM, MATHEW HOME PHONE: (920)889-1518
 ADDRESS: 225 PEBBLE BEACH RD
 CITY STATE: CEDAR GROVE, WI
 ZIP: 53013

POINT OF IMPACT: 0

LIC#: STATE: VIN: 2G1WZ151359248210
 BODY COLOR: MILEAGE:
 CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

2005 CHEVROLET MONTE CARLO TONY STEWART 2DOOR COUPE 6CYL SUPERCHARGED 3.8
 CODE: U2452C/F OPTNS L/24PADJMESGHI

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
BUMPER COVER MOUNTED FOG LAMPS	HEATED FRONT SEATS
HEATED REMOTE CONTROL MIRRORS	REMOTE KEYLESS ENTRY SYSTEM
REAR SPOILER	TRACTION CONTROL SYSTEM
ANTI-LOCK BRAKE SYSTEM	CRUISE CONTROL
OVERHEAD CONSOLE	STRG WHEEL MTD RADIO CONTROLS

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
BR0183	13		PANEL, BODYSIDE OTR RT BLEND REFINISH					1.4	4
			0.5 BLEND						
			0.6 TWO STAGE SETUP						
			0.3 TWO STAGE						

RI0157	MLDG,ROCKER PANEL	RT R&I ASSEMBLY		0.4	1
I 0208	DOOR SHELL,FRONT	RT REPAIR		8.0	*1
L 0208	DOOR SHELL,FRONT	RT REFINISH		2.9	4
			2.4		SURFACE
			0.5		TWO STAGE
RI0198	MLDG,FRONT DOOR BEL	RT R&I ASSEMBLY		0.9	1
RI0230	MIRROR,SPORT R/C	RT R&I ASSEMBLY		INC	1
RI0228	HANDLE,FRONT DOOR O	RT R&I ASSEMBLY		0.2	1
I 0390	PANEL,QUARTER	RT REPAIR		12.0	*1
L 0390	PANEL,QUARTER	RT REFINISH		3.1	4
			2.6		SURFACE
			0.5		TWO STAGE
RI0396	QTR GLASS R & I	RT R&I ASSEMBLY		1.0	1
EC0380 #	SEALANT KIT,QTR GLA	RT ECONOMY PART	20.00*	2.0	1
	# = 01, 02				
RI0534	TAILLAMP ASSEMBLY	RT R&I ASSEMBLY		0.3	1
RI0566	REAR BUMPER COVER R&I	R&I ASSEMBLY		1.2	*1
L M14	CORROSION PROTECTION	REFINISH		0.3	*4*
N M17	COVER CAR EXTERIOR	ADDNL LABOR OPERA		0.2	*4*
SBM60	HAZARD. WSTE. REM.	SUBLET REPAIR	5.00*		*1*
L M70	COVER CAR INTERIOR	REFINISH		0.2	*4*
E	STRIPE KIT RT SIDE	NEW PART	442.48*	1.5	*1*
	TONY STEWART				
E	NAME PLATE RT DOOR	NEW PART	122.68*	0.3	*1*
	SUPERCHARGED				
E	NAME PLATE	NEW PART	22.93*		1*
	SS				
E	NAME PLATE RT QTR.	NEW PART	181.92*	0.3	*1*
	TONY STEWART				
L	EDGE RT DOOR	REFINISH		1.0	*4*
L	EDGE RT QTR.	REFINISH		1.0	*4*
L	ROPE BACK GLASS	REFINISH		0.3	*4*
N	FINISH SAND & BUFF 30%	ADDNL LABOR OPERA		1.7	*1*
E	DECAL	NEW PART	68.03*		1*

20

26 ITEMS

MC MESSAGE(S)

- 01 CALL DEALER FOR EXACT PART NUMBER / PRICE
- 02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO
- 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS		838.04
OTHER PARTS		20.00
PAINT MATERIAL		395.20
PARTS & MATERIAL TOTAL		1,253.24
TAX ON PARTS & MATERIAL @	5.000%	62.66

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	58.00	8.1	21.7	1,728.40

2005 CHEVROLET MONTE CARLO TONY STEWART 2DOOR COUPE
LOG NO 7067-1

2-MECH/ELEC	70.00			
3-FRAME	68.00			
4-REFINISH	58.00	10.2	0.2	603.20
5-PAINT MATERIAL	38.00			
LABOR TOTAL				2,331.60
TAX ON LABOR		@	5.000%	116.58
SUBLET REPAIRS				5.00
TAX ON SUBLET		@	5.000%	0.25
TOWING				
STORAGE				
GROSS TOTAL				3,769.33
NET TOTAL				3,769.33

SHOPLINK U3808 ES CD LOG 7067-1 DATE 08/16/13 03:36:10PM R6.37 CD 08/13
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53070
HOST LOG
(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.9 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

TOTAL AUTO BODY, LLC.
1635 N PORTWASHINGTON RD
GRAFTON, WI 53024
PH: 262-375-2727 FAX: 262-375-4786
FED. TAX I.D. 200777001

*** PRELIMINARY ESTIMATE ***

10/16/2013 12:58 PM

Owner

Owner: MATT BRAMM
Address: 225 PEBBLE BEACH RD.
City State Zip: Cedar Grove, WI 53013
Email: mcbramm@gmail.com

Work/Day: (920)889-1518
FAX:

Inspection

Inspection Date: 10/16/2013 12:59 PM
Primary Impact: Right Side

Inspection Type:
Secondary Impact: Right Rear Side

Company: TOTAL AUTO BODY LLC
Contact: BOB GIBSON
Address: 1635 N. PORT WASHINGTON RD.
City State Zip: Grafton, WI 53024
Email: bob@totalautobody.com

Appraiser License # :

Work/Day: (262)375-2727
FAX: (262)375-4786

Repairer

Repairer: TOTAL AUTO BODY
Address: 1635 N. PORT WASHINGTON RD.
City State Zip: GRAFTON, WI 53024
Email: bob@totalautobody.com

Contact: Bob Gibson
Work/Day: (262)375-2727
FAX: (262)375-4786

Vehicle

2005 Chevrolet Monte Carlo Tony Stewart 2 DR Coupe
6cyl Supercharged 3.8
4 Speed Automatic

Lic.Plate: 589-KKN
Lic Expire:
Veh Insp# :
Condition:
Ext. Color: BLACK
Ext. Refinish: Two-Stage
Ext. Paint Code: 8555

Lic State: WI
VIN: 2G1WZ151359248210
Mileage Type: Actual
Code: U2452C
Int. Color:
Int. Refinish: Two-Stage
Int. Trim Code:

Options

AM/FM CD Player
Aluminum/Alloy Wheels
Bucket Seats
Cruise Control
Dual Power Seats
Garage Door Opener

Air Conditioning
Anti-Lock Brakes
Cargo/Trunk Net
Driver Information Sys
Floor Mats
Ground Effects Package

Alarm System
Automatic Dimming Mirror
Center Console
Dual Airbags
Fog Lights
Heated Front Seats

Heated Power Mirrors	Illuminated Visor Mirror	Intermittent Wipers
Keyless Entry System	Leather Seats	Leather Steering Wheel
Lighted Entry System	OnStar System	Overhead Console
Power Brakes	Power Door Locks	Power Steering
Power Windows	Rear Spoiler	Rear Window Defroster
Rem Trunk-L/Gate Release	Split Folding Rear Seat	Sport Suspension
Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Tilt Steering Wheel	Tinted Glass	Traction Control System
Trip Computer	Tutone Paint	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Unibody/Frame										
1	I		M00	Unibody-Frame Incl Setup >> PRE PULL QUARTER PILLAR	Repair				2.0*	SM
Stripes And Mouldings										
2	RI	290		Mldg,Rocker Panel RT	R & I Assembly				0.4	SM
3	E	240	01	Stripe,Front Door RT	88980946 GM Part	\$442.48*			0.6	SM
4	E	250		Nameplate,Bodyside RT	88980959 GM Part	\$60.84*			0.2	SM
5	E	266		Stripe,Quarter Side RT	88980948 GM Part	\$0.00*			0.3	SM
Front Body And Windshield										
6	I	150		Mldg,W/S Reveal Upper >> Lift tape for refinish	Repair				0.2*	SM
Front Doors										
7	EU	208		Door Assembly,Front RT	Replace Recycled	\$300.00*			2.0	SM
8	L	208		Door Shell,Front RT	Refinish 2.4 Surface 1.0 Edge 0.7 Two-stage				4.1	RF
Quarter And Rocker Panel										
9	BR	183	13	Panel,Bodyside Otr Upr RT	Blend Refinish 0.5 Blend 0.6 Two-stage setup 0.3 Two-stage				1.4	RF
10	I	390		Panel,Quarter RT	Repair				9.0*	SM
11	L	390		Panel,Quarter RT	Refinish 2.6 Surface 0.5 Two-stage				3.1	RF
12	E	260	01	Nameplate,Qtr Panel RT >> "SUPERCHARGED"	88980626 GM Part	\$122.68			0.2	SM
13	E	572		Nameplate,Qtr Panel RT >> "SS"	10404076 GM Part	\$34.32			0.2	SM
14	I	366	07	Pillar,Body Lock RT	Repair				1.0*	SM
15	L	366		Pillar,Body Lock RT	Refinish 1.0 Surface 0.2 Two-stage				1.2	RF
16	RI	396		Qtr Glass R & I RT	R & I Assembly				1.0	SM
17	EC	380		Sealant Kit,Qtr Glass RT	Replace Economy	\$25.00*			2.0	SM
Deck Lid And Back Glass										
18	I	372		Mldg Assy,Back Glass >> Lift tape for refinish	Repair				0.2*	SM

Rear Bumper

19	N	566	Rear Bumper Cover R&I >> Loosen for refinish	Additional Labor		0.5*	SM
----	---	-----	---	------------------	--	------	----

Rear Body, Lamps And Floor Pan

20	RI	534	Taillamp Assembly RT	R & I Assembly		0.3	SM
----	----	-----	----------------------	----------------	--	-----	----

Manual Entries

21	EC	M14	Corrosion Protection	Replace Economy	\$10.00*	0.3*	SM
22	EC	M17	Cover Car Exterior	Replace Economy	\$5.00*		RF
23	EC	M60	Hazardous Waste Removal	Replace Economy	\$3.00*		SM
23	Items						

MC Message

01	CALL DEALER FOR EXACT PART # / PRICE
07	STRUCTURAL PART AS IDENTIFIED BY I-CAR
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$660.32	
Other Parts		\$343.00	
Paint Materials		\$372.40	
Parts & Material Total			\$1,375.72
Tax on Parts & Material	@ 5.600%		\$77.04

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$60.00	7.5	12.9	20.4	\$1,224.00
Mech/Elec (ME)	\$95.00				
Frame (FR)	\$75.00				
Refinish (RF)	\$60.00	9.8		9.8	\$588.00
Paint Materials	\$38.00				

Labor Total			30.2 Hours		\$1,812.00
Tax on Labor	@ 5.600%			\$101.47	
Gross Total					\$3,366.23
Net Total					\$3,366.23

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53024 Default

Audatex Estimating 7.0.019 ES 10/16/2013 03:07 PM REL 7.0.019 DT 10/01/2013 DB 10/15/2013
 Copyright (C) 2013 Audatex North America, Inc.

2.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	E = Replace OEM	NG= Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM= Replace PXN Reman/Rebit	UM= Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG= Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2013 Audatex North America, Inc.
Audatex Estimating is a trademark of Audatex North America, Inc.