August 21, 2003

To Whom It May Concern:

This is a letter stating what damages the City of Milwaukee is liable for due to an accident that occurred on Thursday July 31st 2003.

My vehicle was legally parked and was involved in an accident resulting from a police chase. And since the accident, my vehicle has not run properly. I have gone to numerous repair shops to get an idea of what the damages are going to cost. I have enclosed with this letter 2 of the estimates that I have received since speaking with your office on what needed to be done to file this claim. For instance, it has begun to cut off while sitting at a signal light.

Also, as you can see there are internal damages that are hidden and will not be known until the work is started. So for internal hidden damages, we would like to ask for an additional \$3000.00 to cover the damages, which may include:

- 1. Rear brake system which has been squeaking since the accident;
- 2. Exhaust section damaged because of accident
- 3. The axial damage;
- 4. The tire that was needed to be replaced because an object from the other car was stuck in it;

To repair the driver side window that was knocked off track.

Thank you in advance for your immediate attention to this matter.

Sincerely,

LaTonya LeSueur

3603 N. 10th St 873-0481

Job Number:

PINKEY'S CAPITAL AUTO BODY

License #:

PINKEYS CAPITAL AUTO BODY 3859 N RICHARDS STREET MILWAUKEE, WI 53212 (414)962 - 3380

PRELIMINARY ESTIMATE

Written By: Adjuster:

Insured: TYRONNE LESSUELR

Owner: TYRONNE LESSUELR

Address:

Day: (414)873-0481

Claim #

Policy #

Deductible:

Date of Loss:

Type of Loss: Collision Point of Impact: 6. Rear

Inspect Location:

Insurance Company:

Days to Repair

1998 DODG INTREPID 6-2.7L-FI 4D SED

VIN: 2B3HD46R8WH225244 Lic: WPX-351 Air Conditioning

Cruise Control

Clear Coat Paint

Power Windows Power Trunk/Tailgate

Rear Defogger

Intermittent Wipers Power Steering

Power Locks Driver Air Bag

WI Prod Date:

Odometer: Tilt Wheel Dual Mirrors Power Brakes

Power Mirrors Passenger Air Bag

1	Wheel Dis	c Brai	kes Cloth Seats		Bucket	Seats -		
	NO.	OP.	DESCRIPTION	QTY	EXT. PRI	CE LABOR	PAII	JT
	1		REAR BUMPER					
	2**	Repl	A/M CAPA Bumper cover	1	267.00	1.6	3	.2
	3		Add for Clear Coat		•	. •		. 3
	4#	Repl	FLEX ADDITIVE	1	12.00			
	5	Repl	Bumper cover rivet	12	17.40			
	6	Repl	Bumper cover pin	8	12.80			
	7	Repl	Bumper cover clip	1	2.35	•		-
	8	Repl	RT Bumper cover fastener	1	2.35			
	9	Repl	LT Bumper cover fastener	1	2.35			
	10	Repl	RT Bumper cover bracket	1	7.95			
	11	Repl	LT Bumper cover bracket	1	7.95			
	12	_	Energy absorber	1	85.10	Incl.		
	13	_	Reinforcement	1	136.00	0.4		
	14	Repl	Mount kit license plate base	1	26.60			
	15		REAR LAMPS			4.0	24	
	16	Repl	RT Tail lamp assy	. 1	169.00	0.4	* · ;	
	17	Repl	LT Tail lamp assy	1	169.00	0.4	:	
			•					

PRELIMINARY ESTIMATE 1998 DODG INTREPID 6-2.7L-FI 4D SED

					·					
NO	0.	OP.		DESCRIPTION		QTY	EXT.	PRIC	E LABOR	PAINT
18	8		OUARTE	R PANEL						
	9*	Rpr	LT Quarte		. +		٠		2.0	2 4
20	0	•		Clear Coat	÷				2.0	2.4
2.		Refn	Fuel door		•					1.0
22	2			lear Coat			,			0.3
	3*	Rpr	RT Quarte				· .		12 0	0.1
24		1		Major Adj. Panel					12.0	2.4
25				lear Coat	•	-				-0.4
	6#	R&I	ANT ASSY	.1041 .0040					0.5	0.4
	 7 #		UNIBODY S	ЕТ ПР		1				
	3#		REAR SWAY			_			2.0 F	
_	9#	-		E MASH RT & LT	DATTO	i i			3.0 F	
30		- · F~ -		ODY & FLOOR	TATTO				4.0	
	1*	Rpr	Rear body						2 0	4 6
	2	r/Pr		ajor Adj. Panel					<u>3.0</u>	1.2
33				lear Coat	<u>.</u>					-0.4
	1 *	Pnr	Rear floo						4 0	0.2
35		ΝÞΙ		lear Coat					4.0	1.4
36		Repl		rear Coat		. 1	_	0.0	A -	0.3
37			RUSTPROOF	TNC		1		00	0.5	
38		керт	TINT AND			1	10.	00	0.5	
)#			D AND BUFF		1		•		1.5
40				UNDER BUMPÈR		1				1.5
						· <u>-</u>				
				Subtotals	==>		932.	85	34.3	16.4
	6			Danta						
	. r		•	Parts						932. 85
				Body Labor		29.	hrs ب	@ \$	44.00/hr	1289.20
				Paint Labor		16.	4 hrs	@ \$	44.00/hr	721.60
				Frame Labor		5.	0 hrs	@ \$	44.00/hr	
				Paint Supplies		16.	4 hrs	@ \$	24.00/hr	393.60
				CUDMOMAT						
				SUBTOTAL Sales Tax		^	2555			3557.25
				Sales lax		Ş	355/	.25 @	5.6000%	199.21
				CDAND TOTAL			~			
				GRAND TOTAL					. Ş	3756.46
				ADJUSTMENTS:						
						•				
				Deductible						0.00
				CUSTOMER PAY						
			•	INSURANCE PAY					S	0.00
				THOUNDINCE ENI					S	3756.46

Job Number:

PRELIMINARY ESTIMATE

1998 DODG INTREPID 6-2.7L-FI 4D SED

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR3PH98 Database Date 8/2003 and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recon. Recored parts are described as Recore. NAGS Part Numbers and Prices are provided from National Auto Glass Specifications, Inc. Pound sign (#) items indicate manual entries.

Pathways - A product of CCC Information Services Inc.

RUSS DARROW PONTIAC NISSAN ISUZU KIA 7676 NORTH 76TH STREET

PO BOX 240197

MILWAUKEE WI 53224-9010

PHONE (414) 362-7520 FAX (414) 355-6744

CD LOG NO 4154-1 DATE 08/20/03

RUSS DARROW SUPERSTORE INSP DATE: 08/20/03 SHOP:

ADDRESS: 7676 NORTH 76TH STREET CONTACT: MARTIN REHFELDT CITY STATE: MILWAUKEE, WI PHONE 1:

(414) 355-6300 ZIP: 53223-PHONE 2: (414) 362-7520 FAX: (414)355-6744

OWNER: LESUEUR, LATANYA&TYRONNE HOME PHONE: (414)873-0481

ADDRESS: 3603 N 10TH STREET

CITY STATE: MILWAUKEE, WI ZIP: 53206-

POINT OF IMPACT: 10 TYPE OF LOSS: /DRV

LIC#: WPX-351 STATE: WI VIN: 2B3HD46R8WH225244

ACCTNG CTL#:

BODY COLOR: MAROON MILEAGE:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS

UC=RECONDITIONED PRT EC=REPLACE ECONOMY EU=REPLACE SALVAGE UM=REMAN/REBUILT PRT EP=REPLACE PXN PC=PXN RECONDITIONED

PM=PXN REMAN/REBUILT TE=PARTL REPL PRICE ET=PARTL REPL LABOR

IT=PARTIAL REPAIR I=REPAIR L=REFINISH BR=BLEND REFINISH TT=TWO-TONE CG=CHIPGUARD N=ADDITIONAL LABOR

RI=R&I ASSEMBLY RP=RELATED PRIOR SB=SUBLET AA=APPEAR ALLOWANCE P=CHECK

UP=UNRELATED PRIOR

CONDITION: GOOD

MAY BE ADDITIOAL DAMAGE AFTER TORN DOWN.

1998 DODGE INTREPID STD 4DOOR SEDAN 6CYL GASOLINE 2.7

CODE: N2813A/A OPTNS A/24DY

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

HEATED REMOTE CONTROL MIRRORS CRUISE CONTROL

OP	GDE	MC	DESCRIPTION		MFG.PART NO.		PRICE	AJ% B%	HOURS R
I	0389		PANEL, QUARTER	LT	REPAIR				2.5*1
L	0389	13	PANEL, QUARTER	LT	REFINISH				3.5 4
I	0390		PANEL, QUARTER	RT	REPAIR		200		10.0*1
L	0390		PANEL, QUARTER	RT	REFINISH	•		-	2.6 4
BR	0397		DOOR, FUEL FILLER	LT	BLEND REFINISH				0.2 4
RI	0111		MAST, ANTENNA QTR PN	RT	R&I ASSEMBLY				0.2 1
BR	0479		LID, REAR DECK		BLEND REFINISH				1.1 4
I	0509		PANEL, REAR BODY	٠	REPAIR				2.5*1
L	0509		PANEL, REAR BODY		REFINISH	•			1.3 4

E	0533	01	TAILLAMP ASSEMBLY LT	4574961AJ	194.00		0.3 1
E	0534	01	TAILLAMP ASSEMBLY RT	4574960AI	184.00		0.3 1
RI	0538		LAMP, HIGH MOUNTED STOP	R&I ASSEMBLY	•		0.4 1
E	0566		COVER, REAR BUMPER	4574903AC	352.00		1.5 1
L	0566		COVER, REAR BUMPER	REFINISH			3.0 4
E	0573		BRKT, REAR BUMPER MT LT	4805095AB	7.50		INC 1
E	0574		BRKT, REAR BUMPER MT RT		7.50		INC 1
E	0579		ABS, REAR ENERGY	4574902	81.00	•	INC 1
EC	M03		FLEX ADDITIVE	ECONOMY PART	15.00*		4*
EC	M05		RUSTPROOFING	ECONOMY PART	20.00*		0.2*1*
L	M15		COLOR TINT	REFINISH	20,00		0.5*4*
EC	M17		COVER CAR EXTERIOR	ECONOMY PART	5.00*		2*
N	M31		SET-UP FOR REALIGN.	ADDNL LABOR OPERA			2.0*3
SB	M60		HAZARD. WSTE. REM.	SUBLET REPAIR	4.25*		1*
EC	M63		FACTORY HARDWARE	ECONOMY PART	20.25*		1*
		>>	FOR RETAINERS & CLIPS,	NUTS & BOLTS<<	20020		.
I			ROUGH PULL	REPAIR			3.5*1*
		RO	OUGH PULL TO BRING QUART		L BACK TO	PLACE	TO REPAI

25 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL	CALCULATIONS	&	ENTRIES

GROSS PARTS OTHER PARTS				826.00 60.25
PAINT MATERIAL				317.20
PARTS TOTAL		•		1,203.45
TAX ON PARTS & MATERIAL	@		5.600%	67.39
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	46.00	2.9	18.5	984.40
2-MECH/ELEC	85.00			
3-FRAME	46.00		2.0	92.00
4-REFINISH	46.00	12.2		561.20
5-PAINT MATERIAL	26.00		* *	
LABOR TOTAL				1,637.60
TAX ON LABOR		• •	5.600%	91.71
SUBLET REPAIRS				4.25
TAX ON SUBLET		@	5.600%	0.24
TOWING				
STORAGE				

GROSS TOTAL

3,004.64

NET TOTAL

3,004.64


ADP SHOPLINK U1732 ES CD LOG 4154-1 DATE 08/20/03 09:39:38AM R6.3 CD 07/03 HOST LOG


(C) 1998 - 2003 ADP CLAIMS SOLUTIONS GROUP, INC.

2.7 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.


THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

NOTICE: WHEN SELECTING A REPAIR FACILITY, THE VEHICLE OWNER SHOULD CONSIDER THAT THE REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AND THE RESTORATION OF CORROSIVE RESISTANT COATINGS AS RECOMMENDED BY THE MANUFACTURE. FAILURE TO HAVE THE VEHICLE PROPERLY REPAIRED COULD RESULT IN A SAFETY HAZARD





32



Draw Diagram of Accident &				
Indicate North with an arrow in the circle.		presentation of Narra		Skidmarks to Impact Unit 1: 100 Unit 2:
artewin the chee.	Supplemental Reports X X W	Titness Statements 12 Y 1 Measuremen	ts Taken Y. N	PEET
				Surface Type:
	and the second s	·	•	i.
	A 10	P		
	SEE			
The state of the s			marken element of the control of the	
		egmanye e e e e e e e e e e e e e e e e e e	eritario de la Companya de la Compa Esta de la Companya	
N =			Photos By:	
A	F P . /		[05] [200 [200 [200 [200 [200 [200 [200 [20	
ג'וע. D				s Were Doing
4			Unit Number	Unit Number
\hat{T}			6 7 8 9 10	678900
I			2 Making	Straight ①
V Areas State Stat			Slowing of	Right Turn 3 3 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
WITNESS Last	First	ML	Legally Violating No	Parked 6 Passing Zone 7
ADDRESS Street & Number	Date of Birth		8 Illegall 9 Parking	/ Parked &
City & State ZIP	Phone		Changii Changii	Maneuver (10)
ACCESS CONTROL &	Number 413	LIGHT CONDITION	13 Overtakin	ng on Left 12 g on Right 13 U Turn 13
No Control (Unlimited Access)	Part A Straight	I Daylight	15 Turning	on Red (15)
2 Full Control (Only Ramp Entry Exit) 2 Partial Control	2 Curve Part B	Dark—Not Lighted Dark—Lighted	Negotiati	ng Curve (172) ner (18
TRAFFIC WAY	Level/Flat 4 Hill	4) Dawn 5) Dusk		
Not Physically Divided (2-Way Traffic)	ROAD SURFACE CONDITION Dry	• Unknown	Traffic (Control
2 Divided Highway, Median Strip, without Traffic Barrier	2 Wet	WEATHER	Unit Number	Unit Number ① ② ③ ④ ⑤
3. Divided Highway, Median Strip, with Traffic Barrier	4 Ice 3 Sand, Mud, Dirt, Oil	(T) Clear	5 7 8 9 10	5.7.8 3 10
4 One-Way Traffic 5 Parking Lot or Private Property	© Other	Cloudy 3 Rain	No Co Traffic Signa	
RELATION TO B	COADWAY 177	3 Snow 5 Fog, Smog, Smoke	3 Traffic Sign	al Flashing ③ •
2 Parking Lot or Private Property 3 Shoulder (Other Than Shoulder	er within Madian or Com	Sleet, Hail (Freezing Rain or Drizzle)	5 Stop Sign w	ith Flasher 5 •
Median (Other Than Median w Outside Shoulder—Left	rithin Gore)	7. Blowing Sand, Soil, Dirt, Snow	7 Warn Sign w	ith Flasher Z
6 Outside Shoulder—Right 7 Off Roadway—Location Unkno	wn 9 On Ramp	Severe Crosswinds Cother Unknown	9 Traffic Cont	Signal 10:
8 Gore (Area between Ramp & H	lighway) 19 Unknown	** UHAHOWII	11 Oth	er 11

Ė

ALIC A A 2002

Officer's Opinion of Possible Contributing Circumstances

Driver Factors

Vehicle Factors

	Driver Fac	tors		Ve	hicle Fact	ors	
2 4	umber ▶ 4 5 (9 10	Unit Numbe 1 2 3 4 5 7 8 9 N/A	: ā	Unit Number 1 2		1 2	Number 3 4 5 8 9 11 N/A
1 2 3 4 5 5 7 5 9 <u>0</u> 1 2	Exceeding Speed Speed Too Fast Co Fail to Yield Right Inattentive Driv Following Too C Improper Tut Left of Cente Disregarded Truffic Improper Overta Unsafe Backin Failure to Have Co Driver Condition	ndition 2 of Way 3 ring 3 close 5 r 7 Control 6 king 9 ntrol 11 on 12		3 6 7 4 Disabl 3 C	Brake System Tires teering System Turn Signals Head Lamps Stop Lamps Tail Lamps ed in Prior Acc Other Disabled Mirrors pension Syste Other	n cident	
3	Physically Disab	led 13	L	L		<u>_</u>	

Hig	hway Factors
Unit Number	Unit Number
II.	1213
5 .7 .6 9 10	6 7 8 9 10
⇒ N/A	N/A
Si	now, Ice or Wet
	arrow Shoulder 2
3	Low Shoulder
	Soft Shoulder
5	Loose Gravel
S Re	ough Pavement 🔞
Debris	From Prior Accident 7
	Other Debris
Sign O	bscured or Missing
	larrow Bridge
(Cor	nstruction Zone II
	bility Obscured 12
13.	Other 130

OFFICER INFORMATION	Date Notified	(Military Time)	(Military Time)	Date of Report
Last GRANT First TAV C MLI	MONTH DAY YEAR	HOUR MIN.	HOUR MIN.	MONTH DAY YEAR
Law Enforcement Agency Address	<u></u> 3103	2235	2240	Feb 0103
749 W. STATE ST.	∴ Mar (0 0 € 0	0 0 0 0	0000	Mar O O
City & State MICWAUKEE WI, 53233	May 2 2 5 June 3 3	3 2 3	22 333	Apr (1) (1) (2) (2) (2) (3) (3) (4)
Phone Number (4/11) 128 935 - 72.52	☐ July ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	⊕⊕⊕	① ② ④ ⑤ ⑤ ⑤	July J S S S S S S S S S S S S S S S S S S
Agency # Enforcement Agency PURCE Officer ID # 1.9 55 POLITICE DEPT. 155829	Oct 7 7 7 9 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9	7 7 3 3 9 9	7 7	Oct T T
T 1 A D 1 11 a Z A	<u> </u>	1 31	9 9	Dec 9 9 9

Truck & Bus Accident Information (This Section Must Be Completed for Each Truck or Bus Involved in this Accident.).

When To Use This Section: Part A	Did the accident involve:	} *i*
A truck with at least two axles and		
A truck with a hazardous materials	s placard?	
	e persons, including the driver? X N	·····
STOP! If <u>all</u> the responses to Part A ar Accident Information Section. If there	re "NO" do not complete this Truck & Bus e are <u>any</u> "YES" answers, continue to Part B.	
Part B	ja	
Any person who was fatally injured	l?	YN
Any injured person who required t	transport for immediate medical treatment?	Y N
One or more vehicles that had to b	be towed from the scene as a result of the acciden	W Y
	e "NO" do not continue. If there are <u>any</u> "YES" ansi dent Information Section	

Hazardous Material Informa	11011
• Hazardous Material Class Numbers (1-2digit):	
• Hazardous Material "UN" Numbers (4 digit):	
 Hazardous Material Placard Displayed? Hazardous Cargo was Released? 	M. (Y. (A) (X)
List the Hazardous Material(s) by Name in thi	s Load:
List the Name(s) of Released Hazardous Mater	rial(s):

Carrier Information

Carrier Identification Numbers

US DOT 140 LC

Interstate Carrier? Y N Interstate Carrier Name

Carrier Address 142

Vehicle Information Gross Vehicle Weight Rating 145 LBS Total # of Axles	
- Vehicle Configuration	
Bus Single unit truck + 3 axles Fruck Teaser Teams Poubles	
2. Bus Converte Mixer Single unit truck, 2 axies, 5 tites Truck Trailer Tractor-Triples Low Truck Truck Trailer Tractor-Triples Low Truck Tractor-Triples Truc	
EQUENCE OF EVENTS FOR THIS VEHICLE Much a final of one in four arms in the order that they occurred.) 1 2 3 4 Ran off Road T 2 3 4 Collision Involving Motor Vehicle in Transp	
1 2 3 4 Collision Involving Parked Motor Vehicle 3 4 Collision Involving Train Carpo Ends Garber Refine	
1 2 3 4 Downhill Runaway 1 2 3 3 Collision Involving Pedalcycle 1 3 4 Cargo Loss or Shift 1 2 3 3 Collision Involving Animal	
1 2 3 4 Explosion or Fire 1 2 3 4 Collision Involving Fixed Object 5 Dump 10 Lug Inuck	

1 2 3 4 Cargo Loss or Shift
1 2 3 4 Explosion or Fire
1 2 3 4 Separation of Units
1 2 3 4 Collision Involving Pedestrian

GS03

654321

ALIA A I BAAA

EMS Number

MV4000 899