

OP & SAE



U.S. Department
of Transportation
**Federal Railroad
Administration**

1200 New Jersey Ave, SE
Washington, DC 20590

CITY OF MILWAUKEE
2016 JAN 19 P 12:02
CITY CLERK'S OFFICE

January 14, 2016

Mr. James R. Owczarski
City of Milwaukee
Office of the City Clerk
200 E. Wells Street
Milwaukee, Wisconsin 53202

Re: FRA FOIA File No. 16-060
Your File No. 150076

Dear Mr. Owczarski:

This letter is in response to your Freedom of Information Act (FOIA) request to the Federal Railroad Administration (FRA) for copies of "inspections performed on railroad tracks, crossings and bridges within the limits of the City of Milwaukee ..." during the last ten years.

In accordance with the FOIA, I am enclosing copies of the above mentioned inspection reports. No fee has been assessed for the enclosed documents in light of the minimal cost incurred in providing you with these records.

It is FRA's policy to withhold the names and related personal information of individuals from the enclosed materials because such information constitutes sensitive, personal, and private information. Therefore, pursuant to FOIA, the individuals' name and related personal information portions of these materials have been exempted from disclosure by exemption 6, 5 U.S.C. 552(b)(6), which exempts personnel and medical and similar files, the disclosure of which would constitute a clearly unwarranted invasion of personal privacy; and exemption 7(C), 5 U.S.C. 552(b)(7)(C), which exempts investigatory records compiled for law enforcement purposes, the disclosure of which could constitute an unwarranted invasion of personal privacy.

I am responsible for the decision to withhold this information. You may appeal my decision to the Administrator, Federal Railroad Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. According to the Department's FOIA regulations, 49 C.F.R. Part 7, your appeal must be submitted in writing within thirty days after your receipt of this letter, it must indicate that it is an appeal under FOIA, it must include all arguments and information upon which you rely, and the envelope in which the appeal is sent must be prominently marked "FOIA Appeal."

Since FRA has no other records in its possession that are responsive to your request, I am closing your file in this office. If you have any questions regarding the processing of your request, please contact me at (202) 493-6039.

Sincerely,

A handwritten signature in blue ink that reads "Denise Kollahlon". The signature is written in a cursive style with a large, stylized 'D' and 'K'.

Denise Kollahlon
FOIA Officer

Enclosures

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 002		Date yy mm dd 2005 4 5					
Railroad/Company Name & Address CANADIAN PACIFIC RAILWAY COMPANY 11306 Franklin Avenue Franklin Park, IL 60131				R/C R		Division CHICAG		RR/Co. Representative (Receipt Acknowledged) Name CP Railroad Title Manager Structures Signature					
				RR/Co. Code CP		Subdivision C&M							
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes		From Latitude					
State WI		55		City				From Longitude					
County MILWAUKEE		C079		County				To Latitude					
Mile Post: 0083.29 To				Inspection BRIDGE OBSERVATION				To Longitude					
Activity Code:		MSB	BWK	RWP	LRA								
Units:		1	14	14	4								
Sub Units:													
Item 1	Initials/Milepost 83.29	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed 45	Class	Train #/Site BRIDGE	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code
Description ** Comment to Railroad/Company ** Observation of Bridge 83.29. Steel and concrete gangs performing repairs. Good job briefing. No defects found.													
Violation Recommended		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Latitude:				Longitude:					
Written Notification to FRA of Remedial Action		Required <input type="checkbox"/> Optional <input type="checkbox"/>		Railroad Action Code		Date (mm/dd/yyyy)				Comments on back? <input type="checkbox"/>			

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525	Report No. 087	Date yy mm dd 2007 5 31								
Railroad/Company Name & Address UNION PACIFIC RR CO.				R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name <i>W(6)/(6)(7)(C)</i>							
				RR/Co. Code UP	Subdivision MILWAUKEE		Title Manager - Bridge Maintenance							
						Signature								
From: City MILWAUKEE	Codes	Destination City & County			Codes	From Latitude								
State WI	55	City MILWAUKEE			3100	From Longitude								
County MILWAUKEE	C079	County MILWAUKEE			C079	To Latitude								
Mile Post: 0089.00 To 0091.00		Inspection BRIDGE OBSERVATION				To Longitude								
Activity Code:	MSB	BWK	MTW	RWP										
Units:	2	1	1	2										
Sub Units:														
Item 1	Initials/Milepost 89	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code MSB	
Description On-track safety briefing given by MBM <i>W(6)/(6)(7)(C)</i> Observation of Bridge 89.91.														
Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>										Latitude:		Longitude:		
Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input type="checkbox"/>										Railroad Action Code		Date (mm/dd/yyyy)		Comments on back? <input type="checkbox"/>
Item 2	Initials/Milepost 91	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code MSB	
Description Observation of Bridge 91.12.														
Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>										Latitude:		Longitude:		
Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input type="checkbox"/>										Railroad Action Code		Date (mm/dd/yyyy)		Comments on back? <input type="checkbox"/>

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 046		Date yy mm dd 2009 11 4	
Railroad/Company Name & Address UNION PACIFIC RR CO.				R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name <i>(b)(6)/(b)(7)(C)</i>	
				RR/Co. Code UP		Subdivision KENOSHA		Title Bridge Inspector Signature	
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes 2400		From Latitude	
State WI		55		City KENOSHA				From Longitude	
County MILWAUKEE		C079		County KENOSHA		C059		To Latitude	
Mile Post: 0077.00 To 0052.00		Inspection BRIDGE OBSERVATIONS						To Longitude	
Activity Code:		MSB	MTW	MTH	BWK	RWP			
Units:		18	1	1	2	1			
Sub Units:									
Item 1	Initials/Milepost 76	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE
									SNFR* N
									RCL** N
									# of Occ.*** 0
									Activity Code RWP
Description ** Comment to Railroad/Company ** On-track safety briefing by <i>(b)(6)/(b)(7)(C)</i> Bridge observations with:									
Violation Recommended		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>		Railroad Action Code		Date (mm/dd/yyyy)		Comments on back? <input type="checkbox"/>	
Item 2	Initials/Milepost 76.05	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE
									SNFR* N
									RCL** N
									# of Occ.*** 0
									Activity Code MSB
Description ** Comment to Railroad/Company ** Observation of Bridge 76.05.									
Violation Recommended		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>		Railroad Action Code		Date (mm/dd/yyyy)		Comments on back? <input type="checkbox"/>	
Item 3	Initials/Milepost 75.7	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE
									SNFR* N
									RCL** N
									# of Occ.*** 0
									Activity Code MSB
Description ** Comment to Railroad/Company ** Observation of Bridge 75.7.									
Violation Recommended		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>		Railroad Action Code		Date (mm/dd/yyyy)		Comments on back? <input type="checkbox"/>	

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	046	11/4/2009 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	74.52								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 74.52.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	72.42								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 72.42.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	70.51								CULVERT	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of culvert at 70.51.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	69.2								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 69.2.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	68.91								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 68.91.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	046	11/4/2009 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	68.7								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 68.7.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	67.59								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 67.59.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	67.3								CULVERT	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of culverts at 67.3.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	66.23								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Observation of Bridge 66.23.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	65.96								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **
 Arch at MP 65.96.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	046	11/4/2009 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	65.73								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **

Observation of Bridge 65.73.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15	61.53								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **

Observation of Bridge 61.53.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
16	61.49								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **

Observation of bridge 61.49.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
17	61.25								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **

Observation of Bridge 61.25.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
18	59.25								BRIDGE	N	N	0	MSB

Description ** Comment to Railroad/Company **

Observation of filled in location where Bridge 59.25 was filled in and retired.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	046	11/4/2009 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
19	52.34								BRIDGE	N	N	0	MSB

Description	** Comment to Railroad/Company **
Observation of Bridge 52.34.	

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
			Comments on back? <input type="checkbox"/>

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 023		Date yy 2014 mm 3 dd 20	
Railroad/Company Name & Address CANADIAN PACIFIC RWY CO.				R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name <i>7/26/2014</i>	
				RR/Co. Code CP		Subdivision C&M		Title <i>7/26/2014</i>	
								Signature	
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes 3100		From Latitude	
State WI		55		City MILWAUKEE				From Longitude	
County MILWAUKEE		C079		County MILWAUKEE		C079		To Latitude	
Mile Post: 0083.20 To 0083.30				Inspection BRIDGE OBSERVATIONS				To Longitude	
Activity Code:		BOBS	RWP	BWS	MTW	LRA	BMV		
Units:		2	1	1	1	8	1		
Sub Units:		0	3	3	0	0	0		
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site
									SNFR* RCL** # of Occ.*** Activity Code
									N N 0
Description ** Comment to Railroad/Company ** Thorough on-track safety briefing and job-site safety briefing by B&B Foreman <i>7/26/2014</i>									
Violation Recommended		Yes	No	Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required	Optional	Railroad Action Code	Date (mm/dd/yyyy)	Comments on back?			
Item 2	Initials/Milepost 83.2	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE
									SNFR* RCL** # of Occ.*** Activity Code
									N N 0 BMV
Description ** Comment to Railroad/Company ** Observation of Bridge 83.2 over Kinnickinnic River.									
Violation Recommended		Yes	No	Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required	Optional	Railroad Action Code	Date (mm/dd/yyyy)	Comments on back?			
Item 3	Initials/Milepost 83.3	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE
									SNFR* RCL** # of Occ.*** Activity Code
									N N 0 BOBS
Description ** Comment to Railroad/Company ** Observation of Bridge 83.3 over S. Kinnickinnic Avenue.									
Violation Recommended		Yes	No	Latitude:		Longitude:			
Written Notification to FRA of Remedial Action		Required	Optional	Railroad Action Code	Date (mm/dd/yyyy)	Comments on back?			

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 056		Date yy mm dd 2014 7 30					
Railroad/Company Name & Address CANADIAN PACIFIC RY CO.				R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name T					
				RR/Co. Code CP		Subdivision C&M		Title Manager Structures (b)(6)(b)(7)(C)					
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes 3100		From Latitude					
State WI		55		City MILWAUKEE		3100		From Longitude					
County MILWAUKEE		C079		County MILWAUKEE		C079		To Latitude					
Mile Post: 0084.99 To 0084.99				Inspection BRIDGE OBSERVATION				To Longitude					
Activity Code:		BOBS	RWP	BWS	MTW	BIR	LRA	BMV					
Units:		1	1	1	1	1	4	1					
Sub Units:		0	2	2	0	0	0	0					
Item 1	Initials/Milepost 84.99	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code RWP
Description ** Comment to Railroad/Company ** Thorough on-track safety and job-site safety briefings conducted by B&B Foreman Bridges observed with (b)(6)(b)(7)(C) A review of the latest bridge inspection report was conducted. Observed bridge conditions were compared to the conditions reported on the bridge inspection report.													
Violation Recommended		Yes	No	Latitude:		Longitude:							
Written Notification to FRA of Remedial Action		Required	Optional	Railroad Action Code		Date (mm/dd/yyyy)		Comments on back?					
Item 2	Initials/Milepost 84.99	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site BRIDGE	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code BOBS
Description ** Comment to Railroad/Company ** Observation of Bridge 84.99 and review of the latest bridge inspection report. This bridge includes a TRT swing span over the Monominee River. This bridge has 3 spans, TRT and beams, concrete substructure, open deck, double track, and is 293' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 6/18/2014.													
Violation Recommended		Yes	No	Latitude:		Longitude:							
Written Notification to FRA of Remedial Action		Required	Optional	Railroad Action Code		Date (mm/dd/yyyy)		Comments on back?					

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 057		Date yy 2014 mm 7 dd 30	
Railroad/Company Name & Address CANADIAN PACIFIC RWY CO.				R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name (b)(6)/(b)(7)(C)		
				RR/Co. Code CP	Subdivision WATERTOWN		Title Manager Structures		
				Signature					
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes		From Latitude	
State WI		55		City WATERTOWN		5050		From Longitude	
County MILWAUKEE		C079		County DODGE		C027		To Latitude	
Mile Post: 0088.74 To 0130.64		Inspection		BRIDGE OBSERVATIONS				To Longitude	
Activity Code:	BOBS	RWP	BWS	MTW	BIR				
Units:	12	1	1	1	12				
Sub Units:	0	2	2	0	0				

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
<p>Description ** Comment to Railroad/Company **</p> <p>Thorough on-track safety and job-site safety briefings conducted by B&B Foreman: T 7-1</p> <p>Bridges observed with: T (b)(6)/(b)(7)(C)</p> <p>A review of the latest bridge inspection reports was conducted. Observed bridge conditions were compared to the conditions reported on the bridge inspection reports.</p>													
<p>Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/></p> <p>Railroad Action Code <input type="text"/> Date (mm/dd/yyyy) <input type="text"/> Comments on back? <input type="checkbox"/></p>										<p>Latitude: <input type="text"/> Longitude: <input type="text"/></p>			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	88.74								BRIDGE	N	N	0	BOBS
<p>Description ** Comment to Railroad/Company **</p> <p>Observation of Bridge 88.74 and review of the latest bridge inspection report. This bridge is 4 spans of DPG, concrete & stone substructure, steel ballast deck, double track, and 164' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/6/2014.</p>													
<p>Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/></p> <p>Railroad Action Code <input type="text"/> Date (mm/dd/yyyy) <input type="text"/> Comments on back? <input type="checkbox"/></p>										<p>Latitude: <input type="text"/> Longitude: <input type="text"/></p>			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	90.56								BRIDGE	N	N	0	BOBS
<p>Description ** Comment to Railroad/Company **</p> <p>Observation of Bridge 90.56 and review of the latest bridge inspection report. This bridge is a 2 span pony truss, concrete substructure, open deck, double track, and 210' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.</p>													
<p>Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/></p> <p>Railroad Action Code <input type="text"/> Date (mm/dd/yyyy) <input type="text"/> Comments on back? <input type="checkbox"/></p>										<p>Latitude: <input type="text"/> Longitude: <input type="text"/></p>			

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	057	7/30/2014 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	91.75								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 91.75 and review of the latest bridge inspection report. This bridge is 2 beam spans, concrete substructure, concrete ballast deck, double track, and 82' long over Swan Blvd. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	95.20								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 95.20 and review of the latest bridge inspection report. This bridge is 2 concrete spans, concrete substructure, ballast deck, double track, and 28' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	96.52								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 96.52 and review of the latest bridge inspection report. This bridge is 2 TPG spans, concrete substructure, steel ballast deck, double track, and 130' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	97.11								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 97.11 and review of the latest bridge inspection report. This bridge is 2 concrete spans, concrete substructure, ballast deck, and 28' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	100.3								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 100.3 and review of the latest bridge inspection report. This bridge is 2 precast concrete spans, concrete substructure, double track, and 70' long. The bridge inspection report dated 5/7/2014 is for DPG spans, not the precast concrete spans. It appears that the inspection form and the bridge data on the form were not updated to reflect the precast concrete spans when they were installed approximately 10 years ago. The bridge inspection form does not indicate that all superstructure components were inspected.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back?	<input type="checkbox"/>

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID	Report	Report Date
49525	057	7/30/2014 12:00:00 AM

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	105.43								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 105.43 and review of the latest bridge inspection report. This bridge is 1 beam span, concrete substructure, timber ballast deck, and 23' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	106.67								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 106.67 and review of the latest bridge inspection report. This bridge is 1 DPG span, concrete substructure, open deck, and 25' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	118.81								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 118.81. This bridge is a 1 span stone/brick arch 25' long. The electronic bridge inspection report provided was incomplete, only 1 page long, so a review was not done.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	121.95								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 121.95 and review of the latest bridge inspection report. This bridge is 3 DPG spans, concrete substructure, single track, and 188' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 6/4/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	130.65								BRIDGE	N	N	0	BOBS

Description ** Comment to Railroad/Company **
 Observation of Bridge 130.65 and review of the latest bridge inspection report. This bridge is 4 stone arches, single track, and 352' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 5/7/2014.

Violation Recommended	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Latitude:	Longitude:
Written Notification to FRA of Remedial Action	Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/>	Railroad Action Code	Date (mm/dd/yyyy)
		Comments on back? <input type="checkbox"/>	

DEPARTMENT OF TRANSPORTATION

INSPECTION REPORT

FEDERAL RAILROAD ADMINISTRATION (FRA)

OMB Approval No.: 2130-0509

Inspector's Name Krause, Steven G.		Inspector's Signature		Inspector's ID 49525		Report No. 039		Date yy 2015 mm 7 dd 13					
Railroad/Company Name & Address CANADIAN PACIFIC RWY CO. 439 Lake Ave S Spicer, MN 56288				R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Title Signature					
RR/Co. Code CP				Subdivision C&M									
From: City MILWAUKEE		Codes 3100		Destination City & County		Codes		From Latitude					
State WI		55		City				From Longitude					
County MILWAUKEE		C079		County				To Latitude					
Mile Post: 0085.08 To 0085.08		Inspection BRIDGE OBSERVATION						To Longitude					
Activity Code: BOBS		RWP		MTW		BIR		BSSE					
Units: 1		1		1		1		1					
Sub Units: 0		2		0		0		0					
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
										N	N	0	RWP
<p>Description ** Comment to Railroad/Company **</p> <p>Thorough on-track safety and job-site safety briefing conducted by:</p> <p>Bridge observed with CP's Railroad Bridge Engineer</p> <p>A review of the latest bridge inspection report was conducted. Observed bridge conditions were compared to the conditions reported on the bridge inspection report.</p>													
<p>Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>Latitude: Longitude:</p> <p>Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/></p> <p>Railroad Action Code Date (mm/dd/yyyy) Comments on back? <input type="checkbox"/></p>													
Item 2	Initials/Milepost 85.08	Equipment/Track #	Type/Kind	49 CFR/USC	Defect Code	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
										N	N	0	BOBS
<p>Description ** Comment to Railroad/Company **</p> <p>Observation of the section of CP Bridge 85.08 that spans South 1st Street and West Oregon Street and review of the latest bridge inspection report. This section of the bridge consists of 7 trough beam spans, concrete and steel substructures, ballast deck, double track, and is 144' long. Bridge conditions observed generally correspond with conditions reported on bridge inspection report dated 05/21/2015.</p> <p>A detailed rating inspection of this bridge was conducted by an engineering consultant firm and was concluded on 07/06/2015. The ratings and corresponding report have not yet been completed.</p>													
<p>Violation Recommended Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>Latitude: Longitude:</p> <p>Written Notification to FRA of Remedial Action Required <input type="checkbox"/> Optional <input checked="" type="checkbox"/></p> <p>Railroad Action Code Date (mm/dd/yyyy) Comments on back? <input type="checkbox"/></p>													