120 DAY CORRECTION PLAN

Next Door Head Start 05CH8319

Safe and Clean Facilities 1304.53(a)(10)(vi)Concern Safe and Clean Facilities 1304.53(a)(10)(vii).....Non-compliance Healthy Learning Environments 1304.22(c)....Concern Safe Learning Environments and Supervision 1304.52(i)(1)(iii).....Non-compliance

Life Safety Code: Next Door Head Start is unable to meet these codes for all classrooms. Next Door Head Start classrooms meet all local licensing requirements, however Next Door is unable to have exits from all classrooms leading directly outside. Some classrooms do have direct access to the outside but many are in older buildings including school district building

Date	Activity	Participants	Correction Oversight	Corrective Actions Or Content Covered
	afe and Clean Fac			
May 27, 2015	Request to Milwaukee Public Schools (MPS) to install smoke detectors	Executive Director See email below from MPS facilities manager	Executive Director Classrooms 119, 123, 118	Next Door leases space from MPS for Head Start Classrooms at the Oliver Wendall Holmes School. The School is grandfathered in from installing smoke detectors. The School has approved safety equipment installed to alert staff of an impending or potential fire.

From: Lenski, Michelle J [lenskimj@milwaukee.k12.wi.us] Sent: Wednesday, May 27, 2015 12:39 PM To: Carol Keintz Cc: Linn, John A Subject: RE: Message from KMBT_C360

Carol,

I enlisted the help of our mechanical engineer to help you answer your question about the smoke detectors.

The Fire Alarm (FA) system is grandfathered under the code and at the time of installation the code did not require smoke detection in all areas of the building. The existing fire alarm system meets the code and does not require installation of smoke detectors since it is grand fathered in.

If you did need to have smoke detection added, the units would need to meet today's code which would include a smoke detector connected to and monitored by the building fire alarm system. The stand-alone/battery operated units used in homes are not allowed.

If you need to have smoke detectors installed in the classrooms, it would cost approximately \$10,000 which would need to be paid for by NDF. However, you can hopefully explain to the auditors that the existing rooms meet the code. Hopefully this information will help you answer the question from your audit. Let me know if you have any further questions.

Michelle

Date	Activity	Responsible Staff	Correction Oversight	Corrective Actions Or Content Covered
	Safe and Clean Facilities – The nd 41 did not have Exit signs post			arly marked. Forty-six settings were
April 2015	 "Exit" signs were posted over classroom doors Maliaka: 125,121,122,124, Urban Day School 126,114,124,125,113,119,127, Next Door 29th St 68,77,65,129,131,120,128, Next Door Capitol 149,104,101,109,131,129,139, 120,122,107,127,106,103,137, 115,151,133,113,131, Oliver Wendall Holmes 121,119,123,118 	I T and Facilities Director	Head Start Director	Signs are now posted, see photo below

Date	Activity	Responsible	Correction	Corrective Actions
		Staff	Oversight	Or
				Content Covered

Г

Immediately	Following medication procedures	Nurse	Lead Pediatric Nurse / Head Start Director	•	Nurse provided the medication authorization form for the epi-pen to the medication box. Met with nursing staff to ensure that procedures are followed for classroom 77 and all classrooms Teachers in classroom 77 were provided with training on medication procedures
2015 Pre- service Training	Revised Health and Safety Checklist	Nurses will conduct H&S Checks during summer / Health Assistant will conduct H&S Checks in fall	Head Start Director		H & S Checks will be monitored monthly and reviewed by Site Directors and Head Start Director to ensure that authorizations are present for all medications