

CERTIFICATE OF APPROPRIATENESS APPLICATION FORM

Incomplete applications will not be processed for Commission review.

Please print legibly.

1.	Concordia	
	ADDRESS OF PROPERTY: 3011 W. State Street	
2.	NAME AND ADDRESS OF OWNER:	
	Name(s): Thomas Matthews	
	Address: 3011 W. State Street	
	City: Milwaukee State: Wi ZIP: 53208	
	Email: matthete@milwaukee.k12.wi.us	
	Telephone number (area code & number) Daytime: 414-331-3489 Evening: 414-331-3489	
3.	APPLICANT, AGENT OR CONTRACTOR: (if different from owner)	
	Name(s): AD Rooting and Gotters Address: 19700 W. Edgewood Prive	
	Address: 19700 W. Edgewood Prive	
	City: Landon State: W/ ZIP Code: 53046	
	Email: adrooting@MSN, COM	
	Email: ad roofing @ M S N, COM Telephone number (area code & number) Daytime: (4/4) 299-95WEvening: (24) 25/- 4500	
4.	ATTACHMENTS: (Because projects can vary in size and scope, please call the HPC Office at 414-286-5712 for submittal requirements)	
	A. REQUIRED FOR MAJOR PROJECTS;	
	Photographs of affected areas & all sides of the building (annotated photos recommended)	
	Sketches and Elevation Drawings (1 full size and 1 reduced to 11" x 17" or 8 ½" x 11") A digital copy of the photos and drawings is also requested.	
	Material and Design Specifications (see next page)	
	B. NEW CONSTRUCTION ALSO REQUIRES:	
	Floor Plans (1 full size and 1 reduced to a maximum of 11" x 17")	
	Site Plan showing location of project and adjoining structures and fences	
	PLEASE NOTE: YOUR APPLICATION CANNOT BE PROCESSED UNLESS	

LEASE NOTE: YOUR APPLICATION CANNOT BE PROCESSED UNLESS

BOTH PAGES OF THIS FORM ARE PROPERLY COMPLETED
AND SIGNED.

5. DESCRIPTION OF PROJECT:

Tell us what you want to do. Describe all proposed work including materials, design, and dimensions. Additional pages may be attached.

Royler praising stare loss
With GAF stare line
Shingles (Nor With (ur Corners).

6. SIGNATURE OF APPLICANT:

/ homes M/ lett 44

Signature

Thomas Matthews

Please print or type name

7-11-16

This form and all supporting documentation **MUST** arrive by 12:00 noon on the deadline date established to be considered at the next Historic Preservation Commission Meeting. Any information not provided to staff in advance of the meeting will not be considered by the Commission during their deliberation. Please call if you have any questions and staff will assist you.

Hand Deliver or Mail Form to:

Historic Preservation Commission City Clerk's Office 200 E. Wells St. Room B-4 Milwaukee, WI 53202

PHONE: (414) 286-5722

FAX: (414) 286-3004

www.milwaukee.gov/hpc

Or click the SUBMIT button to automatically email this form for submission.

SUBMIT

6/22/12

Jim Schleif Shorewest Realty

Re: Complete Shingle Roof on House at 3011 W. State St., Milwaukee, WI

Dear Mr. Schleif:

Thank you for giving us the opportunity to inspect the above roof. We recommend the following:

- Completely remove all shingles, roof felt, plumber pipe flashings, and vents on above roofs, and remove all debris from premises to a licensed recycling disposal site.
- If rotted wood is found, we will repair it at \$55 per man hour plus materials. We will include the first \$200 of repairs and this should cover needed repairs with no additional costs expected.
- 3. Furnish and install three feet of ice and water shield (brand determined by shingle selected) on all gutter edges, down all valleys, and around any chimneys or skylights.
- Furnish and install GAF Shinglemate, OC Reinforced, or Certainteed Roofers Select shingle felt depending on shingle selected over rest of deck.
- Install starter shingles on all gutter and rake edges.
- 6. We will install one of the following: GAF Timberline HD, Owens Corning TruDefinition Duration, Owens Corning Oakridge, or Certainteed Landmark dimensional shingles. The customer will have a wide variety of shingle colors to choose from. Each shingle will be securely fastened in place with five or six large-head galvanized nails according to manufacturer's specifications.
- Where flashing on plumber's pipe flashings are removed, we will replace with new flashings.
- 8. New factory painted W-valleys will be installed where old valleys are removed.
- Metal flashing around chimneys will be replaced as needed.
- 10. We will furnish and install 60 mil epdm rubber roof systems on flat roof areas (main upper, over hangs, rear entry, bay window, and top of steeple).
 - *We will remove decorative railings as carefully as possible, considering their age and condition, and save for owner. You will be responsible for new railings
- 11. Where necessary we will caulk and seal with Vulkem caulk.
- 12. All gutters will be cleaned of all roofing debris.
- Price Twenty-two thousand, six hundred, eighty-five dollars, and no/100s (\$22,685.00)
- *Discount \$1,650.00 if widows peak is left as is. ____yes or ______no (please initial)

 AD Roofing LLC will pull any necessary permits and cost will be added to price of contract. (Permit costs vary depending on municipality - usual cost is \$50 to \$150)
- We do not use dumpaters. We remove all debris from the premises using our pickup truck dump trucks which return to our shop each and every night.
- 10% down upon acceptance of contract and balance upon completion
- AD ROOFING LLC warrantles roof for 10 years of workmanship

Again, thank you for allowing us the opportunity to earn your business.

If you have any questions, please feel free to call	or visit us online at www.adroofingcontractors.com.
Sincerely,	APPROVED:
Aaron Dwyer	DATE:
W	ww.ADROOFINGLLC.com

A member of The Better Business Bureau, NARI, and MBA

Jul. 14. 2016 1:58PM

Hensiak Inspection Service, Inc

18:59 July 06, 2016

3011 W State St.inspx Andrew Larsen & Jason Tetzlaff 3011 W State St Page 5 of 34

General Information (Continued)


Fax 262-549-6112 E-Mail hensiakinspect@gmail.com File Number 17143

Conditions

Overview Pre Purchase Property Inspection
Confirmation Yes
Building Type Single family Garage
Estimated Age 100+ Entrance Faces North
Others Present Buyer, Buyer's Agent Property Occupied Occupied
Inspection Date 07/06/2016
Temperature 86
Weather Clear Soil Conditions Damp
Start Time 2:00pm
Electric On Yes
Gas/Oil On Yes
Water On Yes
Sewage Disposal City Sewer
Water Source City

Roof

Typical maintenance of a roof includes monitoring for any loose, damaged or missing shingles/shakes. Look for any rising nails or staples (fasteners). On a flat roof monitor for holes, open seams, edges or joints. Maintain the perimeter glued or metal strip fasteners. Periodic evaluation and maintenance of all roof flashings at valleys, penetrations (vents/pipes), transitions (roof/walls) and terminations (cut off/discharge areas). Keep roof, valleys and gutters free of moss, leaves, branches or debris, Roofs in shady areas or under branches and limbs require more attention. Regular maintenance will help your roof last longer. Only the exterior of chimney/fireplace liners are visible.



Palm-Tech Inspector, Copyright @ 1998-2016, PDmB, Inc.

Jul. 14. 2016 1:59PM

Hensiak Inspection Service, Inc

18:59 July 06, 2016

3011 W State St.inspx Andrew Larsen & Jason Tetzlaff 3011 W State St Page 6 of 34

Roof (Continued)

Overview (continued)




Roof Surface -

Method of Inspection: Ground level, Binoculars, Walk on roof

Unable to Inspect:

Satisfactory

Material: Slate, Metal roofing




Hensiak Inspection Service, Inc

18:59 July 06, 2016

3011 W State St.inspx Andrew Larsen & Jason Tetzlaff 3011 W State St Page 7 of 34

Roof (Continued)

Material: (continued)



Type: Hip, Flat, Low sloping-low sloping roofs are susceptible to leaking. Keep roof and gutters free of debris, leaves, ice and snow. This will help to prevent seepage up under the shingles.

Approximate Age: 10-75 years

Needs Attention

Flashing: Galvanized - Surface rust. Suggest painting rusting metal flashing. Dormers typically have side wall and lower flashings that may deteriorate or rise up over time and require attention. If asphalt or caulk sealant is used monitor yearly to keep sealed down and the joint tight to keep water out. Tarred-flashing needs resealing on a yearly basis to prevent leakage. This is a homeowner type (non professional) improvement to seal a roof joint and prevent water leakage. This will need replacing with the next roof installation or earlier if a roof leak occurs





Hensiak Inspection Service, Inc

18:59 July 06, 2016

3011 W State St.inspx Andrew Larsen & Jason Tetzlaff 3011 W State St Page 8 of 34

Roof (Continued)

Satisfactory Satisfactory Maintenance Needed


Plumbing Vents: Cast Iron/lead Electrical Mast: Overhead

Gutters/Downspts Metal, Drain onto grade, maintain 6'-10' extensions - Downspout is damaged/split, usually caused from obstructed water flow and freezing. Replacement needed, Need cleaning, Holding water, improve pitch and/or maintain unobstructed downspout extensions




Satisfactory Needs Attention Signs of Leaks: No evidence of roof leaks at this time Comment; Trim overhanging tree limbs or branches - Loose damage slate roofing, flashing joints have opened evidence of past roof leaks, flashings are rusted and need

condition recommend further evaluation by A qualified specialist. A local roofing specialist was present and will provide a repair or replacement quote



Chimney ----

Maintenance Needed




Hensiak Inspection Service, Inc

18:59 July 06, 2016

3011 W State St.inspx Andrew Larsen & Jason Tetzlaff 3011 W State St Page 9 of 34


Roof (Continued)

Chimney: (continued)



Needs Attention

Flue/Flue Cap: Concrete - Crown is cracked and in need of repair. West chimney may need a flu extension. Consult qualified specialist to evaluate chimneys and determine what action is necessary and any repair costs



Maintenance Needed

Chimney Flashing: Metal, Tar covered - Flashing must be kept sealed down and joints must be caulked/ sealed to preserve the chimney and prevent water intrusion Comment:

Palm-Tech Inspector, Copyright © 1998-2016, PDmB, Inc.