

LIVING WITH HISTORY

Milwaukee Historic Preservation Commission Staff Report

HPC meeting date: 5/6/2019 Ald. Khalif Rainey District: 7 Staff reviewer: Tim Askin PTS #114723 CCF #181893		
Property	2703 N. SHERMAN BL.	
Owner/Applicant	SHERMAN PARK LUTHERAN CHURCH 2703 N SHERMAN BLVD MILWAUKEE WI 532102426	Thomas Proffitt 2703 N. Sherman Bl. Milwaukee, WI 53210 Phone: (414) 445-5185
Proposal	Applicant replaced a basement window with glass block on the Center Street elevation at this address following a traffic accident in March 2014 that resulted in the loss of the original window.	
Staff comments	The building is a Neo-gothic church built in 1928 and has been part of the Sherman Boulevard district since it was established in 1995. This comes from a citizen complaint. In an unfortunate incident of presumably reckless driving, the window was damaged beyond repair. As a result, the window was replaced, though without approval or a building permit. Permits are generally required for windows on "commercial" buildings.	
	A glass block window that is above grade on a stread acceptable by this body.	eet-facing elevation has never been deemed
	t directly violates Sherman Boulevard design guidelines: Windows and Doors a. Retain existing window and door openings that are visible from the public right-of-way. Retain the present configuration of panes, sash, sills, architraves, hoods, doors and hardware, except as necessary to restore to the original condition. Avoid making additional openings or changes in the principle elevations by enlarging or reducing window or door sizes. Avoid changing the size or configuration of windowpanes or sash. Avoid discarding original windows, doors, and door hardware when they can be repaired or reused.	
	b. Respect the stylistic period or periods a building or doors is necessary, the replacement should dup original window sash or door. Avoid using inapprop unpainted aluminum storm and screen window cor openings with materials like glass block or the insta proportion to the openings or that are historically o modern style window units, such as with horizontal or the substitution of units with glazing configuratio building. The installation of glass block in basemer generally not permitted.	blicate the appearance and design of the briate sash and door replacements such as mbinations. Avoid the filling in or covering of allation of fake shutters that are not in but of character the building. Avoid using I sliding sash, in place of double-hung sash box not appropriate to the style of the
Recommendation	Recommend HPC Denial	
Conditions		
Previous HPC action		

Previous Council action